

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21000187/EPA3Q2

Date: 24/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900231029

Claimant
Vehicle No : SLM3885H **Insured Vehicle No :** GBJ9640S

Date of Loss: 01/01/2021 Nature of Claim: TP Claim No: 7237692461SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLM3885H	Engine No:	G4FGGH667924
Make & Model:	KIA CERATO, 1.6 (A)	Chassis No:	KNAFX411MH5696965
Reg. Date:	29/03/2017 (Man. Year: 2016)	Odometer:	63524 km
Colour:	Grey		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55ZR16	Rear Tyre Size:	205/55ZR16
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,039.60	4,440.80	1,598.80	26.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,630.00	2,740.00	1,890.00	40.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,669.60	7,180.80	3,488.80	32.70
+ GST 7.00/7.00% (S\$)	746.87	502.66	244.21	32.70
Nett Amount (S\$)	11,416.47	7,683.46	3,733.01	32.70
+ Car Rental (4.0 x S\$80.00/day + 7.00% GST) (S\$)		342.40		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		8,027.86		

INSPECTION

Date of Assignment: 04/01/2021

Date Inspected: 11/01/2021 Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RR NUMBER PLATE WITH CASING	Not Necessary	50.00 FS	*- FS
2	1		*REVERSE SENSOR	Not Necessary	220.00 FS	*- FS
3	1		*BODY PNL SEALANT	Necessary	80.00 FS	*40.00 FS
4	1		*C&C BADGE	Necessary	40.00 FS	*40.00 FS
5	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
6	1		*COVER -RR BUMPER	Dented	550.40 FS	*550.40 FS
7	1		*COVER -RR BUMPER ,CTR	Crushed	252.00 FS	*252.00 FS
8	1		*BEAM -RR BUMPER	Broken	254.40 FS	*254.40 FS
9	1		*STAY -RR BUMPER LH	Bent	96.00 FS	*96.00 FS
10	1		*STAY -RR BUMPER RH	Bent	96.00 FS	*96.00 FS
11	1		*BRACKET ,RR BUMPER SIDE MTG ,LH	Not Necessary	23.20 FS	*- FS
12	1		*BRACKET ,RR BUMPER SIDE MTG ,RH	Not Necessary	23.20 FS	*- FS
13	1		*GUARD -BUMPER REAR ,RH	Not Necessary	13.60 FS	*- FS
14	1		*PANEL ASSY -TRUNK LID	Dented	1,256.00 FS	*1,256.00 FS
15	1		*HINGE ASSY -TRUNK LID ,LH	Not Necessary	54.40 FS	*- FS
16	1		*HINGE ASSY -TRUNK LID ,RH	Not Necessary	54.40 FS	*- FS
17	1		*W/STRIP TRUNK LID OPNG	Not Necessary	80.00 FS	*- FS
18	1		*LATCH ASSY -TRUNK LID	Not Necessary	89.60 FS	*- FS
19	1		*STRIKER ASSY -TRUNK LID	Not Necessary	14.40 FS	*- FS
20	1		*LOGO ASSY -KIA SUB	Necessary	29.60 FS	*29.60 FS
21	1		*EMBLEM -CERATO	Necessary	28.00 FS	*28.00 FS
22	1		*EMBLEM K3	Necessary	12.00 FS	*12.00 FS
23	1		*PANEL ASSY -BACK	Repair	259.20 FS	*- FS
24	1		*TRIM -TRANSVERSE RR	Not Necessary	46.40 FS	*- FS
25	1		*LAMP ASSY -REAR COMB INSIDE ,LH	Broken	568.00 FS	*568.00 FS
26	1		*LAMP ASSY -REAR COMB INSIDE ,RH	Broken	568.00 FS	*568.00 FS
27	1		*LAMP ASSY -REAR COMBINATION -LH	Broken	630.40 FS	*630.40 FS
28	1		*LAMP ASSY -REAR COMBINATION -RH	Not Necessary	630.40 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$) **6,039.60** **4,440.80**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	RENEW RR BUMPER ,BOOTLID & RR END PNL REPAIR RR FLR PNL ,LHR FENDER & RHR FENDER	New	2,000.00	1,200.00
2	RESPRAY RR BUMPER ,BOOTLID ,RR END PNL ,RR FLR PNL ,LHR FENDER & RHR FENDER	New	2,100.00	1,050.00
3	REMOVE & REFIT BOOTLID COMPONENT	New	120.00	120.00
4	REMOVE & REFIT RR FLR BOARD ,TRIM & CARPET	New	120.00	120.00
5	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI SCAN PROT TEST USING HI-SCAN PRO TEST	New	120.00	120.00
7	REMOVE & REFIT REVERSE SENSOR	New	60.00	60.00
8	APPLY ANTI CORROSION ON AFFECTED AREAS	New	80.00	40.00
Gross Labour Cost (\$\$)			4,630.00	2,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >