

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG21000191/R1PA3Q2
Date: 04/06/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SMG7346R	Insured Vehicle No :	SMJ7715T
Date of Loss:	05/01/2021	Nature of Claim:	TP
		Claim No:	5642301637SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG7346R	Engine No:	CJS297253
Make & Model:	VOLKSWAGEN PASSAT B8, 1.8 TFSI (A)	Chassis No:	WVWZZZ3CZKE016473
Reg. Date:	28/12/2018 (Man. Year: 2018)	Odometer:	9492 km
Colour:	Grey		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,228.72	8,993.70	4,235.02	32.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,310.00	8,490.00	4,820.00	36.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	26,538.72	17,483.70	9,055.02	34.12
+ GST 7.00/7.00% (\$\$)	1,857.71	1,223.86	633.85	34.12

Nett Amount (S\$)	28,396.43	18,707.56	9,688.87	34.12
+ Car Rental (15.0 x S\$120.00/day + 7.00% GST) (S\$)		1,926.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		20,635.56		

INSPECTION

Date of Assignment: 06/01/2021

Date Inspected: 06/01/2021

Estimated Period of Repair: 11.0 days

Inspected At:

VOLKSWAGEN GROUP SINGAPORE PTE LTD
 247 Alexandra Road
 Singapore 159934

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TRUNK LID	Bent	2,733.59 FS	*2,733.59 FS
2	1		*FLAP HINGE LHR	Serviceable	109.92 FS	*- FS
3	1		*FLAP HINGE RHR	Serviceable	109.92 FS	*- FS
4	1		*DECKLID WEATHERSTRIP BLAC	Serviceable	317.42 FS	*- FS
5	1		*INSCRIPTION BRIGHT CHROME PASSAT	Necessary	74.25 FS	*74.25 FS
6	1		*INSCRIPTION BRIGHT CHROME 280 TSI	Not Necessary	74.25 FS	*- FS
7	1		*COVER PRIMED REAR BUMPER	Torn	1,655.72 FS	*1,655.72 FS
8	1		*SPOILER PRIMED	Deformed	288.69 FS	*288.69 FS
9	1		*SET SENSOR BRACKETS	Necessary	44.68 FS	*44.68 FS
10	1		*2K-PLASTIC ADHESIVE	Necessary	78.91 FS	*78.91 FS
11	1		*BONDING AGENT FOR PLASTIC	Necessary	62.81 FS	*62.81 FS
12	4		*RIVET	Necessary	4.56 FS	*4.56 FS
13	1		*BUMPER REINFORCEMENT	Bent	602.16 FS	*602.16 FS
14	1		*ATTACHMENT STRIP LHR TAILLIGHT	Cracked	61.50 FS	*61.50 FS
15	1		*GUIDE LHR TAIL LIGHT BRACKET	Cracked	22.98 FS	*22.98 FS
16	1		*GUIDE PIECE LHR SIDE BRACKET	Serviceable	39.43 FS	*- FS
17	1		*DECORATIVE MOULDING BRIGH LHR CHROME	Cracked	168.93 FS	*168.93 FS
18	1		*DECORATIVE MOULDING BRIGH RHR CHROME	Serviceable	168.93 FS	*- FS
19	1		*ZIERLEISTE CHROMGIANZ CTR CHROME	Serviceable	102.32 FS	*- FS
20	1		*END PLATE END PANEL INNER	Serviceable	985.21 FS	*- FS
21	1		*LOCK CARRIER END PANEL OUTER	Bent	408.26 FS	*408.26 FS
22	1		*MOUNTING FOR TAILLIGHT LHR END PANEL TAILLIGHT MOUNT	Bent	168.07 FS	*168.07 FS
23	1		*ZINC SPRAY	Necessary	62.88 FS	*62.88 FS
24	1		*2K-BODY ADHESIVE	Necessary	428.72 FS	*428.72 FS
25	1		*SEALANT CAB BE SPRAYED	Necessary	64.15 FS	*64.15 FS
26	1		*LED TAIL LIGHT LHR OUTER	Serviceable	611.56 FS	*- FS
27	1		*LED TAIL LIGHT LHR INNER	Serviceable	561.33 FS	*- FS
28	1		*REFLECTOR LHR INNER	Cracked	68.61 FS	*68.61 FS
29	1		*REFLECTOR LHR OUTER	Scratched	68.61 FS	*68.61 FS
30	1		*EXHAUST SILENCER REAR	Bent	1,498.02 FS	*1,498.02 FS
31	1		*MIDDLE EXHAUST MUFFLER	Serviceable	635.13 FS	*- FS
32	2		*DUAL CLAMP	Necessary (1 PCS ONLY)	124.08 FS	*62.04 FS
33	1		*BRACKET FOR EXHAUST SYSTE	Serviceable	42.26 FS	*- FS
34	1		*ENTLUFTUNGSBLENDE REAR LHR VENT TRIM	Serviceable	38.62 FS	*- FS
35	1		*HARNESS FOR BUMPER	Serviceable	128.61 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*NUMBER PLATE	Not Necessary	80.00 FS	*- FS
37	1		*LHR TAILLIGHT PANEL	Repeated	168.07 FS	*- FS
38	1		*HEAT SHIELD FOR EXHAUST M	Bent	145.69 FS	*145.69 FS
39	1		*BUMPER CTR MLDG CHROME	Cracked	219.87 FS	*219.87 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	13,228.72	8,993.70
--------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK SHORT CIRCUIT /HARNESS REPAIR	New	280.00	0.00
2	DIAGNOSTIC AND PROGRAMMING	New	480.00	480.00
3	LABOUR	New	5,040.00	3,360.00
4	TRANSFER BOOTLID MECHANISM	New	840.00	420.00
5	R&R REAR LUGGAGE COMPARTMENT	New	840.00	420.00
6	R&R EXHAUST	New	840.00	420.00
7	SPRAY PAINTING	New	4,000.00	2,400.00
8	CHECK WATER LEAK	New	150.00	150.00
9	LABOR TO REPLACE TAIL LIGHT PANEL	New	840.00	840.00
Gross Labour Cost (\$\$)			13,310.00	8,490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >