

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933  
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG21000193/GVD3E2  
**Date:** 25/01/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993863  
**Claimant Vehicle No :** SJX5618R **Insured Vehicle No :** SMA8872M  
Date of Loss: 28/12/2020 Nature of Claim: TP Claim No: 8450798935SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJX5618R**  
Make & Model: MINI COOPER, 1.6 (A) Engine No: A213I687  
Reg. Date: 25/06/2010 (Man. Year: 2010) Chassis No: WMWSU32000TY89289  
Colour: White Odometer: 146676 km  
Engine Capacity: 1598 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/45 R17 Rear Tyre Size: 205/45 R17  
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm  
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 04/01/2021  
Date Inspected: 12/01/2021 Inspected At: Yong Seng Motor (HQ)  
160 Sin Ming Drive, #04-20 Sin Ming AutoCity  
Singapore 575722  
Estimated Period of Repair: 4.0 days

**Adjuster:** XING GUO QIANG

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER UPPER	Deformed	0.00 F	*- F
2	1		*REAR BUMPER LOWER	Scratched	0.00 F	*- F
3	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
4	1		*REAR BUMPER BRACKET	Deformed	0.00 F	*- F
5	1		*REAR BUMPER REFLECTOR	Scratched	0.00 F	*- F
6	1		*REAR END PANEL	Repair	0.00 F	*- F
7	1		*TAILGATE	Buckled	0.00 F	*- F
8	2		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
9	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
10	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
11	1		*TAILGATE RUBBER	Torn	0.00 F	*- F
12	1		*REAR LH FENDER PROTECTOR	Necessary	0.00 F	*- F
13	1		*REAR RH FENDER PROTECTOR	Necessary	0.00 F	*- F

F=Franchise part.

**Total Parts (\$\$)**

**0.00**

**0.00**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**