Adjuster Report Page 1 of 3

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21000197/GA3Q2

**Date:** 15/01/2021

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700090544

Claimant
Vehicle No: SJL2175J Insured Vehicle No: GBD1378J

Date of Loss: 01/01/2021 Nature of Claim: TP Claim No: 3567219865SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SJL2175J

Make & Model: HONDA CIVIC, 1.3 IMA CVT (A) Engine No: LDA24006767

Reg. Date: 19/11/2008 (Man. Year: 2008) Chassis No: JHMFD36209S200748

Colour: White Odometer: 274063 km

Engine Capacity: 1339 cc
Market Value/New Car
N/A

Price:
Sum Insured (S\$):

Market Value/Ne

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Tourador 6 mm Rear Left Side: Tourador 6 mm
Front Right Side: Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 05/01/2021

Date Inspected: 05/01/2021 Inspected At: Teamwork Garage Pte Ltd (HQ)

53 Ubi Ave 1 #01-24, Paya Ubi

Industrial Park Singapore 408934

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG Manager: HOW MEI KWAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

# **REPAIR DETAILS**

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Bent	0.00 F	*- F
2	1		*REAR NUMBER PLATE BASE	Deformed	0.00 F	*- F
3	1		*REAR BUMPER	Deformed	0.00 F	*- F
4	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
5	2		*REAR BUMPER SIDE RETAINER	Cracked	0.00 F	*- F
6	1		*REVERSE SENSOR	Not Working	0.00 F	*- F
7	1		*REAR END PANEL	Buckled	0.00 F	*- F
8	1		*REAR END PANEL TOP GARNISH	Deformed	0.00 F	*- F
9	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
10	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
11	1		*BOOTLID	Bent	0.00 F	*- F
12	3		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
13	1		*BOOTLID HANDLE	Broken	0.00 F	*- F
14	1		*BOOTLID LAMP LH	Cracked	0.00 F	*- F
15	1		*BOOTLID LAMP RH	Cracked	0.00 F	*- F
16	1		*BOOTLID LOCK	Bent	0.00 F	*- F
17	1		*BOOTLID RUBBER	Twisted	0.00 F	*- F
18	1		*SPARE TYRE PANEL	Repair	0.00 F	*- F
19	1		*REAR EXHAUST PIPE	Repair	0.00 F	*- F
F=Fra	anchise	part.		Total Darta (CC)	0.00	0.00
				Total Parts (S\$)	0.00	0.00

Report was unsubmitted during this print-out.

Adjuster Report Page 3 of 3

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >