

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21000200/KQD3E2

Date: 15/02/2021

REFERENCE

Insured/Claimant: DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD

Policy No:

Date of Loss: 12/12/2020

Nature of Claim: OD Claim No: 9018775079SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ8766U	Engine No:	CXH179424
Make & Model:	VOLKSWAGEN T6 VAN, 2.0 TDI NWB DSG (A)	Chassis No:	WV1ZZZ7HZKH031227
Reg. Date:	25/09/2019 (Man. Year: 2018)	Odometer:	49629 km
Colour:	Red		
Engine Capacity:	1968 cc		
Market Value/New Car Price:	S\$58,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65 R16	Rear Tyre Size:	215/65 R16
Front Left Side:	Goodyear 8 mm	Rear Left Side:	Gremax 9 mm
Front Right Side:	Goodyear 8 mm	Rear Right Side:	Gremax 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,233.80	4,497.80	736.00	14.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,400.00	1,070.00	1,330.00	55.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,633.80	5,567.80	2,066.00	27.06
- Excess (S\$)	1,400.00	1,400.00	0.00	0.00
(S\$)	6,233.80	4,167.80	2,066.00	33.14
+ GST 7.00/7.00% (S\$)	436.37	291.75	144.62	33.14
Nett Amount (S\$)	6,670.17	4,459.55	2,210.62	33.14

INSPECTION

Date of Assignment: 06/01/2021

Date Inspected: 06/01/2021 Inspected At:

Tong Luck Auto Pte Ltd (HQ)
160 Sin Ming Drive, #07-01 Sin Ming AutoCity
Singapore 575722

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET (WCP)	Bent	1,180.00 F	*1,180.00 F
2	1		*SUPPORT PANEL (WCP)	Cracked	780.00 F	*780.00 F
3	1		*HEADLAMP ASSY - RH (WCP)	Mtg Cracked	485.00 F	*485.00 F
4	1		*FRONT BUMPER (WCP)	Cracked	880.00 F	*880.00 F
5	1		*FRONT BUMPER REINFORCEMENT (WCP)	Repair	520.00 F	*- F
6	1		*FRONT BUMPER SIDE RETAINER - RH (WCP)	Cracked	28.00 F	*28.00 F
7	1		*FRONT BUMPER INSIDE PART - RH (WCP)	Serviceable	65.00 F	*- F
8	1		*FRONT BUMPER CLIPS (WCP)(15 pcs)	Necessary	82.50 FS	*50.00 FS
9	1		*FRONT FENDER - RH (WCP)	Bent	485.00 F	*485.00 F
10	1		*FRONT FENDER INNER SHIELD - RH (WCP)	Cracked	160.00 F	*160.00 F
11	20		*FRONT FENDER INNER SHIELD CLIPS (WCP)	Necessary	110.00 FS	*50.00 FS

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	4,775.50	4,098.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	458.30	399.80
Total Parts (\$\$)	5,233.80	4,497.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT AND STRAIGHTEN RH FRONT FENDER INNER PANEL, RH FRONT CHASSIS FRAME, INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY, TO REFIT AND ADJUST THE SAME	New	1,000.00	400.00
2	TO CHECK AND RECTIFY WIRING SYSTEM	New	80.00	20.00
3	TO PUTTY AND SPRAY SAME ON AFFECTED AREAS	New	1,000.00	400.00
4	TO SUPPLY ARTWORK AND PASTE LOGO ON BONNET	New	220.00	150.00
5	REMOVE & REFIX AIR-CON CONDENSER, RADIATOR ASSY TO FACILITATE THE REPAIRS (Supplementary)	New	100.00	100.00
Gross Labour Cost (\$\$)			2,400.00	1,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >