

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21000202/DGA3Q2**Date:** 18/03/2021REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100484642  
**Claimant**  
**Vehicle No :** SGZ1200M **Insured Vehicle No :** SKB6011M  
Date of Loss: 02/01/2021 Nature of Claim: TP Claim No: 7094593436SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGZ1200M**  
Make & Model: LAND ROVER RANGE ROVER VELAR, 2.0 P Si4 Engine No: 171109Y0149PT204  
S/R (A)  
Reg. Date: 24/09/2018 (Man. Year: 2017) Chassis No: SALYA2AX0JA738859  
Colour: Red Odometer: 22717 km  
Engine Capacity: 1997 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/50 R20 Rear Tyre Size: 255/50 R20  
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm  
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	9,090.60	2,549.20	6,541.40	71.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,330.00	1,080.00	1,250.00	53.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>11,420.60</b>	<b>3,629.20</b>	<b>7,791.40</b>	<b>68.22</b>
<b>+ Loss of Use (4.0 x S\$100.00/day) (S\$)</b>		400.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>4,036.65</b>		

INSPECTION

Date of Assignment: 05/01/2021  
Date Inspected: 08/01/2021 Inspected At: Alfred Auto Services & Supplies (HQ)  
Blk 5035, Ang Mo Kio Ave 3, #01-351,  
Ang Mo Kio Industrial Park 2  
Singapore 569538  
Estimated Period of Repair: 3.0 days

**Adjuster:** BRYAN TANI**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Mtg Broken / Cut	3,123.00 F	*2,397.60 F
2	1		*FRONT BUMPER SIDE RETAINER	Serviceable	39.00 F	*- F
3	2		*FRONT BUMPER PARKING SENSOR	Serviceable	624.00 F	*- F
4	10		*FRONT BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
5	1		*FRONT FENDER	Repair	1,170.00 F	*- F
6	1		*FRONT FENDER DUST GARNISH	Serviceable	388.00 F	*- F
7	10		*FRONT FENDER DUST GARNISH CLIPS	Serviceable	55.00 F	*- F
8	1		*FRONT HEAD LAMP ASSY (LH)	Not Necessary	3,510.00 F	*- F
9	1		*FRONT BUMPER LH PROCTER	Dislodged	121.60 F	*121.60 F
<b>Total Parts (\$\$)</b>					<b>9,090.60</b>	<b>2,549.20</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	120.00	0.00
2	TO REPAIR & RENEW ALL ACCIDENT AFFECTED DAMAGE AREA & STRAIGHTEN DAMAGE AREA	New	800.00	400.00
3	TO RESPRAY PAINTING ON ALL ACCIDENT DAMAGE AFFECTED AREA (2 COLOR)	New	900.00	500.00
4	TO RUST PROOF ALL ACCIDENT AFFECTED AREA	New	150.00	30.00
5	TO DIAGNOSTIC ALL ACCIDENT SENSOS & ERASE FAULT CODE	New	180.00	150.00
6	TO CHECK COMPUTER WHEEL ALIGNMENT & CAMBER ,CASTOR	New	180.00	0.00
<b>Gross Labour Cost (\$)</b>			<b>2,330.00</b>	<b>1,080.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >