

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21000206/BGA3Q2**Date:** 10/08/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900246607
Claimant Vehicle No :	GBK4403M	Insured Vehicle No :	SMR526B
Date of Loss:	05/01/2021	Nature of Claim:	TP
		Claim No:	1703148809SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBK4403M		
Make & Model:	MITSUBISHI CANTER, 3.0 D FEA01BR1SDEK (CBU) (M)	Engine No:	4P10D88275
Reg. Date:	30/07/2020 (Man. Year: 2019)	Chassis No:	FEA01BA30392
Colour:	White	Odometer:	7827 km
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/75 R15	Rear Tyre Size:	185/75 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,819.75	5,920.07	9,899.68	62.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,600.00	1,970.00	3,630.00	64.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,419.75	7,890.07	13,529.68	63.16
Approved Total (Overridden) (S\$)		6,300.00		
(S\$)	21,419.75	6,300.00	15,119.75	70.59
+ GST 7.00/7.00% (S\$)	1,499.38	441.00	1,058.38	70.59
Nett Amount (S\$)	22,919.13	6,741.00	16,178.13	70.59
+ Loss of Use (9.0 x S\$100.00/day) (S\$)		900.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		7,648.45		

INSPECTION

Date of Assignment:	05/01/2021	
Date Inspected:	06/01/2021	Inspected At: 160 SIN MING DR #01-14 Repairer: Team Autopro Pte Ltd (Sin Ming)
Estimated Period of Repair:	6.0 days	

Adjuster: Lim Teow Guan**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT PANEL	Dented	1,481.40 FL	*1,481.40 FL
2	1		*FRONT PANEL EMBLEM FUSO	Necessary	89.40 FL	*89.40 FL
3	1		*FRONT CORNER PANEL	N/S Broken	1,011.60 FL	*482.00 FL
4	1		*FRONT WIPER PANEL	Not Damaged	440.00 FL	*- FL
5	1		*FRONT WIPER MOTOR	Not Damaged	210.60 FL	*- FL
6	1		*FRONT GRILLE	Broken	1,102.80 FL	*565.00 FL
7	1		*FRONT GRILLE LOGO	Necessary	78.80 FL	*38.50 FL
8	1		*FRONT GRILLE EMBLEM CANTER	Necessary	58.00 FL	*58.00 FL
9	1		*HEADLAMP	N/S Broken	978.20 FL	*461.00 FL
10	2		*HEADLAMP LOWER RUBBER LID	Not Damaged	90.00 FL	*- FL
11	1		*FRONT SIGNAL LAMP	N/S Broken	514.20 FL	*257.10 FL
12	1		*FRONT SIDE LAMP LH	Missing	255.40 FL	*255.40 FL
13	1		*FRONT BUMPER	Bent	768.60 FL	*768.60 FL
14	2		*FRONT BUMPER BRACKET	Not Damaged	316.00 FL	*- FL
15	1		*FRONT BUMPER SIDE COVER	N/S Broken	617.80 FL	*170.00 FL
16	1		*FRONT CROSS MEMBER LH	Not Damaged	483.00 FL	*- FL
17	1		*FRONT DOOR LH	Repair	1,983.50 FL	*- FL
18	1		*FRONT DOOR WEATHERSTRIP	Not Damaged	268.00 FL	*- FL
19	1		*FRONT DOOR LOCK	Not Damaged	238.00 FL	*- FL
20	1		*WING MIRROR ASSY	Missing	428.90 FL	*317.70 FL
21	1		*FRONT WINDSCREEN RUBBER	Not Damaged	183.60 FL	*- FL
22	1		*FRONT STEP GARNISH	Not Damaged	380.00 FL	*- FL
23	1		*FRONT WHEEL ARCH MOULDING	Not Damaged	182.30 FL	*- FL
24	1		*FRONT DASHBOARD ASSY	Repair	2,886.00 FL	*- FL
25	1		*FRONT DASHBOARD REINFORCEMENT	Not Damaged	786.30 FL	*- FL
26	1		*AIRCON BLOWER	Broken	1,198.00 FL	*1,198.00 FL
27	1		*AIRCON COOLING COIL	Broken	1,458.00 FL	*1,458.00 FL
28	1		*HEATER UNIT	Not Damaged	884.60 FL	*- FL
29	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
30	1		*FRONT PANEL SEALANT	Necessary	100.00 FS	*30.00 FS
31	1		*FRONT CORNER PANEL SEALANT	Not Necessary	100.00 FS	*- FS
32	1		*FRONT WIPER PANEL CLIPS	Not Necessary	50.00 FS	*- FS
33	1		*FRONT WIPER PANEL SIDE GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
34	1		*FRONT GRILLE CLIPS	Necessary	50.00 FS	*30.00 FS
35	1		*FRONT BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
36	1		*FRONT CROSS MEMBER SEALANT	Not Necessary	100.00 FS	*- FS
37	1		*FRONT DOOR SEALANT	Not Necessary	100.00 FS	*- FS
38	1		*FRONT DOOR COMPANY STICKER	Necessary	80.00 FS	*40.00 FS
39	1		*FRONT DOOR STICKER BLUETEC	Necessary	40.00 FS	*20.00 FS
40	1		*FRONT STEP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
41	1		*RADIATOR COOLANT	Necessary	120.00 FS	*40.00 FS
42	1		*AIRCON FLUID	Necessary	120.00 FS	*60.00 FS
43	1		*BRAKE FLUID	Not Necessary	120.00 FS	*- FS
44	1		*FRONT NUMBER PLATE	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	20,663.00	7,820.10
- List Item Discount on L Items 25.00/25.00% (\$)	4,843.25	1,900.03
Total Parts (\$)	15,819.75	5,920.07

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R FRONT DOOR COMPONENT	New	150.00	0.00
2	R&R FRONT WINDSCREEN	New	250.00	0.00
3	R&R FRONT DASHBOARD	New	450.00	200.00
4	R&R FRONT DASHBOARD WIRING HARNESS	New	200.00	0.00
5	R&R FRONT SEAT	New	150.00	0.00
6	R&R COOLING COIL	New	250.00	130.00
7	R&R BRAKE MASTER PUMP SYSTEM	New	250.00	0.00
8	CHECK WIRING	New	100.00	40.00
9	UPHOLSTERY	New	300.00	0.00
10	CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
11	PANEL BEAT	New	1,600.00	800.00
12	RUST PROOFING	New	200.00	0.00
13	SPRAY PAINTING	New	1,600.00	800.00
Gross Labour Cost (\$\$)			5,600.00	1,970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >