

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21000207/EQD3Q2

Date: 08/02/2021

REFERENCE

Insured/Claimant:	GOH KENG SWEE	Policy No:	2070150291	
Date of Loss:	05/01/2021	Nature of Claim:	OD	Claim No: 4986006754SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGP5005L			
Make & Model:	MITSUBISHI ECLIPSE CROSS, 1.5 (A)	Engine No:	4B40HM9006	
Reg. Date:	29/10/2020 (Man. Year: 2019)	Chassis No:	JMAXTGK1WLZ001714	
Colour:	Blue	Odometer:	5608 km	
Engine Capacity:	1499 cc			
Market Value/New Car Price:	S\$110,000.00			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55R18	Rear Tyre Size:	225/55R18
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,982.11	2,376.97	605.14	20.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,770.00	2,380.00	3,390.00	58.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,752.11	4,756.97	3,995.14	45.65
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	7,952.11	3,956.97	3,995.14	50.24
+ GST 7.00/7.00% (S\$)	556.65	276.99	279.66	50.24
Nett Amount (S\$)	8,508.76	4,233.96	4,274.80	50.24

INSPECTION

Date of Assignment: 06/01/2021

Date Inspected: 06/01/2021 Inspected At:

Cycle & Carriage Automotive Pte Ltd
(Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL ASSY,FR DOOR,RH	Dented	949.00 FL	*949.00 FL
2	1		*MOULDING,F/DR SASH,UPR RH	Necessary	119.00 FL	*119.00 FL
3	1		*MLDG,F/DR WDO BELT LINE,RH	Not Necessary	89.00 FL	*- FL
4	1		*GARNISH,FR DOOR SASH,RH	Not Necessary	66.00 FL	*- FL
5	1		*GARNISH,FR DOOR,RH	Cut	241.00 FL	*241.00 FL
6	1		*PANEL ASSY,RR DOOR,RH	Dented	937.00 FL	*937.00 FL
7	1		*MLDG,R/DR WDO BELT LINE,RH	Not Necessary	120.00 FL	*- FL
8	1		*MOULDING,R/DR SASH,UPR RH	Necessary	114.00 FL	*114.00 FL
9	1		*GARNISH,RR DOOR,RH	Missing	160.00 FL	*160.00 FL
10	1		*MOULDING,R/DOOR PROTECT,RH	Cut	105.00 FL	*105.00 FL
11	1		*GARNISH,SIDE SILL,RH	Not Necessary	91.00 FL	*- FL
12	1		*GARNISH,RR DOOR SASH,FR RH	Not Necessary	108.00 FL	*- FL
13	1		*GARNISH,RR DOOR SASH,RR RH	Not Necessary	49.00 FL	*- FL
14	1		*MOULDING,RR WHEEL ARCH,RH	Not Necessary	159.00 FL	*- FL
15	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
16	1		*BODY PNL SEALANT	Not Necessary	80.00 FS	*- FS
17	1		*SIDE EXTENSION (Supplementary)	Cut	436.00 FL	*436.00 FL
					Sub Total (\$\$)	3,843.00 3,081.00
					- List Item Discount on L Items 23.00/23.00% (\$\$)	860.89 704.03
					Total Parts (\$\$)	2,982.11 2,376.97

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	RENEW RHF DOOR & RHR DOOR.REPAIR RHR FENDER ARC,RH ROCKER PNL & RH CENTRE PILLAR	New	2,500.00	900.00
2	RESPRAY RHF DOOR,RHR DOOR,RHR FENDER,RH ROCKER PNL & RH CENTRE PILLAR	New	2,800.00	1,050.00
3	REMOVE & REFIT RHF DOOR COMPONENT	New	120.00	120.00
4	REMOVE & REFIT RHR DOOR COMPONENT	New	120.00	120.00
5	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
7	APPLY ANTI CORROSION ON AFFECTED AREAS	New	80.00	40.00
Gross Labour Cost (\$\$)			5,770.00	2,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >