

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG21000208/T1VD3E2

Date: 03/11/2021

REFERENCE

Insured/Claimant: PREMIUM AUTOMOBILES PTE LTD
Date of Loss: 29/12/2020

Policy No: 999993763
Nature of Claim: OD Claim No: 1966647656SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN9189C	Engine No:	CHH310224
Make & Model:	AUDI TT, 2.0 COUPE (A)	Chassis No:	TRUZZZFV9K1009836
Reg. Date:	30/08/2019 (Man. Year: 2019)	Odometer:	22495 km
Colour:	White		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$180,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,281.00	9,622.32	3,658.68	27.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,952.00	2,402.00	1,550.00	39.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	17,233.00	12,024.32	5,208.68	30.23
- Excess (\$\$)	3,000.00	3,000.00	0.00	0.00
(\$\$)	14,233.00	9,024.32	5,208.68	36.60
+ GST 7.00/7.00% (\$\$)	996.31	631.70	364.61	36.60
Nett Amount (\$\$)	15,229.31	9,656.02	5,573.29	36.60

INSPECTION

Date of Assignment: 05/01/2021

Date Inspected: 05/01/2021

Estimated Period of Repair: 4.0 days

Premium Automobiles Pte Ltd
24 Benoi Sector
Singapore 629857

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	3,032.00 FS	*2,614.40 FS
2	1		*FRONT BUMPER CLOSING ELEMENT - LH	Not Necessary	110.00 FS	*- FS
3	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Missing	248.00 FS	*200.00 FS
4	1		*FRONT REINFORCEMENT BEAM	Not Necessary	977.00 FS	*- FS
5	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	188.00 FS	*- FS
6	1		*LED HEADLIGHT - LH	Cracked	7,836.00 FS	*6,340.80 FS
7	1		*LIFT CYLINDER - LH	Broken	157.00 FS	*127.20 FS
8	1		*LIFT CYLINDER BRACKET - LH	Missing	29.00 FS	*23.20 FS
9	1		*LIFT CYLINDER HOSE - LH	Not Necessary	76.00 FS	*- FS
10	1		*FRONT PARKING AID SENSOR - OUTER	Missing	242.00 FS	*193.60 FS
11	4		*FRONT PARKING AID SEAL RING	Necessary	14.00 FS	*11.20 FS
12	1		*AUDI EMBLEM	Necessary	122.00 FS	*110.00 FS
13	1		*SUNDRIES	Necessary	250.00 FS	*1.92 FS
					Total Parts (\$\$)	13,281.00 9,622.32

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER	New	360.00	360.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
4	TO RESPRAY FRONT BUMPER AND BONNET	New	2,000.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			3,952.00	2,402.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >