

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

**Our File No:** CC4/AIG21000210/KGA3Q2  
**Date:** 10/05/2021

**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100159337
<b>Claimant Vehicle No :</b>	SKN1543P	<b>Insured Vehicle No :</b>	SJS6875J
Date of Loss:	17/11/2020	Nature of Claim:	TP
		Claim No:	5802946551SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SKN1543P</b>		
Make & Model:	NISSAN TEANA, 2.0 CVT (A)	Engine No:	MR20031743R
Reg. Date:	17/05/2014 (Man. Year: 2013)	Chassis No:	MNTBBAL33Z0000015
Colour:	Metallic Black	Odometer:	128371 km
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Yokohama 9 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Yokohama 9 mm	Rear Right Side:	Yokohama 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,309.26	2,175.97	133.29	5.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,330.00	1,150.00	180.00	13.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,639.26</b>	<b>3,325.97</b>	<b>313.29</b>	<b>8.61</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,650.00</b>		

(S\$)	3,639.26	2,650.00	989.26	27.18
<b>+ GST 7.00/7.00% (S\$)</b>	254.75	185.50	69.25	27.18
<b>Nett Amount (S\$)</b>	<b>3,894.01</b>	<b>2,835.50</b>	<b>1,058.51</b>	<b>27.18</b>
<b>+ Loss of Use (5.0 x S\$100.00/day) (S\$)</b>		500.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>3,342.95</b>		

INSPECTION

Date of Assignment: 05/01/2021

Date Inspected: 19/01/2021

Inspected At:

Lim Tan Motor Pte Ltd (HQ)  
 Blk 176 Sin Ming Drive #03-09/10, Sin Ming Auto Care  
 Singapore 575721

Estimated Period of Repair: 5.0 days

**Adjuster:** KENNETH KONG**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	907.10 FN	*848.10 FN
2	1		*RH REAR BUMPER RETAINER	Necessary	55.10 FN	*55.10 FN
3	10		*REAR BUMPER CLIPS	Necessary	26.00 FN	*26.00 FN
4	1		*RH REAR FENDE	Buckled	1,377.30 FN	*1,288.20 FN
5	1		*REAR WINDSCREEN MOULDING	Necessary	155.90 FN	*155.90 FN
6	1		*TUBE REAR WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

<b>Sub Total (\$)</b>	<b>2,561.40</b>	<b>2,413.30</b>
<b>- Nett Item Discount on N Items 10.00/10.00% (\$)</b>	252.14	237.33
<b>Total Parts (\$)</b>	<b>2,309.26</b>	<b>2,175.97</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PUTTY & SPRAY PAINT	New	500.00	420.00
2	TO REMOVE & REFIX REAR WINDSCREEN GLASS	New	100.00	100.00
3	TO ANTI RUST	New	50.00	30.00
4	LABOUR CHARGES	New	680.00	600.00
<b>Gross Labour Cost (\$)</b>			<b>1,330.00</b>	<b>1,150.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >