

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

# VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG21000212/APA3Q2

**Date:** 15/04/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900081171

**Claimant**  
**Vehicle No :** SML8600Z **Insured Vehicle No :** SMK897S

Date of Loss: 04/01/2021 Nature of Claim: TP Claim No: 4802745676SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SML8600Z</b>		
Make & Model:	TOYOTA SIENTA, 1.5 CVT ELEGANCE (A)	Engine No:	2NRX468608
Reg. Date:	07/06/2019 (Man. Year: 2019)	Chassis No:	MHFZ28H3900064170
Colour:	White	Odometer:	20252 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

### CONDITION OF TYRES

Front Tyre Size:	195/50R16	Rear Tyre Size:	195/50R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,525.76	4,185.35	6,340.41	60.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,460.00	2,050.00	2,410.00	54.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>14,985.76</b>	<b>6,235.35</b>	<b>8,750.41</b>	<b>58.39</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,900.00</b>		
<b>Nett Amount (S\$)</b>	<b>14,985.76</b>	<b>4,900.00</b>	<b>10,085.76</b>	<b>67.30</b>
<b>+ Car Rental (6.0 x S\$100.00/day) (S\$)</b>		600.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>5,507.45</b>		
<b>Global Sum Settlement (S\$)</b>		<b>5,500.00</b>		

### INSPECTION

Date of Assignment: 05/01/2021

Date Inspected: 06/01/2021 Inspected At:

Smartone Auto Pte Ltd (HQ)  
8 Kaki Bukit Avenue 4, #08-09  
Premier @ Kaki Bukit  
Singapore 415875

Estimated Period of Repair: 6.0 days

**Adjuster:** ADRIAN LING**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	466.90 FL	*466.90 FL
2	1		*REAR CENTER BUMPER (UPPER)	Deformed	186.70 FL	*186.70 FL
3	2		*REAR BUMPER REFLECTOR	Not Necessary	117.20 FL	*- FL
4	1		*REAR BUMPER REFLECTOR GARNISH	N/S Cut	257.40 FL	*128.70 FL
5	2		*REAR BUMPER SIDE RETAINER	Necessary	139.60 FL	*139.60 FL
6	1		*REAR BUMPER CENTER LAMP	Cracked	231.20 FL	*231.20 FL
7	2		*REAR FENDER COWLING	Not Necessary	258.20 FL	*- FL
8	2		*REAR FENDER INNER TRIM BOARD (LOWER)	Not Necessary	1,254.20 FL	*- FL
9	2		*TAILLAMP	Not Necessary	1,055.80 FL	*- FL
10	2		*TAILLAMP LOWER BRACKET	Not Necessary	91.20 FL	*- FL
11	1		*TAIL GATE	Dented	2,378.01 FL	*1,180.00 FL
12	2		*TAIL GATE LAMP (LED)	Not Necessary	715.80 FL	*- FL
13	1		*TAIL GATE LOGO	Necessary	75.24 FL	*75.24 FL
14	1		*TAIL GATE EMBLEM SIENTA	Necessary	58.67 FL	*58.67 FL
15	1		*TAIL GATE EMBLEM V	Necessary	38.60 FL	*38.60 FL
16	1		*TAIL GATE OUTER MOULDING	Not Necessary	243.70 FL	*- FL
17	1		*TAIL GATE INNER HOLDER GARNISH	Not Necessary	28.60 FL	*- FL
18	1		*TAIL GATE LOCK	Damaged	458.70 FL	*396.00 FL
19	1		*TAIL GATE CATCH	Not Necessary	38.90 FL	*- FL
20	1		*TAIL GATE INNER TRIM	Not Necessary	578.60 FL	*- FL
21	4		*TAIL GATE STOPPER	Not Necessary	98.40 FL	*- FL
22	1		*TAIL GATE WEATHERSTRIP	Cut	325.17 FL	*325.17 FL
23	1		*TAIL GATE DETECTOR	Damaged	239.10 FL	*72.00 FL
24	1		*TAIL GATE DETECTOR WIREHARNES	Not Necessary	288.90 FL	*- FL
25	3		*TAIL GATE WINDSCREEN GLASS MOULDING	Necessary	97.80 FL	*97.80 FL
26	1		*REAR END PANEL (OUTER)	Dented	696.70 FL	*599.00 FL
27	1		*REAR END PANEL (INNER)	Dented	433.80 FL	*433.80 FL
28	1		*REAR END PANEL TOP GARNISH	Deformed	145.20 FL	*145.20 FL
29	1		*REAR TOOL HOLDER GARNISH	Deformed	123.20 FL	*123.20 FL
30	1		*REAR TOOL COVER BOARD	Not Necessary	475.10 FL	*- FL
31	2		*REVERSE SENSOR	Damaged	576.02 FL	*576.02 FL
32	1		*REVERSE SENSOR WIRE HARNESS	Not Necessary	229.70 FL	*- FL
33	1		*REVERSE CAMERA	Not Necessary	458.70 FL	*- FL
34	1		*REAR NUMBER PLATE	Bent	80.00 FS	*60.00 FS
35	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
36	1		*SET REAR BUMPER REFLECTOR GARNISH CLIP	Necessary	40.00 FS	*10.00 FS
37	1		*SET TAIL LAMP CLIP RH	Not Necessary	60.00 FS	*- FS
38	1		*SET TAIL GAT OUTER MOULDING CLIP		50.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Not Necessary		
39	1		*SET TAIL GATE INNER TRIM CLIP	Not Necessary	80.00 FS	*- FS
40	1		*TAIL GATE WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
41	1		*TAIL GATE WINDSCREEN INNER SHIELD	Not Necessary	60.00 FS	*- FS
42	1		*SET REAR FENDER COWLING CLIP RH	Not Necessary	80.00 FS	*- FS
43	1		*SET REAR FENDER INNER TRM BOARD (LOWER) CLIP	Not Necessary	80.00 FS	*- FS
44	1		*REAR END PANEL (OUTER) SEALANT	Necessary	150.00 FS	*60.00 FS
45	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	40.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>13,741.01</b>	<b>5,503.80</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	3,215.25	1,318.45
<b>Total Parts (\$\$)</b>	<b>10,525.76</b>	<b>4,185.35</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	PANEL BEATING ,REMOVING AND REPLACING PARTS	New	1,400.00	800.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,400.00	800.00
3	TUFF COAT	New	250.00	60.00
4	WIRING CHECK	New	180.00	30.00
5	REMOVE & REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	350.00	60.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	60.00
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	80.00	60.00
8	REMOVE AND REFIX VIDEO RECORDER	New	80.00	0.00
9	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
10	TRANSFER TAILGATE MECHANISM	New	120.00	60.00
11	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	280.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,460.00</b>	<b>2,050.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >