

SmartOne Auto Pte. Ltd.

Co. Reg No: 201939368E

8 Kaki Bukit Avenue 4

#08-09 Premier @ Kaki Bukit

Singapore 415875

Tel: 6341 6789 Fax: 6341 6778

Email: smartoneauto@gmail.com



DATE : 05.01.20

TO : AIG MOTOR CLAIMS DEPTS
VEHICLE NO : SML8600Z
MODEL : TOYOTA SIENTA
DATE OF ACCIDENT : 04.01.21
TIME OF ACCIDENT : 17:05HRS

Xiao Tony

MH FZ228H 39000 64170

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Deland</i>	1	\$ 466.90	\$ 466.90
2	REAR CENTER BUMPER (UPPER) <i>Deland</i>	1	\$ 186.70	\$ 186.70
3	REAR BUMPER REFLECTOR <i>New</i>	2	\$ 58.60	\$ 117.20
4	REAR BUMPER REFLECTOR GARNISH <i>EH</i>	2	\$ 128.70	\$ 257.40
5	REAR BUMPER SIDE RETAINER <i>New</i>	2	\$ 69.80	\$ 139.60
6	REAR BUMPER CENTER LAMP <i>crushed</i>	1	\$ 231.20	\$ 231.20
7	REAR FENDER COWLING <i>New</i>	2	\$ 129.10	\$ 258.20
8	REAR FENDER INNER TRIM BOARD (LOWER) <i>New</i>	2	\$ 627.10	\$ 1,254.20
9	TAILLAMP <i>New</i>	2	\$ 527.90	\$ 1,055.80
10	TAILLAMP LOWER BRACKET <i>New</i>	2	\$ 45.60	\$ 91.20
11	TAIL GATE <i>Dented</i>	1	\$ 2,378.01	\$ 2,378.01
12	TAIL GATE LAMP (LED) <i>New</i>	2	\$ 357.90	\$ 715.80
13	TAIL GATE LOGO <i>New</i>	1	\$ 75.24	\$ 75.24
14	TAIL GATE EMBLEM 'SIENTA' <i>3x1</i>	1	\$ 58.67	\$ 58.67
15	TAIL GATE EMBLEM 'V'	1	\$ 38.60	\$ 38.60
16	TAIL GATE OUTER MOULDING <i>New</i>	1	\$ 243.70	\$ 243.70
17	TAIL GATE INNER HOLDER GARNISH <i>New</i>	1	\$ 28.60	\$ 28.60
18	TAIL GATE LOCK <i>Damaged</i>	1	\$ 458.70	\$ 458.70
19	TAIL GATE CATCH <i>New</i>	1	\$ 38.90	\$ 38.90
20	TAIL GATE INNER TRIM <i>New</i>	1	\$ 578.60	\$ 578.60
21	TAIL GATE STOPPER <i>New</i>	4	\$ 24.60	\$ 98.40
22	TAIL GATE WEATHERSTRIP <i>lit</i>	1	\$ 325.17	\$ 325.17
23	TAIL GATE DETECTOR <i>Damaged</i>	1	\$ 239.10	\$ 239.10
24	TAIL GATE DETECTOR WIREHARNES <i>New</i>	1	\$ 288.90	\$ 288.90
25	TAIL GATE WINDSCREEN GLASS MOULDING <i>New</i>	3	\$ 32.60	\$ 97.80
26	REAR END PANEL (OUTER) <i>Dented</i>	1	\$ 696.70	\$ 696.70
27	REAR END PANEL (INNER) <i>Dented</i>	1	\$ 433.80	\$ 433.80

✓
✓
+
128.70
-
-
+
+
+
+
1180
+
-
-
+
+
396
+
+
+
72
+
588

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SML8600Z**
 MODEL : **TOYOTA SIENTA**
 DATE OF ACCIDENT : 04.01.21
 TIME OF ACCIDENT : 17:05HRS

28	REAR END PANEL TOP GARNISH <i>Delcd</i>	1	\$ 145.20	\$ 145.20	✓
29	REAR TOOL HOLDER GARNISH <i>Delcd</i>	1	\$ 123.20	\$ 123.20	✓
30	REAR TOOL COVER BOARD <i>New m</i>	1	\$ 475.10	\$ 475.10	+
31	REVERSE SENSOR <i>Delcd</i>	2	\$ 288.01	\$ 576.02	✓
32	REVERSE SENSOR WIRE HARNESS <i>new</i>	1	\$ 229.70	\$ 229.70	+
33	REVERSE CAMERA <i>new</i>	1	\$ 458.70	\$ 458.70	+

5273.80

3955.35

TOTAL PRICE \$ 12,861.01

LESS 25% \$ 3,215.25

SUB TOTAL PRICE \$ 9,645.76

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>Bent.</i>	1	\$ 80.00	\$ 80.00	60
2	REAR BUMPER CLIP (SET) <i>New</i>	1	\$ 80.00	\$ 80.00	30
3	REAR BUMPER REFLECTOR GARNISH CLIP (SET) <i>New</i>	1	\$ 40.00	\$ 40.00	10
4	TAIL LAMP CLIP RH (SET) <i>New</i>	1	\$ 60.00	\$ 60.00	+
5	TAIL GATE OUTER MOULDING CLIP (SET) <i>New</i>	1	\$ 50.00	\$ 50.00	+
6	TAIL GATE INNER TRIM CLIP (SET) <i>New</i>	1	\$ 80.00	\$ 80.00	+
7	TAIL GATE WINDSCREEN SEALANT <i>New</i>	1	\$ 80.00	\$ 80.00	60
8	TAIL GATE WINDSCREEN INNER SHIELD <i>New</i>	1	\$ 60.00	\$ 60.00	+
9	REAR FENDER COWLING CLIP RH (SET) <i>New</i>	1	\$ 80.00	\$ 80.00	+
10	REAR FENDER INNER TRIM BOARD (LOWER) CLIP (SET) <i>New</i>	1	\$ 80.00	\$ 80.00	+
11	REAR END PANEL (OUTER) SEALANT <i>New</i>	1	\$ 150.00	\$ 150.00	60
12	REAR END PANEL TOP GARNISH CLIP (SET) <i>New</i>	1	\$ 40.00	\$ 40.00	10

TOTAL \$ 880.00

230

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,400.00	800
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,400.00	800
3	TUFF COAT	\$ 250.00	60
4	WIRING CHECK	\$ 180.00	30
5	REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 350.00	60

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SML8600Z**
 MODEL : **TOYOTA SIENTA**
 DATE OF ACCIDENT : 04.01.21
 TIME OF ACCIDENT : 17:05HRS

6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	60
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	60
8	REMOVE AND REFIX VIDEO RECORDER	\$ 80.00	X
9	CONDUCT WATER LEAKAGE TEST	\$ 120.00	X
10	TRANSFER TAILGATE MECHANISM	\$ 120.00	60
11	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 280.00	X

TOTAL

\$4,460.00

2050

TOTAL PARTS COST : \$ 10,525.76

TOTAL LABOUR COST : \$ 4,460.00

TOTAL REPAIR COST : \$ 14,985.76

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

MICHELLE

SERVICE ADVISOR

MICHELLE

HP : 9856 4815

Adrian King
 h/s 06/01/21

06 Days

total: 6233.35

h/s: A.K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: