

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG121000214/ATD3N2**Date:** 13/12/2021**REFERENCE**

Handling Insurer:	ERGO Insurance Pte. Ltd.	Policy No:	DMCG20001996
Claimant Vehicle No :	SLH9072Z	Insured Vehicle No :	GX1637Y
Date of Loss:	03/01/2021	Nature of Claim:	TP
		Claim No:	CDMCG21000013

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH9072Z	Engine No:	2ZR1840773
Make & Model:	TOYOTA WISH, 1.8 (A)	Chassis No:	JTDGG20W20J005480
Reg. Date:	23/11/2016 (Man. Year: 2016)	Odometer:	329852 km
Colour:	Grey		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45R17	Rear Tyre Size:	225/45R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,201.55	1,715.06	5,486.49	76.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,750.00	1,080.00	1,670.00	60.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,951.55	2,795.06	7,156.49	71.91
Approved Total (Overridden) (\$\$)		2,200.00		
(\$\$)	9,951.55	2,200.00	7,751.55	77.89
+ GST 7.00/7.00% (\$\$)	696.61	154.00	542.61	77.89
Nett Amount (\$\$)	10,648.16	2,354.00	8,294.16	77.89

INSPECTION

Date of Assignment:	06/01/2021	Green Forest Automobile Pte Ltd (Kaki Bukit)
Date Inspected:	06/01/2021 Inspected At:	8 Kaki Bukit Avenue 4, #05-25,, Premier@Kaki Bukit
Estimated Period of Repair:	4.0 days	Singapore 415875

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Dec 2021)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLH9072Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP-RH	Not Necessary	950.00 F	*- FL
2	1		*FRONT GRILLE (NPA)	Not Necessary	0.00 F	*- FL
3	1		*FRONT GRILLE EMBLE LOGO (NPA)	Not Necessary	0.00 F	*- FL
4	1		*FRONT BUMPER	Not Necessary	452.00 F	*- FL
5	2		*FRONT BUMPER SIDE BRACKET	Not Necessary	170.00 F	*- FL
6	8		*FRONT BUMPER CLIPS	Not Necessary	103.20 F	*- FL
7	1		*FRONT FENDER-RH	Dented	412.20 F	*412.20 FL
8	1		*FRONT FENDER COWLING-RH	Deformed	153.20 F	*153.20 FL
9	8		*FRONT FENDER COWLING CLIPS-RH	Necessary	103.20 F	*30.00 FL
10	1		*FRONT R/H DOOR	Dented	1,050.10 F	*1,050.10 FL
11	1		*FRONT OUTER HANDLE-RH	Not Necessary	155.30 F	*- FL
12	1		*FRONT R/H DOOR PROTECTOR-LOWER	Not Necessary	161.40 F	*- FL
13	1		*FRONT R/H DOOR PROTECTOR MOLDING	Necessary	123.05 F	*123.05 FL
14	1		*FRONT R/H DOOR INNER LOCK	Not Necessary	289.90 F	*- FL
15	1		*FRONT R/H DOOR INNER TRIM BOARD	Not Necessary	551.20 F	*- FL
16	1		*FRONT SIDE SKIRT	Not Necessary	551.00 F	*- FL
17	1		*FRONT R/H DOOR INNER GEAR MOTOR ASSY	Not Necessary	372.40 F	*- FL
18	1		*FRONT TYRE-RH	Not Necessary	250.00 F	*- FL
19	1		*FRONT SPORT RIM-RH	Cut	350.00 F	*350.00 FL
20	1		*FRONT SHOCK ABSORBER-RH	Not Necessary	312.00 F	*- FL
21	1		*FRONT KNUCKLE ARM-RH	Not Necessary	268.10 F	*- FL
22	1		*FRONT LOWER ARM-RH	Not Necessary	255.10 F	*- FL
23	1		*FRONT WHEEL BEARING-RH	Damaged	168.20 F	*168.20 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	7,201.55	2,286.75
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	571.69
Total Parts (\$\$)	7,201.55	1,715.06

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT CUSHION	New	120.00	0.00
2	TO REMOVE & REFIT FRONT & RH DOOR GEAR MOTOR GLASS	New	200.00	80.00
3	TO REMOVE & REFIT R/H FRONT UNDERCARRIAGE	New	250.00	60.00
4	TO CHECK WHEEL ALIGNMENT COMPUTER	New	150.00	80.00
5	TO CHECK WIRING	New	60.00	30.00
6	TUFF KOTE	New	120.00	30.00
7	TOWING FEE	New	100.00	0.00
8	PANEL BEATING	New	800.00	400.00
9	SPRAY PAINTING	New	800.00	400.00
10	WHEEL ALIGNMENT (COMPUTER)	New	150.00	0.00
Gross Labour Cost (\$\$)			2,750.00	1,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >