

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21000215/ABA3Q2
Date: 08/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900045285
Claimant Vehicle No :	GBK967D	Insured Vehicle No :	SJN6863U
Date of Loss:	30/12/2020	Nature of Claim:	TP
		Claim No:	2840634981SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBK967D		
Make & Model:	TOYOTA DYNA, 3.0 D (M)	Engine No:	1KDB019264
Reg. Date:	26/12/2019 (Man. Year: 2019)	Chassis No:	KDY2318041240
Colour:	White	Odometer:	48988 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185 R15C	Rear Tyre Size:	145 R13
Front Left Side:	Hankook 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,888.57	4,941.15	9,947.42	66.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,610.00	1,680.00	3,930.00	70.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,498.57	6,621.15	13,877.42	67.70
Approved Total (Overridden) (S\$)		5,300.00		

Nett Amount (S\$)	20,498.57	5,300.00	15,198.57	74.14
+ Car Rental (6.0 x S\$90.00/day + 7.00% GST) (S\$)		577.80		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,885.25		
Global Sum Settlement (S\$)		5,800.00		

INSPECTION

Date of Assignment: 06/01/2021

Date Inspected: 06/01/2021

Estimated Period of Repair: 6.0 days

Inspected At: Kt Motorwerk (HQ)
Blk 3012 Bedok Industrial Park E, #01-2020
Singapore 489978

Adjuster: ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,348.50 FL	*1,348.50 FL
2	1		*TAILGATE SIDE LOCK BRACKETS	N/S Bent	257.40 FL	*128.70 FL
3	2		*TAILGATE SIDE LOCK	Not Necessary	257.80 FL	*- FL
4	1		*TAILGATE SIDE LOCK LOWER BRACKETS	N/S Bent	217.00 FL	*108.50 FL
5	1		*TAILGATE SIDE STOPPERS	N/S Cut	224.80 FL	*45.00 FL
6	4		*TAILGATE HINGES	Bent	358.40 FL	*358.40 FL
7	2		*TAILGATE LOWER HOOKS	Not Necessary	137.00 FL	*- FL
8	1		*TAILGATE LOWER PANEL	Dented	852.20 FL	*545.00 FL
9	2		*REAR CHASSIS FRAME MEMBER	Repair	1,975.20 FL	*- FL
10	1		*REAR LOWER CHASSIS MEMBER	Bent	857.20 FL	*748.00 FL
11	2		*REAR NUMBER PLATE LAMPS	Not Necessary	109.60 FL	*- FL
12	1		*REAR NUMBER PLATE BASE	Bent	125.90 FL	*125.90 FL
13	2		*TAILAMPS	Cracked	691.60 FL	*570.60 FL
14	2		*TAILAMPS BASE	Bent	511.20 FL	*238.00 FL
15	1		*SPARE TYRE CARRIER	Missing	385.90 FL	*385.90 FL
16	1		*SPARE TYRE CARRIER BRACKET	Not Necessary	185.20 FL	*- FL
17	1		*REAR EXHAUST PIPE	Bent	385.70 FL	*385.70 FL
18	2		*REAR EXHAUST PIPE MOUNTINGS	Not Necessary	157.00 FL	*- FL
19	1		*REAR EXHAUST PIPE BRACKET	Not Necessary	198.50 FL	*- FL
20	2		*REAR CARRIER PANEL	Not Necessary	1,179.20 FL	*- FL
21	4		*SIDE PANEL HINGES	Not Necessary	342.80 FL	*- FL
22	1		*REAR NUMBER PLATE WITH CASING	Bent	50.00 FS	*30.00 FS
23	1		*REAR STEP PANEL	Bent	280.00 FS	*180.00 FS
24	1		*REAR TOOL BOX	Dented	650.00 FS	*380.00 FS
25	1		*REAR TOOL BOX BRACKET	Bent	250.00 FS	*150.00 FS
26	1		*TAILGATE DYNA STICKER	Necessary	55.00 FS	*30.00 FS
27	1		*TAILGATE 1500KG STICKER	Necessary	55.00 FS	*30.00 FS
28	1		*TAILGATE 6 PAX STICKER	Necessary	15.00 FS	*15.00 FS
29	1		*TAILGATE 70KM/H STICKER	Necessary	15.00 FS	*15.00 FS
30	1		*TAILAMP LOWER REFLECTORS (ROUND)	N/S Cut	90.00 FS	*20.00 FS
31	1		*TAILGATE COMPANY STICKER	Necessary	550.00 FS	*350.00 FS
32	2		*TAILGATE SIDE TOP PROTECTIVE BAR	Not Necessary	1,300.00 FS	*- FS
33	1		*SPARE TYRE (BIG)	Not Necessary	180.00 FS	*- FS
34	1		*ALLOY RIM (BIG)	Not Necessary	350.00 FS	*- FS
35	1		*SPARE TYRE (SMALL)	Not Necessary	180.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*ALLOY RIM (SMALL)	Not Necessary	350.00 FS	*- FS
37	1		*SET RIVETS	Not Necessary	150.00 FS	*- FS
38	1		*REAR FLOOR TOP ALUMINIUM PLATE	Not Necessary	1,200.00 FS	*- FS
39	2		*SIDE COMPANY STICKER	Not Necessary	1,100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	17,578.10	6,188.20
- List Item Discount on L Items 25.00/25.00% (\$)	2,689.53	1,247.05
Total Parts (\$)	14,888.57	4,941.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RENEW ,REPAIR ,REALIGN DAMAGED PARTS ,REPLACE BEAT AND WELD	New	2,200.00	800.00
2	TO RESRPAY AFFECTED AREAS	New	2,000.00	600.00
3	TO TUFFCOAT AFFECTED AREA	New	200.00	60.00
4	TO REMOVE /REPLACE REAR ALUMINIUM PLATE	New	400.00	0.00
5	LABOUR TO APPLY SEALANT TO AFFECTED AREAS	New	180.00	60.00
6	TO CONDUCT WIRING CHECK AND ADJUST THE REAR TAILAMPS	New	180.00	30.00
7	TO REMOVE /REFIT REAR SILENCER BOX	New	150.00	80.00
8	LABOUR TO REMOVE AND WRAPPING OF THE COMPANY STICKER	New	300.00	50.00
Gross Labour Cost (S\$)			5,610.00	1,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >