

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Mithoo Singh, Aashweenjeet Kaur

Date: 08 Jan 2021

Preliminary Advice

Vehicle No	: GBK837X	Accident Date	: 21/12/2020
Make	: TOYOTA HIACE	Policy No.	: 2070175444
Assignment Date	: 07/01/2021	Excess	: S\$0.00
Date of Inspection	: 07/01/2021	Est. Duration of Repair	: 6
Inspection At	: OMEGA AUTO PTE LTD 160 SIN MING DRIVE #06-06, SIN MING AUTO CITY SINGAPORE 575722		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,802.50
Revised Amount	:S\$	4,882.75
Check Items (Estimated)	:S\$	1,250.25
Total	:S\$	6,133.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	67,000.00
COE / PARF Rebate	:S\$	19,921.00
Salvage Value	:S\$	
Margin for Repair	:S\$	47,079.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :