

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21000219/KGA3Q2  
**Date:** 08/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070122980
<b>Claimant Vehicle No :</b>	SJA9852A	<b>Insured Vehicle No :</b>	SMV7860T
Date of Loss:	30/12/2020	Nature of Claim:	TP
		Claim No:	2941361512SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SJA9852A</b>	Engine No:	BLG031528
Make & Model:	VOLKSWAGEN GOLF, 1.4 GT TSI (A)	Chassis No:	WVWZZZ1KZ8U013542
Reg. Date:	27/12/2007 (Man. Year: 2007)	Odometer:	225214 km
Colour:	Metallic Black		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Goodyear 8 mm	Rear Left Side:	Goodyear 8 mm
Front Right Side:	Goodyear 8 mm	Rear Right Side:	Goodyear 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,062.01	4,019.58	3,042.43	43.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,840.00	1,380.00	460.00	25.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,902.01</b>	<b>5,399.58</b>	<b>3,502.43</b>	<b>39.34</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,050.00</b>		

(S\$)	8,902.01	5,050.00	3,852.01	43.27
<b>+ GST 7.00/7.00% (S\$)</b>	623.14	353.50	269.64	43.27
<b>Nett Amount (S\$)</b>	<b>9,525.15</b>	<b>5,403.50</b>	<b>4,121.65</b>	<b>43.27</b>
<b>+ Car Rental (4.0 x S\$100.00/day) (S\$)</b>		400.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>5,805.50</b>		

INSPECTION

Date of Assignment: 05/01/2021

Date Inspected: 06/01/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Ah Lim Motor Company (AMK)  
 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint  
 Singapore 568047

**Adjuster:** KENNETH KONG**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,875.45 FL	*1,875.45 FL
2	1		*TAILGATE EMBLEM	Not Necessary	710.55 FL	*- FL
3	1		*TAILGATE GOLF LOGO	Necessary	94.35 FL	*94.35 FL
4	1		*TAILGATE TST LOGO	Necessary	87.25 FL	*87.25 FL
5	1		*TAILGATE LAMP LH	Cracked	269.70 FL	*269.70 FL
6	1		*TAILGATE LOCK	Repair	192.30 FL	*- FL
7	1		*TAILGATE LOCK CATCH	Repair	98.45 FL	*- FL
8	1		*TAILGATE INNER TRIMBOARD	Serviceable	562.80 FL	*- FL
9	1		*TAILGATE RUBBER (50%)	Distorted / Dented	291.47 FS	*161.93 FS
10	1		*REAR BUMPER	Buckled	1,088.40 FL	*1,088.40 FL
11	1		*REAR BUMPER LOWER GARNISH	Dented	400.90 FL	*400.90 FL
12	2		*REAR BUMPER SIDE RETAINER LH& RH	Serviceable	93.50 FL	*- FL
13	12		*REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
14	1		*REAR BUMPER CTR RETAINER	Cracked	112.45 FL	*112.45 FL
15	1		*REAR BUMPER REINFORCEMENT	Repair	611.05 FL	*- FL
16	1		*REAR END PANEL	Repair	806.85 FL	*- FL
17	1		*REAR END PANEL GARNISH	Serviceable	161.05 FL	*- FL
18	1		*INNER SEAL	Necessary	20.00 FS	*20.00 FS
19	1		*WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
20	1		*NUMBER PLATE	Dented	35.00 FS	*35.00 FS
21	1		*SET REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>7,781.52</b>	<b>4,415.43</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	719.51	395.85
<b>Total Parts (\$\$)</b>	<b>7,062.01</b>	<b>4,019.58</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING ,WIRE SOCKETS AND ETC .TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS ,TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	20.00
2	TO REMOVE AND REINSTALL /REPLACED FRONT /REAR WINDSCREEN	New	120.00	120.00
3	TO REMOVE AND REINSTALL /REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES	New	60.00	60.00
4	TO REMOVE AND REINSTALL REPLACE FRONT /REAR BUMPER SENSORS	New	60.00	50.00
5	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	60.00	30.00
6	TO DISMANTLE ALL DAMAGED PARTS .TO CUT & WELD END PANEL TO KNOCK & REPAIR SPARE TYRE PANEL ,REAR INNER PANELS AND AFFECTED AREAS.TO REFIT LISTED PARTS BACK SAME	New	800.00	500.00
7	TO SPRAY TAILGATE ,REAR BUMPER ,END PANEL	New	700.00	600.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,840.00</b>	<b>1,380.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >