



SERVICE REQUESTS

MESSAGES

CLAIMS

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving TPVD TBC (SJK6153U)

Date of Loss 4 January 2021

Time of Loss 7.30

Loss Description SHD6595U (INSD) C/W SJK6153U > SJP9311R

Comment

Workshop Details

Total Rebate Amount

Nett Loss Amount \$13,333.00

Assigned Workshop LKK AUTO CONSULTANTS PTE LTD (TP)

Days of work completion *



SERVICE REQUESTS

MESSAGES

CLAIMS

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# SJQ6153U

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

19/05/2009



Mileage

168956

Age of Vehicle

11

Driver Details

CATEGORY

POLICY
INFORMATION

ASSESSMENT INFORMATION

Manufacturing
Year

2009

Make

TPVD

KIA

Model

TBC

CERATO FORTE 1.6(A) !

CATEGORY

FNOL INFORMATION

POST SURVEY
INFORMATION

Driver Name

NARESH KUMAR S/O
MEENACHISUNDARAM

Date of Birth

dd/mm/yy



Age

0



SERVICE REQUESTS

MESSAGES

CLAIMS

Type of Paint

Chassis No

KNAFH221395068159

Engine No

G4FC9H251295

Engine
Capacity

1591

Sum Insured

0

Market Value

22000

CATEGORY

FNOL INFORMATION

POST SURVEY
INFORMATION

Occupation

Unknown

Education
Qualification

Other

Driving
Experience

0

Driver
License #

License Type

License Issue
Date

dd/mm/yy

License
Expiration
Date

dd/mm/yy

Address

Singapore

English (SG) ▾

LKK AUTO CONSULTANTS PTE LTD (TP) ▾



SERVICE REQUESTS

MESSAGES

CLAIMS

CATEGORY

FNOL INFORMATION

POST SURVEY
INFORMATION

Address type

Personal Correspondence

Gender

Unknown

Marital
status

Unknown

Identification
#

TBC



SERVICE REQUESTS

MESSAGES

CLAIMS

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

06/01/2021



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/
Unnamed Driver
Excess

0

Other Excess

Age of Tyres

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Tyre Condition

Spare wheel

English (SG) ▾

LKK AUTO CONSULTANTS PTE LTD (TP) ▾



SERVICE REQUESTS

MESSAGES

CLAIMS

Front right side

GOODYEAR8mm

Rear Tyre Size

215/45R17

Rear left side

GOODYEAR4mm

Rear right side

GOODYEAR4mm



SERVICE REQUESTS

MESSAGES

CLAIMS

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

10

Settlement%

100

Paint Labour/Material Ratio

Paint Labour Ratio

20

Paint Material Ratio

80

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save



SERVICE REQUESTS

MESSAGES

CLAIMS

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	2		FRONT HEADLAMP ASSY	Cracked	0	497	No		10			894.6	Reviewing
<input type="checkbox"/>		0	1		FRONT GRILLE	Cracked	0	255	No		10			229.5	Reviewing
<input type="checkbox"/>		0	1		FRONT GRILLE EMBLEM	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		FRONT BUMPER	Cracked	0	562	No		10			505.8	Reviewing
<input type="checkbox"/>		0	1		FRONT BUMPER REINFORCEMENT	Bent	0	356	No		10			320.4	Reviewing
<input type="checkbox"/>		0	1		FRONT BUMPER SPONGE	Cracked	0	155	No		10			139.5	Reviewing
<input type="checkbox"/>		0	1		FRONT BUMPER LOWER GRILLE	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		FRONT SUPPORT PANEL	Cracked	0	550	No		10			495	Reviewing
<input type="checkbox"/>		0	1		REAR BOOTLID	Bent	0	793.8	No		10			714.42	Reviewing
<input type="checkbox"/>		0	1		REAR BOOT LID INNER LOCK	Dented	0	155	No		10			139.5	Reviewing



SERVICE REQUESTS

MESSAGES

CLAIMS

OT LID
HROME

HANDLE

Damaged

0

197

No

10

177.3

Reviewing



0

1

REAR BOOT LID
EMBLEM "KIA"

Necessary

0

48

No

10

43.2

Reviewing



0

1

REAR BOOT LID
EMBLEM
"CERATO"

Necessary

0

45

No

10

40.5

Reviewing



0

1

N/S REAR BOOT
LID LAMP

Serviceable

0

0

No

10

0

Deny



0

1

O/S REAR BOOT
LID LAMP

Cracked

0

405

No

10

364.5

Reviewing



0

2

REAR TAIL-LAMP
ASSY

Cracked

0

605

No

10

1089

Reviewing



0

2

REAR TAIL-LAMP
PANEL

Bent

0

235

No

10

423

Reviewing



0

1

REAR END PANEL

Bent

0

488

No

10

439.2

Reviewing



0

1

REAR END PANEL
INNER GARNISH

Damaged

0

155

No

10

139.5

Reviewing



0

2

REAR FENDER
INNER TRIM
BOARD

Serviceable

0

0

No

10

0

Deny



0

1

REAR N/S
FENDER AIR
DUCT

Serviceable

0

0

No

10

0

Deny

English (SG) ▾

LKK AUTO CONSULTANTS PTE LTD (TP) ▾

				E	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
	SERVICE REQUESTS	MESSAGES	CLAIMS	ORDER FIELD	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1	REAR SPARE TYRE PANEL	Bent	0	685	No		10			616.5	Reviewing
<input type="checkbox"/>		0	1	REAR SPARE TYRE COVER BOARD	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1	REAR BUMPER	Bent	0	658	No		10			592.2	Reviewing
<input type="checkbox"/>		0	2	REAR BUMPER BRACKET	Repair	0	0	No		10			0	Deny
<input type="checkbox"/>		0	2	REAR BUMPER SIDE RETAINER	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1	REAR BUMPER REINFORCEMENT	Cracked	0	356	No		10			320.4	Reviewing
<input type="checkbox"/>		0	1	REAR BUMPER SPONGE	Cracked	0	135	No		10			121.5	Reviewing
<input type="checkbox"/>		0	1	BONNET	Bent	0	655.7	No		10			590.13	Reviewing
<input type="checkbox"/>		0	1	BOOT LID INSULATOR	Deformed	0	195.1	No		10			175.59	Reviewing
<input type="checkbox"/>		0	3	REAR REVERSE SENSOR - 4PCS	Cracked	0	210	No		10			567	Reviewing
<input type="checkbox"/>		0	1	REAR EXHAUST SILENCER	Bent	0	762	No		10			685.8	Reviewing

Labour

			NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
	SERVICE REQUESTS	MESSAGES	CLAIMS						
<input type="checkbox"/>		0	REMOVE / RENEW THE ABOVE PARTS INCLUDING KNOCKING, CUTTING & WELDING	0	1400	0	0	Reviewing	
<input type="checkbox"/>		0	TO PUTTY & SPRAY PAINT ON ACCIDENT AFFECTED PORTION	0	1400	0	0	Reviewing	
<input type="checkbox"/>		0	CHECK / RECONNECT WIRING	0	40	0	0	Reviewing	
<input type="checkbox"/>		0	TO SPRAY ANTI RUST ON ACCIDENT AFFECTED PORTION	0	120	0	0	Reviewing	
<input type="checkbox"/>		0	REMOVE / REFIT REAR BOOT UPHOLSTERY TO FACILITATE REPAIR	0	80	0	0	Reviewing	
<input type="checkbox"/>		0	REMOVE / REFIT FUEL TANK TO FACILITATE REPAIR	0	60	0	0	Reviewing	
<input type="checkbox"/>		0	REMOVE / RENEW REAR EXHAUST SILENCER	0	60	0	0	Reviewing	
<input type="checkbox"/>		0	REMOVE / REFIT AIR CON CONDENSER AND TO TOP UP GAS	0	100	0	0	Reviewing	



SERVICE REQUESTS

MESSAGES

CLAIMS

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

- Add
- Approve
- Deny
- Submit All

	EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		0	DAYS OF REPAIR : 12 DAYS	Reviewing		0		
<input type="checkbox"/>		0	REAR BOOT RUBBER (\$187.00) (50%)	Reviewing		93.5	CUT	
<input type="checkbox"/>		0	FRONT NO PLATE	Reviewing		40	DENTED	

English (SG) ▾

LKK AUTO CONSULTANTS PTE LTD (TP) ▾

MATED
DUNT

ADJUSTED
AMOUNT

COMMENT

REMOVE



SERVICE REQUESTS

MESSAGES

CLAIMS



0

TYRE
PANEL
BLACK
INSULATOR

Reviewing

100

NECESSARY



0

REAR NO
PLATE

Reviewing

40

DENTED



0

REAR
BUMPER
CLIP -
20PCS

Reviewing

40

NECESSARY





SERVICE REQUESTS

MESSAGES

CLAIMS

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim
Amount

\$0.00

Adjusted Claim
Amount

\$13,397.54

CATEGORY

ESTIMATE

ADJUSTED

Spare Parts

\$0.00

\$9,824.04

Labour

\$0.00

\$3,260.00

Miscellaneous

\$0.00

\$313.50

Submit for Review



SERVICE REQUESTS

MESSAGES

CLAIMS

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

- Add
- Approve
- Deny
- Submit All

	EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		0	FINAL LUMP SUM	Reviewing		10550		



SERVICE REQUESTS

MESSAGES

CLAIMS

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim
Amount

\$0.00

Adjusted Claim
Amount

\$10,550.00

CATEGORY

ESTIMATE

ADJUSTED

Miscellaneous

\$0.00

\$10,550.00

Submit for Review