

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURAN	NCE BHD		Ref:	CS3/LPC21000224/Gqd3e2	
	300 BEACH ROAD SINGAPORE 1995	#17-04/07 THE CONCOURSE 55		Date:	14/01/2021	
				Code:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	GBF 5936L	Veh. Inspected		SKA 6187U	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	20/21/21/VC00/024082	Excess (\$)		0.00	
	Assign From	ONG LI LI	Assign Date		05/01/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA PREVIA	c.c		2362	
	Engine No.	HIDDEN	Year of Reg.		2011	
	Chassis No.	JTEGD54M30A026773	Colour		SILVER	
	Odometer	150983 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	215/60 R16	KAPSEN		6 mm	
	L/H Front Tyre	215/60 R16	KAPSEN		6 mm	
	R/H Rear Tyre	215/60 R16	KAPSEN		6 mm	
	L/H Rear Tyre	215/60 R16	KAPSEN		6 mm	
4. Description of Damages						
	THE VEHICLE SUS	ISTAINED DAMAGES AT THE REAR PORTION.				
5.	General Information					
	Accident Date	02/01/2021	Inspect Date /	Time	11/01/2021 (04:30 PM)	
	Survey held at	HUP LEY HUAT MOTOR SPRAY PAINTING SVS				
		BLK 1 KAKI BUKIT AVE 6, #01-35 AUTOBAY SINGAPORE 417883				
5a.		Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC21000224/Gqd3e2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor