

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21000232/T1PA3Q2
Date: 19/11/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100417875
Claimant Vehicle No :	GV3399G	Insured Vehicle No :	SKT6649D
Date of Loss:	04/12/2020	Nature of Claim:	TP
		Claim No:	0854506661SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GV3399G		
Make & Model:	MERCEDES-BENZ VITO 113, 2.1 D Long (M)	Engine No:	65194031109966
Reg. Date:	05/12/2012 (Man. Year: 2012)	Chassis No:	WDF63960323744675
Colour:	Grey	Odometer:	202753 km
Engine Capacity:	2143 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,119.11	4,523.48	1,595.63	26.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,010.00	1,580.00	430.00	21.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,129.11	6,103.48	2,025.63	24.92
Approved Total (Overridden) (S\$)		4,800.00		

(S\$)	8,129.11	4,800.00	3,329.11	40.95
+ GST 7.00/7.00% (S\$)	569.04	336.00	233.04	40.95
Nett Amount (S\$)	8,698.15	5,136.00	3,562.15	40.95
+ Loss of Use (6.0 x S\$120.00/day) (S\$)		720.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,863.45		
Global Sum Settlement (S\$)		5,800.00		

INSPECTION

Date of Assignment: 12/01/2021

Date Inspected: 12/01/2021

Estimated Period of Repair: 6.0 days

Inspected At:

Woon Meng Motor Pte Ltd (Bukit Batok)
 50 Bukit Batok Street 23,, #01-06 Midview Building
 Singapore 659578

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	2,998.72 FL	*2,550.00 FL
2	1		*VIANO	Necessary	89.20 FL	*89.20 FL
3	1		*EMBLEM	Necessary	115.49 FL	*115.49 FL
4	1		*REAR BUMPER SIDE O/S	Deformed	454.71 FL	*354.00 FL
5	1		*REAR BUMPER CENTER	Deformed	1,534.20 FL	*1,334.00 FL
6	1		*REAR BUMPER REFLECTOR O/S	Missing	181.94 FL	*181.94 FL
7	1		*REAR LAMP O/S	Not Necessary	899.61 FL	*- FL
8	1		*REAR BUMPER BRACKET	N/S Not Necessary/O/SNecessary	202.92 FL	*101.46 FL
9	2		*REAR WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
10	1		*6 PAX	Necessary	15.00 FS	*15.00 FS
11	1		*70KM/H	Necessary	15.00 FS	*15.00 FS
12	1		*SET REAR SENSOR	Not Working	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)
6,766.79
4,996.09
- List Item Discount on L Items 10.00/10.00% (\$\$)
647.68
472.61
Total Parts (\$\$)
6,119.11
4,523.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,REPLACE ,REPAIR & WELD REAR DAMAGED PARTS	New	900.00	700.00
2	TO REMOVE & REPLACE REAR WINDSCREEN GLASS	New	150.00	120.00
3	TO R&R LIGHT WIRING	New	60.00	30.00
4	TO R&R SENSOR WIRING	New	100.00	30.00
5	TO PUTTY & SPRAY PAINTING	New	800.00	700.00
Gross Labour Cost (S\$)			2,010.00	1,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >