



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLX 6729Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DISTORTED	1,286.40	585.20
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	420.80	-
1	FRONT BUMPER INNER SPONGE	NOT NECESSARY	210.30	-
1	FRONT BUMPER CENTRE AIR-GRILLE	NOT NECESSARY	195.60	-
1	FRONT BUMPER SIDE GARNISH RH	NOT NECESSARY	286.20	-
1	FRONT BUMPER FOG LAMP RH	NOT NECESSARY	296.40	-
1	FRONT BUMPER BRACKET RH	NOT NECESSARY	175.40	-
1	FRONT BUMPER SIDE RETAINER RH	BENT	112.40	39.50
1	SET FRONT BUMPER CLIPS	NECESSARY	60.00	38.00
1	FRONT RADIATOR GRILLE BASE	NOT NECESSARY	495.10	-
1	FRONT RADIATOR GRILLE LOGO	NOT NECESSARY	125.40	-
1	FRONT HEADLAMP ASSY RH	SCRATCHED	1,186.90	1,186.90
1	FRONT HEADLAMP BRACKET RH	NOT NECESSARY	210.50	-
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	985.40	-
1	FRONT FENDER INNER SHIELD RH	DEFORMED	298.30	166.20
1	SET FRONT FENDER INNER SHIELD CLIPS	NOT NECESSARY	60.00	-
1	FRONT KNUCKLE ARM RH	NOT NECESSARY	786.20	-
1	FRONT KNUCKLE HUB,WHEEL BEARING RH	NOT NECESSARY	495.70	-
1	FRONT LOWER ARM RH	NOT NECESSARY	520.30	-
1	FRONT LOWER ARM BALL JOINT RH	NOT NECESSARY	245.10	-
1	FRONT SHOCK ABSORBER RH	NOT NECESSARY	395.80	-
	LESS 20% DISCOUNT		-1,769.64	-403.16
			7,078.56	1,612.64
<u>SPECIAL NETT ITEMS</u>				
1	FRONT BUMPER LOWER LIP (ACCESSORIES)(SN)	GRAZED / CRACKED	1,400.00	1,000.00
1	FRONT BUMPER LOWER LIP CENTRE GARNISH (ACCESSORIES)(SN)	NOT NECESSARY	980.00	-
1	FRONT BUMPER LOWER SIDE LIP RH (ACCESSORIES)(SN)	CRACKED	650.00	250.00
1	FRONT FOG LAMP SIDE UP RH (ACCESSORIES)(SN)	NOT NECESSARY	480.00	-

Report Ref No. CS/INC21000250/Uvd3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BUMPER FOG LAMP GARNISH W/LIGHTS (ACCESSORIES)(SN)	NOT NECESSARY	580.00	-
1	FRONT BUMPER STICKER (ACCESSORIES)(SN)	NECESSARY	250.00	100.00
1	FRONT RH RIM (SN)(CUT)	NOT CONSISTENT WITH THE IMPACT	950.00	-
1	FRONT RH TYRE (SN)	NOT NECESSARY	320.00	-
			5,610.00	1,350.00
	LABOUR			
	TO REMOVE,REPAIR & RENEW AFFECTED ACCIDENT AREAS.INCLUSIVE OF THE REPAIR OF FRONT FENDER RH.		1,000.00	300.00
	TO PUTTY,SPRAY PAINT ON FRONT AFFECTED ACCIDENT AREAS.		1,200.00	600.00
	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING.		50.00	20.00
	TO REMOVE & INSTALL FRONT RIGHT UNDERCARRIAGE COMPONENTS.	NOT NECESSARY	250.00	-
	TO CONDUCT ALL WHEEL ALIGNMENT.	NOT NECESSARY	250.00	-
	TO DIAGNOSTIC & RESET TO SPECIFICATION.	NOT NECESSARY	450.00	-
	TO RUST PROOF AFFECTED AREAS.	NOT NECESSARY	200.00	-
			3,400.00	920.00
GRAND TOTAL			16,088.56	3,882.64
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				3,100.00

Report Ref No. CS/INC21000250/Uvd3q2

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.