

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT NTUC INCOME INSURANCE CO-OPERATIVE LTD CS3/INC21000258/Gvd3e2 Ref: 73 BRAS BASAH ROAD #05-01 NTUC TRADE Date: 15/01/2021 UNION HOUSE SINGAPORE 189556 ATTN: ENG HUEY HUEY Code: INC 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SLB 6279X SMF 9196Z Veh. Inspected Policy No. Coverage (\$) 0.00 Claim No. MT/1116082-002 Excess (\$) 0.00 THERESA VIMALA **Assign Date** 06/01/2021 Assign From **Vehicle Particulars & Condition** 2. **HYUNDAI ELANTRA 1.6** Make & Model 1591 C.C HIDDEN 2016 Engine No. Year of Reg. KMHD841CMHU144125 RED Chassis No. Colour 141096 KM Odometer Steering IN ORDER **IN ORDER** STANDARD ALLOY RIM **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 205/55 R16 YOKOHAMA 6 mm YOKOHAMA L/H Front Tyre 205/55 R16 6 mm 205/55 R16 YOKOHAMA R/H Rear Tyre 6 mm YOKOHAMA L/H Rear Tyre 205/55 R16 6 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. 5. **General Information** 03/01/2021 06/01/2021 (05:40 PM) Inspect Date / Time Accident Date **GARAGE 13 PTE LTD** Survey held at 8 KAKI BUKIT AVE 4 #03-46 PREMIER 415875 SINGAPORE. 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

Report Ref No. CS3/INC21000258/Gvd3e2

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

Inspected By

XING GUO QIANG

M.MATAI. AMSAE-A

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor