



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |                                     |                 |                               |  |
|--|-------------------------------------|-----------------|-------------------------------|--|
| LONPAC INSURANCE BHD<br>300 BEACH ROAD<br>#17-04/07 THE CONCOURSESINGAPORE 199555  |                                     |                 | Ref: CS3/LPC20009444/Gtd3e2-2 |  |
|  |                                     |                 | Date: 29/01/2021              |  |
|  |                                     |                 | Code: LPC2                    |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)</b>  |                                     |                 |                               |  |
| Insured Veh.   | GBC 9923M                           | Veh. Inspected  | YN 8114H                      |  |
| Policy No.   |                                     | Coverage (\$)   | 0.00                          |  |
| Claim No.  | 20/20/20/VC05/023622                | Excess (\$)     | 0.00                          |  |
| Assign From  | ONG LI LI                           | Assign Date     | 06/01/2021                    |  |
| <b>2. Vehicle Particulars &amp; Condition</b>  |                                     |                 |                               |  |
| Make & Model   | ISUZU NPR85UH5A 3.0                 | c.c             | 2999                          |  |
| Engine No.   | HIDDEN                              | Year of Reg.    | 2015                          |  |
| Chassis No.  | JAANPR85HF7100196                   | Colour          | BLUE                          |  |
| Odometer   | 323775 KM                           | Steering        | IN ORDER                      |  |
| Brakes   | IN ORDER                            | Modification    | NIL                           |  |
| General  | GOOD                                |                 |                               |  |
| <b>3. Conditions of Tyres</b>  |                                     |                 |                               |  |
|  | Size                                | Make            | Balance                       |  |
| R/H Front Tyre   | 195/85 R16                          | WEST LAKE       | 6 mm                          |  |
| L/H Front Tyre   | 195/85 R16                          | WEST LAKE       | 6 mm                          |  |
| R/H Rear Tyre  | 205/85 R16                          | HANKOOK         | 6 mm                          |  |
| L/H Rear Tyre  | 205/85 R16                          | HANKOOK         | 6 mm                          |  |
| <b>4. Description of Damages</b>   |                                     |                 |                               |  |
| THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.<br>REPAIR CONDITION SEE DETAILS.   |                                     |                 |                               |  |
| <b>5. General Information</b>  |                                     |                 |                               |  |
| Accident Date  | 03/09/2020                          | Inspection Date | 20/01/2021                    |  |
| Survey held at   | BLK 7 SIN MING IND EST SEC C #01-76 |                 |                               |  |
| Repairer   | MJE MOTOR                           |                 |                               |  |
| <b>5a. Remarks</b>   |                                     |                 |                               |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                     |                 |                               |  |
| <b>5b. Estimate Days of Repair</b>   |                                     |                 |                               |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:  |                                     |                 | 1 Working Days                |  |