

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4795C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER FRT (DISC 25%)	DEFORMED	482.00	361.50
10	BUMPER CLIPS @\$1.61 (DISC 25%)	NECESSARY	16.10	12.08
1	FENDER FRT / RH	SERVICEABLE	723.40	-
1	NAME PLATE (HYBRID)	SERVICEABLE	51.90	-
1	BUMPER SUPPORT F/RH	SERVICEABLE	76.40	-
1	BUMPER ENERGY ABSORBER FRT	SERVICEABLE	78.80	-
1	BUMPER REINFORCEMENT FRT	SERVICEABLE	498.40	-
1	ARM SUB-ASSY, FR BUMPER RH	SERVICEABLE	250.40	-
1	BUMPER GRILLE SUB-ASSY, LOWER	SERVICEABLE	311.10	-
1	LENS & BODY, FR TURN RH	SERVICEABLE	511.80	-
1	FENDER LINER FRT / RH	SERVICEABLE	171.70	-
1	FENDER LINER PAD, FR WHEEL, RH	SERVICEABLE	49.30	-
1	HEAD LAMP RH	SERVICEABLE	945.20	-
1	BRACKET, FR BUMPER	SERVICEABLE	110.40	-
			4,276.90	373.58
	<u>LABOUR</u>			
	PANEL BEATING AND BODY WORK.		338.00	200.00
	SPRAY PAINT.		558.00	200.00
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	20.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO CHECK & RESET SYSTEM FUNCTION.	NOT NECESSARY	80.00	-
			1,216.00	420.00
	GRAND TOTAL		5,492.90	793.58





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		650.00
(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)		

Report Ref No. NS/INC21000267/Qqd3e2

Ja

OI SUN PIN

**Asst. Automotive Assessor** 

L

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

**REGD Auto Consultant-SAE, Licensed Appraiser**