



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 6989S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT BUMPER	CRACKED	430.90	430.90
1	FRT BUMPER BRKT LH	NOT NECESSARY	28.00	-
1	FRT BUMPER MOULDING LH	CUT	93.60	93.60
1	DAY RUNNING LIGHT LH	NOT NECESSARY	642.50	-
	LESS 20% DISCOUNT		-239.00	-104.90
			956.00	419.60
	<u>LABOUR</u>			
	PANEL BEATING.		350.00	320.00
	SPRAYPAINT CHARGE.		250.00	200.00
	CHECK ALL LIGHTING.		40.00	30.00
			640.00	550.00
GRAND TOTAL			1,596.00	969.60
RECOMMENDED COST OF REPAIRS (CONFIRMED)				969.60

Report Ref No. NS/INC21000269/T1vd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.