

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 1405J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	TO REPAIR SEE LABOUR	1,106.00	-
1	REAR BUMPER BRACKET RH	NOT NECESSARY	35.00	-
1	REAR RH DOOR PANEL	BENT	2,201.10	2,201.10
1	REAR RH FENDER	TO REPAIR SEE LABOUR	2,171.40	-
1	REAR DOOR PROTECTOR RH	NOT NECESSARY	56.90	-
1	REAR WHEEL CAP RH	NOT NECESSARY	214.20	-
	LESS 20% DISCOUNT		-1,156.92	-440.22
			4,627.68	1,760.88
	SPECIAL NETT ITEMS			
1	REAR BUMPER MAT (SN)	NOT NECESSARY	50.00	-
1	REAR BUMPER ADVERTISEMENT (SN)	NOT NECESSARY	50.00	-
1	REAR DOOR ADVERTISEMENT (SN)	CUT	100.00	100.00
1	REAR DOOR COMFORT APP STICKER (SN)	NECESSARY	72.00	72.00
1	REAR FENDER ADVERTISEMENT (SN)	CUT	100.00	100.00
			372.00	272.00
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BUMPER AND REAR RH FENDER.		800.00	640.00
	SPRAY PAINTING CHARGE.		800.00	600.00
	REMOVE/REFIX DOOR PARTS.		120.00	60.00
	TUFF COAT.		120.00	30.00
	REMOVE/REFIX REAR LH UPHOLSTERY.		90.00	60.00
			1,930.00	1,390.00
	GRAND TOTAL		6,929.68	3,422.88





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		2,750.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. NS/INC21000270/T1qd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser