

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/TMI21000272/KQD3Q2

**Date:** 13/01/2021

### REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MT104890

**Claimant**  
**Vehicle No :** SHC5436H

**Insured Vehicle No :** SMD489Z

Date of Loss: 04/01/2021

Nature of Claim: TP

Claim No: M2100052

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC5436H**

Make & Model: RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR (A)

Engine No: M9R8839C002077

Reg. Date: 19/11/2014 (Man. Year: 2014)

Chassis No: VF1ABL15AUC280058

Colour: Metallic White/Red

Odometer: 685059 km

Engine Capacity: 1995 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/60R16

Rear Tyre Size:

215/60R16

Front Left Side: Sailun 9 mm

Rear Left Side:

Sailun 9 mm

Front Right Side: Sailun 9 mm

Rear Right Side:

Sailun 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,671.58	1,008.24	1,663.34	62.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,070.00	480.00	6,590.00	93.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,741.58</b>	<b>1,488.24</b>	<b>8,253.34</b>	<b>84.72</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,200.00</b>		
<b>(S\$)</b>	9,741.58	1,200.00	8,541.58	87.68
<b>+ GST 7.00/7.00% (S\$)</b>	681.91	84.00	597.91	87.68
<b>Nett Amount (S\$)</b>	<b>10,423.49</b>	<b>1,284.00</b>	<b>9,139.49</b>	<b>87.68</b>

### INSPECTION

Date of Assignment: 07/01/2021

Date Inspected: 05/01/2021 Inspected At:

TRANS-CAB AUTO SERVICES PTE LTD  
NO.2 ANG MO KIO ST 63  
SINGAPORE 569111

Estimated Period of Repair: 1.5 days

**Adjuster:** KENNETH KONG

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 13 Jan 2021)
<b>Parts:</b>	143	RENAULT LATITUDE 2.0 L DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHC5436H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*BUMPER COVER REAR	Buckled	561.70 FL	-	*561.70 FL
2	1		*BUMPER LOWER REAR	Dented/Cut	411.90 FL	-	*411.90 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	98.10 FL	-	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	82.10 FL	-	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	59.80 FL	-	*- FL
6	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	80.80 FL	-	*- FL
7	1		*BUMPER RETAINER LH REAR	Serviceable	54.20 FL	-	*- FL
8	1		*BUMPER BEAM REAR	Repair	547.80 FL	-	*- FL
9	1		*SET PARKING AID	Serviceable	700.00 FS	-	*- FS
10	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	-	*66.00 FS
11	1		*SET BUMPER BRACKET CTR CLIP	Not Necessary	33.00 FS	-	*- FS
12	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	-	*- FS
13	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	-	*- FS
14	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	-	*- FS
15	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	-	*- FS
16	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	-	*- FS
17	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	-	*66.00 FS
18	1		*EXHAUST MOUNTING REAR	Serviceable	17.82 FS	-	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>2,861.22</b>	<b>1,105.60</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	189.64	97.36

<b>Total Parts (\$\$)</b>	<b>2,671.58</b>	<b>1,008.24</b>
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	220.00
2	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	3,000.00	200.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
5	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
6	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
7	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
8	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>7,070.00</b>	<b>480.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >