Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI21000273/KVD3Q2

Date: 15/01/2021

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MK000765 Claimant

SHC5020Z **Insured Vehicle No:** SLJ7565X Vehicle No:

Date of Loss: Nature of Claim: TP 26/12/2020 Claim No: M2100114

DESCRIPTION & IDENTIFICATION OF VEHICLE

SHC5020Z Reg No:

Make & Model: TOYOTA PRIUS, 1.5 (A) Engine No: 2ZR2G79750

Chassis No: Reg. Date: 28/08/2020 (Man. Year: 2020) JTDKB3FU003091400

Colour: Metallic Pearl White/Red Odometer: 28884 km

Engine Capacity: Market Value/New Car

N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

1798 cc

CONDITION OF VEHICLE AT THE TIME OF SURVEY

Yes Footbrake (Serviceable): General Condition: Steering (Serviceable): Yes

Yes Engine Modification: Pre-accident Condition: Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65r15 Front Left Side: Sailun 9 mm Rear Left Side: Dunlop 5 mm Front Right Side: Rear Right Side: Dunlop 5 mm Sailun 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,143.77	1,203.02	5,940.75	83.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,100.00	1,330.00	3,770.00	73.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,243.77	2,533.02	9,710.75	79.31
+ GST 7.00/7.00% (S\$)	857.06	177.31	679.75	79.31
Nett Amount (S\$)	13,100.83	2,710.33	10,390.50	79.31

INSPECTION

07/01/2021 Date of Assignment:

Date Inspected: 05/01/2021 Inspected At: Trans-cab Auto Services Pte Ltd (Ang

Mo Kio)

2, Ang Mo Kio Street 63 Singapore 569111

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 4

Different 1 cents -Finalise confirm amount: \$2,533.03

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference				
Part Source:	: MRM-SG	Version: 1.0 (Last Synchronised: 15 Jan 2021)		
Parts:	144	TOYOTA PRIUS 1.5 (A) (Catalogue:Merimen Singapore 1.0)		
Labour:	Repairer's	(Price-denominated Standard List)		
Print Code:	(Unsubmitted, no print-code for SHC5020Z)			
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page			
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.				

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*COVER,REAR BUMPER	Repair	485.60 FL	-	*- FL
2	1		*GUARD,REAR BUMPER,CENTER	Serviceable	374.50 FL	-	*- FL
3	1		*SEAL,REAR BUMPER SIDE,RH	Serviceable	118.30 FL	-	*- FL
1	1		*RETAINER,REAR BUMPER SIDE,RH	Serviceable	132.60 FL	=	*- FL
5	1		*LENS & BODY,REAR COMBINATION LAMP,RH	Serviceable	339.60 FL	-	*- FL
6	1		*LENS & BODY,REAR COMBINATION LAMP,NO 2 RH	Serviceable	261.00 FL	-	*- Fl
7	1		*REFLECTOR ASSY,REFLEX,RH	Serviceable	39.00 FL	-	*- FL
3	1		*MOULDING ASSY,BODY ROCKER PANEL RH	- Repair	594.80 FL	-	*- Fl
9	1		*PANEL SUB-ASSY,QUARTER,RH	Repair	871.50 FL	-	*- Fl
0	1		*LINER,REAR WHEEL HOUSE,RH	Serviceable	139.80 FL	-	*- Fl
1	1		*PANEL SUB-ASSY,REAR DOOR,RH	Bent	1,294.90 FL	-	*1,294.90 Fl
12	1		*REGULATOR SUB-ASSY,REAR DOOR WINDOW,RH	Serviceable	206.70 FL	-	*- Fl
3	1		*TAPE,BLACK OUT,NO 1 REAR RH	Necessary	21.90 FL	-	*21.90 FI
4	1		*TAPE,BLACK OUT,NO 2 REAR RH	Necessary	34.90 FL	-	*34.90 FI
5	1		*TAPE,BLACK OUT,NO 3 REAR RH	Necessary	15.40 FL	-	*15.40 FI
6	1		*REAR BUMPER SIDE CLIP	Not Necessary	60.00 FS	-	*- F\$
17	1		*REAR FENDER LINER CLIP	Not Necessary	65.00 FS	-	*- F
18	1		*TYRE	Serviceable	300.00 FS	-	*- F\$
9	1		*RIM	Serviceable	1,879.40 FS	-	*- F\$
20	1		*RIM COVER	Dented	211.50 FS	-	*177.70 F
21	1		*TAIL LAMP CLIP	Not Necessary	70.00 FS	-	*-F\$
22	1		*SET PARKING AID	Serviceable	700.00 FS	-	*- F\$
23	1		*SET REAR BUMPER CLIP	Not Necessary	85.00 FS	-	*-F\$
24	1		*REAR BUMPER RETAINER CLIP	Not Necessary	75.00 FS	-	*- F\$
=Fra	nchise	part. S=	SpcNett. L=ListItemDisc.		P		
				Sub Total (S\$)	•	1,544.80	
			- List Item Discount on L Items 25.	.00/25.00% (S\$)	1,232.63	341.78	
				Γotal Parts (S\$)	7 143 77		1,203.02

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	30.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00
3	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	1,600.00	400.00
4	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT TO FACILITATE BODYWORK REPAIR	New	380.00	0.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,600.00	880.00
6	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
7	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	0.00
8	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
10	TO REMOVE AND REFIT OF REAR FENDER FITTINGS ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
	Gross Labou	r Cost (S\$)	5,100.00	1,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >