

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21000274/T1GA3Q2
Date: 16/11/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100501996
Claimant Vehicle No :	SLF3232D	Insured Vehicle No :	SJQ1368A
Date of Loss:	31/12/2020	Nature of Claim:	TP
		Claim No:	4121889308SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF3232D	Engine No:	2ARJ253230
Make & Model:	TOYOTA VELLFIRE, 2.5 Z G CVT (A)	Chassis No:	AGH300237653
Reg. Date:	23/01/2020 (Man. Year: 2019)	Odometer:	15166 km
Colour:	Black		
Engine Capacity:	2493 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Toyo 7 mm	Rear Left Side:	Toyo 7 mm
Front Right Side:	Toyo 7 mm	Rear Right Side:	Toyo 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,566.50	9,413.83	12,152.67	56.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,200.00	1,320.00	9,880.00	88.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	32,766.50	10,733.83	22,032.67	67.24
Approved Total (Overridden) (S\$)		8,600.00		

(S\$)	32,766.50	8,600.00	24,166.50	73.75
+ GST 7.00/7.00% (S\$)	2,293.66	602.00	1,691.66	73.75
Nett Amount (S\$)	35,060.16	9,202.00	25,858.16	73.75
+ Car Rental (6.0 x S\$120.00/day + 7.00% GST) (S\$)		770.40		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		9,979.85		
Global Sum Settlement (S\$)		9,950.00		

INSPECTION

Date of Assignment: 05/01/2021

Date Inspected: 06/01/2021

Estimated Period of Repair: 4.0 days

Inspected At:

AP Automotive Services Pte Ltd (HQ)
 Blk 9006 Tampines Street 93, #01-202
 Singapore 528840

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Not Necessary	572.50 FL	*- FL
2	1		*BONNET CHROME	Not Necessary	462.85 FL	*- FL
3	1		*BONNET LOCK	Not Necessary	176.50 FL	*- FL
4	2		*BONNET HINGE L+R	Not Necessary	131.90 FL	*- FL
5	1		*HEAD LAMP L+R	O/S Cracked	11,691.50 FL	*5,845.75 FL
6	2		*HEAD LAMP GARNISH L+R	Not Necessary	206.24 FL	*- FL
7	2		*HEAD LAMP LOWER BRACKET L+R	Cracked	550.40 FL	*450.00 FL
8	1		*FRONT GRILLE ASSY	Cracked	1,241.90 FL	*1,241.90 FL
9	1		*FRONT GRILLE LOGO -TOYOTA	Cracked	1,091.65 FL	*891.65 FL
10	1		*FRONT GRILLE LOGO RADAR	Not Necessary	2,125.76 FL	*- FL
11	1		*FRONT FENDER COWLING RH	Not Necessary	221.15 FL	*- FL
12	1		*FRONT BUMPER	Torn	1,468.45 FL	*1,468.45 FL
13	1		*FRONT BUMPER GRILLE	Deformed	213.60 FL	*213.60 FL
14	2		*FRONT BUMPER FOGLAMP L+R	Not Necessary	1,043.40 FL	*- FL
15	1		*FRONT BUMPER FOGLAMP GARNISH WITH CHROME L+R	N/S Not Necessary /O/S Deformed	1,354.64 FL	*485.00 FL
16	1		*SET FRONT BUMPER SENSOR	N/S Cut / O/S Not Necessary	795.70 FL	*397.85 FL
17	2		*FRONT BUMPER RETAINER L+R	Not Necessary	135.40 FL	*- FL
18	1		*FRONT BUMPER REINFORCEMENT BAR	Not Necessary	352.89 FL	*- FL
19	1		*FRONT BUMPER SPONGE	Deformed	90.45 FL	*90.45 FL
20	1		*WIPER WASHER TANK	Not Necessary	142.65 FL	*- FL
21	1		*FRONT SUPPORT PANEL	Not Necessary	1,189.78 FL	*- FL
22	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	245.95 FL	*- FL
23	2		*AIRCON CONDENSOR AIRGUIDE L+R	Deformed (1 PCS ONLY)	179.24 FL	*89.62 FL
24	1		*BRACE PANEL	Bent	127.65 FL	*127.65 FL
25	1		*SET FRONT BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
26	1		*SET FRONT FENDER COWLING CLIPS	Not Necessary	200.00 FS	*- FS
27	1		*SET FRONT SUPPORT TOP GARNISH CLIPS	Not Necessary	100.00 FS	*- FS
28	1		*FRONT CAMERA	Not Necessary	900.00 FS	*- FS
29	1		*AIRCON CONDENSOR	Dented	1,209.85 FL	*1,209.85 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	28,322.00	12,541.77
- List Item Discount on L Items 25.00/25.00% (\$\$)	6,755.50	3,127.94
Total Parts (\$\$)	21,566.50	9,413.83

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SPRAY PAINT ON AFFECTED AREAS	New	2,700.00	400.00
2	PANEL BEATING ON AFFECTED AREAS	New	3,600.00	400.00
3	TO CHECK WIRING AND HEADLAMP FOCUS	New	150.00	30.00
4	TO CHECK WIRING AND FOG LAMP FUNCTION	New	150.00	30.00
5	TO RNR FRONT LOGO RADAR AND TEST FUNCTION	New	600.00	150.00
6	TO UNLOAD AND RNR UPHOLSTERY	New	1,200.00	0.00
7	TO CHECK WATER LEAK	New	150.00	0.00
8	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	New	1,200.00	180.00
9	TO PERFORM RUST PROOFING	New	600.00	0.00
10	TO RNR FRONT CAMERA AND TEST FUNCTION	New	600.00	30.00
11	TO RNR AIRCON CONDENSOR AND TOP UP GAS	New	250.00	100.00
Gross Labour Cost (S\$)			11,200.00	1,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >