

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21000275/T1GA3Q2**Date:** 14/12/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070107280
Claimant Vehicle No :	SKT233J	Insured Vehicle No :	SMT7643P
Date of Loss:	04/01/2021	Nature of Claim:	TP
		Claim No:	8930945474SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKT233J		
Make & Model:	VOLKSWAGEN NEW GOLF, 1.4 TSI 5K14Q5 (A)	Engine No:	CAV094696
Reg. Date:	08/10/2009 (Man. Year: 2009)	Chassis No:	WVWZZZ1KZAW012829
Colour:	Grey	Odometer:	183231 km
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,286.18	4,164.16	19,122.02	82.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,950.00	2,060.00	3,890.00	65.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,236.18	6,224.16	23,012.02	78.71
Approved Total (Overridden) (S\$)		5,000.00		
(S\$)	29,236.18	5,000.00	24,236.18	82.90
+ GST 7.00/7.00% (S\$)	2,046.53	350.00	1,696.53	82.90
Nett Amount (S\$)	31,282.71	5,350.00	25,932.71	82.90
+ Car Rental (9.0 x S\$100.00/day + 7.00% GST) (S\$)		963.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,320.45		
Global Sum Settlement (S\$)		6,300.00		

INSPECTION

Date of Assignment:	05/01/2021		
Date Inspected:	06/01/2021	Inspected At:	AP Automotive Services Pte Ltd (HQ) Blk 9006 Tampines Street 93, #01-202 Singapore 528840
Estimated Period of Repair:	6.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	1,840.91 FL	*- FL
2	1		*TAILGATE WINDSCREEN MOULDING	Not Necessary	189.45 FL	*- FL
3	1		*TAILGATE LOGO OPENER	Not Necessary	685.20 FL	*- FL
4	1		*TAILGATE LAMP LH	Not Necessary	497.60 FL	*- FL
5	1		*TAILGATE LOCK	Not Necessary	425.55 FL	*- FL
6	1		*TAILGATE LOCK CATCH	Not Necessary	95.21 FL	*- FL
7	1		*TAILGATE TRIM	Not Necessary	521.56 FL	*- FL
8	2		*SET TAILGATE HINGE	Not Necessary	190.40 FL	*- FL
9	2		*SET TAILGATE DAMPER	Not Necessary	275.60 FL	*- FL
10	1		*TAILGATE WEATHERSTRIP	Torn	339.48 FL	*275.00 FL
11	1		*TAIL LAMP LH	Cracked	543.82 FL	*543.82 FL
12	1		*TAIL LAMP LOWER BRACKET LH	Cracked	89.33 FL	*89.33 FL
13	1		*TAIL LAMP PANEL LH	Not Necessary	381.50 FL	*- FL
14	1		*REAR BUMPER	Deformed	1,510.75 FL	*1,100.00 FL
15	2		*REAR BUMPER NUMBER PLATE LAMP L+R	Not Necessary	130.80 FL	*- FL
16	1		*REAR BUMPER REFLECTOR LH	Cut	102.30 FL	*102.30 FL
17	1		*REAR BUMPER LOWER	Torn	410.32 FL	*410.32 FL
18	1		*REAR BUMPER RETAINER LH	Cracked	124.25 FL	*124.25 FL
19	1		*REAR BUMPER CENTER BRACKET	Cracked	256.80 FL	*256.80 FL
20	1		*REAR BUMPER REINFORCEMENT BAR	Not Necessary	697.75 FL	*- FL
21	1		*REAR BUMPER BRACKET LH	Cracked	86.90 FL	*86.90 FL
22	1		*REAR BUMPER SPONGE	Not Necessary	123.45 FL	*- FL
23	1		*REAR FENDER LH	Repair	375.95 FL	*- FL
24	1		*REAR FENDER AIR VENT LH	Cracked	90.10 FL	*90.10 FL
25	1		*REAR FENDER INNER TRIM BOTTOM LH	Not Necessary	429.35 FL	*- FL
26	1		*REAR FENDER COWLING LH	Torn	212.47 FL	*212.47 FL
27	1		*END PANEL	Bent	859.65 FL	*780.00 FL
28	1		*END PANEL TOP GARNISH	Not Necessary	345.78 FL	*- FL
29	1		*REAR SMART LOCK ANTENNA	Not Necessary	279.50 FL	*- FL
30	1		*REAR SMART LOCK ANTENNA WIRE HARNESS	Not Necessary	638.20 FL	*- FL
31	1		*SPAREWHEEL PANEL	Not Necessary	1,234.80 FL	*- FL
32	1		*SPAREWHEEL PANEL TOP BOARD	Not Necessary	501.62 FL	*- FL
33	2		*SET EXHAUST MOUNTING	Not Necessary	144.40 FL	*- FL
34	1		*EXHAUST HEAT SHIELD	Not Necessary	231.67 FL	*- FL
35	1		*TAILGATE WINDSCREEN SEALANT	Not Necessary	120.00 FS	*- FS
36	1		*SET TAILGATE INNER TRIM CLIPS	Not Necessary	100.00 FS	*- FS
37	1		*SET TAIL LAMP CLIPS	Necessary	40.00 FS	*10.00 FS
38	1		*TAIL LAMP PANEL SEALANT	Not Necessary	100.00 FS	*- FS
39	1		*SET REAR BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
40	1		*SET REAR BUMPER REVERSE SENSOR	Not Working	300.00 FS	*200.00 FS
41	1		*REAR NUMBER PLATE	Not Necessary	100.00 FS	*- FS
42	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	100.00 FS	*- FS
43	1		*SET REAR FENDER COWLING CLIPS	Necessary	100.00 FS	*20.00 FS
44	1		*END PANEL SEALANT	Necessary	250.00 FS	*40.00 FS
45	1		*SET END PANEL TOP GARNISH CLIPS	Not Necessary	100.00 FS	*- FS
46	1		*SPAREWHEEL PANEL SEALANT	Not Necessary	300.00 FS	*- FS
47	1		*EXHAUST PIPE	Not Necessary	8,000.00 FS	*- FS
48	1		*CHROME TIP	Cut	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	24,772.42	4,571.29
- List Item Discount on L Items 10.00/10.00% (\$)	1,486.24	407.13
Total Parts (\$)	23,286.18	4,164.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINT ON AFFECTED AREAS	New	1,400.00	800.00
2	PANEL BEATING ON AFFECTED AREAS	New	1,500.00	900.00
3	TO RNR REAR EXHAUST	New	250.00	60.00
4	TO CHECK WIRING AND TAIL LAMP FUNCTION	New	150.00	30.00
5	TO CHECK WIRING AND TAILGATE LAMP FUNCTION	New	150.00	0.00
6	TO UNLOAD AND UPHOLSTERY REAR BOOT	New	400.00	60.00
7	TO CHECK WATER LEAK	New	150.00	0.00
8	TO RNR FUEL TANK	New	250.00	0.00
9	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	New	800.00	150.00
10	TO RNR REAR TAILGATE MECHANISM	New	350.00	0.00
11	TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION	New	150.00	30.00
12	TO PERFORM RUST PROOFING	New	400.00	30.00
Gross Labour Cost (\$)			5,950.00	2,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >