

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21000276/DBA3Q2
Date: 01/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070165968
Claimant Vehicle No :	SMS1258M	Insured Vehicle No :	SMR3926K
Date of Loss:	03/01/2021	Nature of Claim:	TP
		Claim No:	2205839341SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS1258M		
Make & Model:	HYUNDAI AD AVANTE, 1.6 GLS S (A)	Engine No:	G4FGKU017723
Reg. Date:	12/02/2020 (Man. Year: 2019)	Chassis No:	KMHD841CMLU031564
Colour:	Blue	Odometer:	63461 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Kumho 5 mm	Rear Left Side:	Kumho 5 mm
Front Right Side:	Kumho 5 mm	Rear Right Side:	Kumho 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	44,565.49	5,961.32	38,604.17	86.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,200.00	2,640.00	6,560.00	71.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	53,765.49	8,601.32	45,164.17	84.00
Approved Total (Overridden) (S\$)		6,700.00		

(S\$)	53,765.49	6,700.00	47,065.49	87.54
+ GST 7.00/7.00% (S\$)	3,763.58	469.00	3,294.58	87.54
Nett Amount (S\$)	57,529.07	7,169.00	50,360.07	87.54
Global Sum Settlement (S\$)	0.00			

INSPECTION

Date of Assignment: 05/01/2021

Date Inspected: 06/01/2021 Inspected At:

JWG International Pte Ltd (HQ)
Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK AutoPoint
Singapore 568047

Estimated Period of Repair: 7.0 days

Adjuster: BRYAN TANI**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Not Necessary	2,071.00 FL	*- FL
2	1		*HEAD LAMP RH	Not Necessary	1,857.00 FL	*- FL
3	1		*HEAD LAMP LOWER BRACKET RH	Not Necessary	54.00 FL	*- FL
4	1		*HEAD LAMP PANEL RH	Not Necessary	1,050.00 FL	*- FL
5	1		*FRONT FENDER RH	Dented	1,328.00 FL	*985.60 FL
6	1		*FRONT FENDER INNER SHIELD RH	Serviceable	156.00 FL	*- FL
7	1		*FRONT RIM RH	Cut	1,072.35 FS	*500.00 FS
8	1		*FRONT WHEEL BEARING & HUB ASSY RH	Damaged	563.00 FL	*174.90 FL
9	1		*FRONT ABSORBER RH	Distorted	473.00 FL	*389.65 FL
10	1		*FRONT KNUCKLE ARM RH	Distorted	764.00 FL	*363.60 FL
11	1		*FRONT LOWER ARM RH	Distorted	497.00 FL	*345.20 FL
12	1		*FRONT STABILIZER BAR	Not Necessary	692.40 FL	*- FL
13	1		*FRONT STABILIZER LINK RH	Not Necessary	319.80 FL	*- FL
14	1		*STEERING RACK & PINION ASSY	Not Necessary	2,980.20 FL	*- FL
15	1		*DRIVE SHAFT	Not Necessary	3,209.40 FL	*- FL
16	1		*FRONT BUMPER	Repair	675.00 FL	*- FL
17	1		*FRONT BUMPER SIDE RETAINER RH	Serviceable	44.00 FL	*- FL
18	1		*SIDE MIRROR ASSY RH	Not Necessary	739.00 FL	*- FL
19	1		*FRONT DASHBOARD ASSY	Not Necessary	1,574.00 FL	*- FL
20	1		*FRONT DOOR RH	Dented	2,005.00 FL	*1,678.00 FL
21	1		*FRONT DOOR INNER WEATHER STRIP RH	Serviceable	323.00 FL	*- FL
22	1		*FRONT DOOR OUTER WEATHER STRIP RH	Serviceable	307.00 FL	*- FL
23	1		*FRONT DOOR LOCK RH	Not Necessary	292.00 FL	*- FL
24	1		*FRONT DOOR WINDOW RH	Not Necessary	516.00 FL	*- FL
25	1		*FRONT DOOR WINDOW MOULDING RH	Serviceable	231.00 FL	*- FL
26	1		*FRONT DOOR CHROME MOULDING RH	Serviceable	295.00 FL	*- FL
27	1		*FRONT DOOR BLACK PLASTIC MOULDING RH	Necessary	131.00 FL	*131.00 FL
28	1		*FRONT DOOR HANDLE RH	Not Necessary	289.10 FL	*- FL
29	1		*FRONT DOOR INNER TRIM RH	Not Necessary	856.90 FL	*- FL
30	1		*FRONT DOOR WINDOW MOTOR RH	Not Necessary	497.80 FL	*- FL
31	1		*FRONT DOOR WINDOW REGULATOR RH	Not Necessary	450.40 FL	*- FL
32	2		*FRONT DOOR HINGE RH	Repair	162.20 FL	*- FL
33	1		*FRONT DOOR STOPPER	Not Necessary	10.00 FL	*- FL
34	1		*REAR DOOR RH	Dented	1,978.30 FL	*1,476.80 FL
35	1		*REAR DOOR INNER WEATHERSTRIP RH	Serviceable	250.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*REAR DOOR OUTER WEATHERSTRIP RH	Serviceable	285.00 FL	*- FL
37	1		*REAR DOOR LOCK RH	Not Necessary	291.50 FL	*- FL
38	1		*REAR DOOR WINDOW RH	Not Necessary	487.90 FL	*- FL
39	1		*REAR DOOR WINDOW MOULDING RH	Not Necessary	231.00 FL	*- FL
40	1		*REAR DOOR CHROME MOULDING RH	Not Necessary	295.00 FL	*- FL
41	1		*REAR DOOR BLACK PLASTIC MOULDING RH	Not Necessary	131.00 FL	*- FL
42	1		*REAR DOOR HANDLE RH	Not Necessary	167.80 FL	*- FL
43	1		*REAR DOOR INNER TRIM RH	Not Necessary	713.60 FL	*- FL
44	1		*REAR DOOR WINDOW MOTOR RH	Not Necessary	460.50 FL	*- FL
45	1		*REAR DOOR WINDOW REGULATOR RH	Not Necessary	483.40 FL	*- FL
46	2		*REAR DOOR HINGE RH	Not Necessary	162.20 FL	*- FL
47	1		*SET REAR DOOR STOPPER	Not Necessary	10.00 FL	*- FL
48	1		*REAR FENDER RH	Repair	3,984.00 FL	*- FL
49	1		*REAR FENDER INNER SHIELD RH	Not Necessary	432.00 FL	*- FL
50	1		*REAR RIM RH	Cut	1,072.35 FS	*500.00 FS
51	1		*REAR WHEEL BEARING & HUB ASSY RH	Damaged	554.00 FL	*321.00 FL
52	1		*REAR ABSORBER RH	Distorted	439.20 FL	*335.90 FL
53	1		*REAR AXLE	Not Necessary	1,788.70 FL	*- FL
54	1		*TAIL LAMP RH	Not Necessary	1,152.10 FL	*- FL
55	1		*TAIL LAMP LOWER BRACKET RH	Not Necessary	201.30 FL	*- FL
56	1		*REAR WINDSCREEN MOULDING	Not Necessary	174.70 FL	*- FL
57	1		*BOOTLID	Not Necessary	1,982.40 FL	*- FL
58	1		*BOOTLID LAMP RH	Not Necessary	764.20 FL	*- FL
59	1		*BOOTLID HYUNDAI LOGO	Not Necessary	196.20 FL	*- FL
60	1		*BOOTLID AVANTE EMBLEM	Not Necessary	187.20 FL	*- FL
61	2		*BOOTLID HINGE LH/RH	Not Necessary	388.60 FL	*- FL
62	1		*REAR BUMPER	Repair	659.40 FL	*- FL
63	2		*REAR BUMPER SIDE RETAINER LH/RH	Not Necessary	112.20 FL	*- FL
64	1		*REAR BUMPER BRACKET	Not Necessary	178.60 FL	*- FL
65	1		*REAR BUMPER CENTER GARNISH	Not Necessary	453.50 FL	*- FL
66	1		*REAR END PANEL	Not Necessary	554.60 FL	*- FL
67	1		*REAR END PANEL TOP GARNISH	Not Necessary	159.80 FL	*- FL
68	2		*TYRE	Serviceable	600.00 FS	*- FS
69	1		*FRONT FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS
70	1		*FRONT BUMPER CLIPS	Serviceable	50.00 FS	*- FS
71	1		*HEAD LAMP CLIPS	Not Necessary	50.00 FS	*- FS
72	1		*FRONT DOOR INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
73	1		*REAR DOOR INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
74	1		*REAR FENDER SEALANT	Not Necessary	80.00 FS	*- FS
75	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
76	1		*REAR WINDSCREEN DAMPING SEAL	Not Necessary	30.00 FS	*- FS
77	1		*REAR BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
78	1		*REAR FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS
79	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
80	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	49,137.80	7,201.65
- List Item Discount on L Items 10.00/20.00% (\$)	4,572.31	1,240.33
Total Parts (\$)	44,565.49	5,961.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	600.00	120.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	3,000.00	800.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	3,000.00	1,200.00
4	TO TUFF COAT DAMAGED AREAS	New	400.00	40.00
5	TO RNR FRONT UNDERCARRIAGE SYSTEM TO FACILITATE REPAIRS	New	400.00	150.00
6	TO RNR REAR UNDERCARRIAGE SYSTEM TO FACILITATE REPAIRS	New	400.00	150.00
7	TO RNR FRONT DOOR MECHANISM TO FACILITATE REPAIRS	New	200.00	60.00
8	TO RNR REAR DOOR MECHANISM TO FACILITATE REPAIRS	New	200.00	60.00
9	TO RNR REAR WINDSCREEN TO FACILITATE REPAIRS	New	300.00	0.00
10	TO RNR REVERSE SENSOR TO FACILITATE REPAIRS	New	100.00	0.00
11	TO CONDUCT 4 WHEEL ALIGNMENT ALIGNMENT	New	100.00	60.00
12	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	0.00
13	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
Gross Labour Cost (S\$)			9,200.00	2,640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >