

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21000277/KGA3Q2

Date: 15/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SMM7920B **Insured Vehicle No :** SMQ9491M

Date of Loss: 31/12/2020 **Nature of Claim:** TP **Claim No:** 4082995449SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM7920B	Engine No:	LEB7110972
Make & Model:	HONDA SHUTTLE HYBRID, 1.5 (A)	Chassis No:	GP72008772
Reg. Date:	15/07/2019 (Man. Year: 2019)	Odometer:	122916 km
Colour:	Metallic Pearl White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	SUNWIDE 8 mm	Rear Left Side:	KAPSEN 3 mm
Front Right Side:	SUNWIDE 8 mm	Rear Right Side:	KAPSEN 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,594.08	1,449.04	1,145.04	44.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,850.00	895.00	955.00	51.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,444.08	2,344.04	2,100.04	47.25
+ GST 7.00/7.00% (S\$)	311.09	164.08	147.01	47.26
Nett Amount (S\$)	4,755.17	2,508.12	2,247.05	47.25
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,010.12		

INSPECTION

Date of Assignment: 06/01/2021

Date Inspected: 06/01/2021 Inspected At: Optima Werkz Pte Ltd (HQ)
6 Kung Chong Road
Singapore 159143

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,193.00 FL	*1,193.00 FL
2	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	75.80 FL	*75.80 FL
3	1		*REAR TAILGATE SHUTTLE EMBLEM	Necessary	65.60 FL	*65.60 FL
4	1		*REAR TAILGATE LOGO EMBLEM	Necessary	58.20 FL	*58.20 FL
5	1		*REAR WINDSCREEN MOULDING	Necessary	118.70 FL	*118.70 FL
6	1		*REAR END PANEL UPPER COVERING	Serviceable	155.50 FL	*- FL
7	1		*REAR BUMPER	Repair	950.80 FL	*- FL
8	1		*REAR END PANEL (NPA)	Repair	0.00 FL	*- FL
9	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
10	1		*REAR TAILGATE INNER TRIME CLIPS	Not Necessary	40.00 FS	*- FS
11	1		*REAR END PANEL UPPER COVERING CLIPS	Not Necessary	30.00 FS	*- FS
12	1		*REAR BUMPER REVERSE SENSOR	Shorted	300.00 FS	*200.00 FS
13	1		*REAR BUMPER CLIPS	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,117.60	1,751.30
- List Item Discount on L Items 20.00/20.00% (\$\$)	523.52	302.26
Total Parts (\$\$)	2,594.08	1,449.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,REPLACE REFIX REPAIR READJUST REAR ACCIDENT AREAS & ETC	New	700.00	300.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE ,REAR END PANEL ,REAR BMPER & ETC	New	700.00	400.00
3	LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS ,REAR WINDSCREEN MOULDING ,REAR WINDSCREEN SEALANT & ETC .TO EFFECT REPLACE OF REAR TAILGATE	New	150.00	120.00
4	LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC BACK TO ORIGINAL OPERTAIONS	New	120.00	60.00
5	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC	New	100.00	0.00
6	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	New	80.00	15.00
Gross Labour Cost (\$\$)			1,850.00	895.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >