

Vehicle No. SMP8020B HYUNDAI AVANTE

KMH D841CML4964093

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE (\$)	SURVEYOR ADJUSTMENT
PARTS (LIST ITEMS)				
1	REAR BOOTLID <i>Distorted</i>		1188.70	✓
1	REAR BOOTLID LOGO <i>new</i>		82.00	✓
2	REAR BOOTLID LAMP LH & RH @\$355.00 <i>RH out</i>		710.00	355
1	REAR BOOTLID LOCK <i>new</i>		210.00	✓
1	REAR BOOTLID INNER TRIM BOARD <i>distorted</i>		290.00	✓
1	REAR BOOTLID WEATHERTRIP <i>new</i>		125.80	✓
1	REAR BOOTLID HINGE LH & RH @\$189.60 <i>Bent</i>		379.20	✓
1	REAR BOOTLID " AVANTE " EMBLEM <i>new</i>		76.00	✓
1	REAR BOOTLID " S " EMBLEM		71.00	✓
1	REAR BOOTLID INNER COVER <i>Repaired</i>			x.
1	REAR BUMPER <i>Distorted</i>		953.70	498.
1	REAR BUMPER LOWER <i>Distorted</i>		341.00	✓
2	REAR BUMPER SIDE RETAINER LH & RH @\$79.00 <i>new</i>		158.00	70.
2	REAR BUMPER BRACKET LH & RH @\$82.60 <i>Distorted</i>		165.20	100.
2	REAR BUMPER REFLECTOR LH & RH @\$256.80 <i>could</i>		513.60	✓
1	REAR BUMPER REINFORCEMENT <i>distorted</i>		441.10	394.
1	REAR BUMPER REINFORCEMENT BRACKET <i>Distorted</i>		176.90	✓
1	REAR BUMPER UNDER COVER <i>torn</i>		81.00	✓
1	REAR BUMPER INNER KEYLESS SENSOR <i>could</i>		228.00	196.
1	REAR BUMPER INNER SPONGE <i>new</i>		162.80	x
1	REAR BUMPER MUD FLAP LH & RH @\$75.20 <i>cut</i>		150.40	✓
2	REAR TAILLAMP LH & RH @\$729.60 <i>could</i>		1459.20	✓
2	REAR TAILLAMP PANEL LH & RH @\$189 <i>Bent</i>		378	✓
1	REAR END PANEL <i>Distorted</i>		485.90	✓
1	REAR END PANEL TOP GARNISH <i>distorted</i>		203.10	189.
1	REAR FENDER INNER TRIM BOARD LH & RH @\$549.20 <i>torn</i>		1098.40	577.
2	REAR FENDER LH & RH @\$771.50 <i>new</i>		1543.00	x.
1	REAR SPARE TYRE PANEL <i>Distorted</i>		982.00	✓
1	REAR SPARE TYRE PANEL TOP COVER <i>distorted</i>		280.00	✓
1	REAR SPARE TYRE PANEL SEALANT <i>new</i>		450.00	250 (SN)
1	REAR EXHUAUST SILENCER <i>Bent</i>		1118.60	688.
1	REAR EXHUAUST SILENCER MOUNTING <i>newer</i>		98.00	x
1	REAR EXHUAUST SILENCER HEAT SHIELD <i>crushed</i>		284.00	187.
			14166.00	
			2833.20	20%
			11332.80	
SPECIAL NETT ITEMS				
1	REVERSE SENSOR <i>new</i>		280.00	200
1	REVERSE CAMERA <i>new</i>		350.00	200
1 SET	REAR BUMPER CLIPS <i>new</i>		100.00	30
1 SET	REAR CAR PLATE WITH HOLDER <i>Bent</i>		70.00	50
1	REAR END PANEL SEALANT <i>new</i>		100.00	60
1 SET	REAR END PANEL TOP GARNISH CLIPS <i>new</i>		80.00	20
Total Parts			12312.80	



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel:6702 4282 Fax:6702 4202

Page No. 2

Vehicle No. SMP8020B HYUNDAI AVANTE

S/N	DESCRIPTION	REPAIRER'S ESTIMATE	OUR ASSESSMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs and replace damaged parts	1800.00	1500.
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1600.00	1500
3	To remove and refix wiring at damaged areas	100.00	32
4	To perform anti rust treatment on affected areas	200.00	120.
5	To remove and replace reverse sensors and check for proper functions	120.00	60.
6	To remove and refix rear boot mechanism	150.00	80
7	To remove and replace exhaust silencer	220.00	80
8	To tuff coat	100.00	✓
9	To remove and refix rear car seat and upholstery.	250.00	✓
Labour Total :		4440.00	3720
TOTAL (PARTS & LABOUR):		16752.80	

To remove and refix rear camera ~~100~~ 50.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

10.5K

Adrian Lim
H/S 07/01/21

10 Days.

total 132886

L/S: 10.5K