

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

**Our File No:** CC4/AIG21000279/KGA3Q2  
**Date:** 08/07/2021

**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100460206
<b>Claimant Vehicle No :</b>	SKH7062C	<b>Insured Vehicle No :</b>	SJM8815B
Date of Loss:	05/01/2021	Nature of Claim:	TP
		Claim No:	6822573712SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SKH7062C</b>	Engine No:	CTH018736
Make & Model:	VOLKSWAGEN TIGUAN, 1.4 TSI (A)	Chassis No:	WVGZZZ1TZDW040949
Reg. Date:	07/01/2013 (Man. Year: 2012)	Odometer:	125182 km
Colour:	Metallic Brown		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Continental 8 mm	Rear Left Side:	Continental 8 mm
Front Right Side:	Continental 8 mm	Rear Right Side:	Continental 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,839.85	2,631.55	1,208.30	31.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,360.00	880.00	480.00	35.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,199.85</b>	<b>3,511.55</b>	<b>1,688.30</b>	<b>32.47</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,800.00</b>		

(S\$)	5,199.85	2,800.00	2,399.85	46.15
<b>+ GST 7.00/7.00% (S\$)</b>	363.99	196.00	167.99	46.15
<b>Nett Amount (S\$)</b>	<b>5,563.84</b>	<b>2,996.00</b>	<b>2,567.84</b>	<b>46.15</b>
<b>+ Loss of Use (5.0 x S\$50.00/day) (S\$)</b>		250.00		
<b>(S\$)</b>		3,246.00		
<b>Liabe Amount (50.00%) (S\$)</b>		<b>1,623.00</b>		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>1,625.00</b>		

INSPECTION

Date of Assignment: 06/01/2021

Date Inspected: 07/01/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Ah Lim Motor Company (AMK)  
 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint  
 Singapore 568047

**Adjuster:** KENNETH KONG**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RH	Repair	608.45 FL	*- FL
2	1		*FRONT FENDER COWLING RH	Serviceable	170.15 FL	*- FL
3	1		*FRONT FENDER COWLING CLIPS	Not Necessary	2.50 FL	*- FL
4	1		*FRONT BUMPER	Buckled / Cut	1,056.95 FL	*1,056.95 FL
5	1		*FRONT BUMPER SIDE RETAINER RH	Serviceable	69.85 FL	*- FL
6	12		*FRONT BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
7	1		*HEADLAMP RH WITH LOWER BEAM	Cut	627.05 FL	*627.05 FL
8	1		*FRONT WHEEL BEARING RH WITH HUB	Serviceable	491.60 FL	*- FL
9	1		*SPORT RIM RHF	Dented	1,209.95 FL	*1,209.95 FL
10	1		*TYRE RHF (NPA)	Serviceable	0.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>4,266.50</b>	<b>2,923.95</b>
<b>- List Item Discount on L Items 10.00/10.00% (S\$)</b>	426.65	292.40
<b>Total Parts (S\$)</b>	<b>3,839.85</b>	<b>2,631.55</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING ,WIRE SOCKETS AND ETC .TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS ,TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	20.00
2	TO CHECK AND READJUST WHEEL ALIGNMENT	New	80.00	60.00
3	TO DISMANTLE ,REPLACE AND REINSTALL UNDERCARRIAGE	New	60.00	0.00
4	LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT	New	120.00	0.00
5	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	60.00	0.00
6	TO DISMANTLE ALL DAMAGED PARTS .TO KNOCK & REPAIR FRONT INNER PANELS AND AFFECTED AREAS ,TO REFIT LISTED PARTS BACK SAME	New	500.00	400.00
7	TO SPRAY FRONT FENDER RH ,FRONT BUMPER	New	500.00	400.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,360.00</b>	<b>880.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >