



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDV 8850Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	CRACKED / DENTED	1,400.00	1,255.00
1	BUMPER ENFORCEMENT	TO REPAIR SEE LABOUR	300.00	-
1	BUMPER SPONGE	SERVICEABLE	200.00	-
1	BUMPER LOWER GRILLE	DENTED	110.00	110.00
1	BUMPER FOGLAMP	MTG CRACKED	300.00	300.00
1	FOGLAMP COVER	DENTED	50.00	50.00
2	LOWER CHROME R N L @\$110.00	NECESSARY	220.00	220.00
1	TOW COVER	SERVICEABLE	80.00	-
1	ENGINE LOWER COVER	CRACKED	300.00	300.00
1	CLIP	NECESSARY	42.00	42.00
1	INTER COOLANT LOWER BRACKET, RH	BENT / DISTORTED	130.00	130.00
1	HORN, RH	CRACKED	290.00	290.00
	LESS 10% DISCOUNT		-342.20	-269.70
			3,079.80	2,427.30
	<u>LABOUR</u>			
	TO REMOVE / REINSTALL RADIATOR, INTER COOLER.		180.00	100.00
	TO REMOVE DAMAGED PARTS AND ATTACHMENTS. REPAIR ALL DENTED AREAS. REPLACE / ALIGN ALL PARTS INTO POSITION. INCLUSIVE OF THE REPAIR OF BUMPER ENFORCEMENT.		750.00	300.00
	TO SPRAY PAINT.		400.00	250.00
			1,330.00	650.00
	GRAND TOTAL		4,409.80	3,077.30
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,450.00

Report Ref No. CS/TP21000283/Kvd3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.