

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG21000287/UBA3Q2

**Date:** 30/04/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800150197

**Claimant**  
**Vehicle No :** SKE3158C **Insured Vehicle No :** SFY2046C

Date of Loss: 01/01/2021 Nature of Claim: TP Claim No: 0535244950SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SKE3158C</b>	Engine No:	1NZ6119134
Make & Model:	TOYOTA PRIUS C CVT, 1.5 (A)	Chassis No:	JTDKD3B3801001512
Reg. Date:	24/02/2012 (Man. Year: 2012)	Odometer:	178724 km
Colour:	Blue		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,640.82	483.75	2,157.07	81.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,630.00	1,020.00	610.00	37.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,270.82</b>	<b>1,503.75</b>	<b>2,767.07</b>	<b>64.79</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,200.00</b>		
<b>(S\$)</b>	4,270.82	1,200.00	3,070.82	71.90
<b>+ GST 7.00/7.00% (S\$)</b>	298.96	84.00	214.96	71.90
<b>Nett Amount (S\$)</b>	<b>4,569.78</b>	<b>1,284.00</b>	<b>3,285.78</b>	<b>71.90</b>
<b>+ Car Rental (2.5 x S\$100.00/day + 7.00% GST) (S\$)</b>		267.50		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>1,553.50</b>		

### INSPECTION

Date of Assignment: 07/01/2021

Date Inspected: 07/01/2021 Inspected At:

Tan Lim Motor Pte Ltd (Defu)  
1 Defu Lane 6  
Singapore 539365

Estimated Period of Repair: 3.0 days

---

**Adjuster:** MARCUS CHUA**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Deformed	645.00 FL	*645.00 FL
2	2		*REAR BUMPER SIDE RETAINER	Not Necessary	132.00 FL	*- FL
3	1		*REAR BUMPER REINFORCEMENT	Repair	396.00 FL	*- FL
4	2		*REAR BUMPER REINFORCEMENT BRACKET	Serviceable	197.80 FL	*- FL
5	2		*TAILLAMP	Not Necessary	500.00 FL	*- FL
6	6		*TAILLAMP CLIPS	Not Necessary	25.80 FL	*- FL
7	1		*TAILGATE LID LOCK	Not Necessary	374.00 FL	*- FL
8	1		*TAILGATE LID TOYOTA EMBLEM BADGE	Not Necessary	39.60 FL	*- FL
9	1		*TAILGATE LID CENTRE LOGO BADGE	Not Necessary	47.90 FL	*- FL
10	1		*TAILGATE LID PRIUS C EMBLEM	Not Necessary	44.00 FL	*- FL
11	1		*TAILGATE LID HYUNDAI EMBLEM	Not Necessary	83.00 FL	*- FL
12	1		*TAILGATE LID WEATHERSTRIP	Not Necessary	242.00 FL	*- FL
13	1		*REAR END PANEL	Repair	580.00 FL	*- FL
14	1		*REAR END PANEL TOP GARNISH	Not Necessary	188.20 FL	*- FL
15	6		*TAILLAMP CLIP HOLDER	Not Necessary	25.80 FL	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>3,521.10</b>	<b>645.00</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	<b>880.28</b>	<b>161.25</b>
<b>Total Parts (\$\$)</b>	<b>2,640.82</b>	<b>483.75</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	50.00	20.00
2	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	60.00	50.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	70.00	0.00
4	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	700.00	550.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	750.00	400.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,630.00</b>	<b>1,020.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**