

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG21000288/UGA3Q2**Date:** 05/01/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800088914
<b>Claimant Vehicle No :</b>	PC8523A	<b>Insured Vehicle No :</b>	SFY886H
Date of Loss:	31/12/2020	Nature of Claim:	TP
		Claim No:	6242266001SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>PC8523A</b>		
Make & Model:	MERCEDES-BENZ VITO 114, 2.1 CDI PANEL VAN LONG ABS 5DR (A)	Engine No:	65195033657071
Reg. Date:	21/02/2017 (Man. Year: 2016)	Chassis No:	WDF44760323208394
Colour:	Silver	Odometer:	110754 km
Engine Capacity:	2143 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/65 R16	Rear Tyre Size:	205/65 R16
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	800.00	500.00	300.00	37.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>800.00</b>	<b>500.00</b>	<b>300.00</b>	<b>37.50</b>
<b>+ GST 7.00/7.00% (S\$)</b>	56.00	35.00	21.00	37.50
<b>Nett Amount (S\$)</b>	<b>856.00</b>	<b>535.00</b>	<b>321.00</b>	<b>37.50</b>
<b>+ Loss of Use (2.0 x S\$100.00/day) (S\$)</b>		200.00		
		<b>(S\$)</b>		
		735.00		
<b>Liabie Amount (50.00%) (S\$)</b>		<b>367.50</b>		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>369.50</b>		

INSPECTION

Date of Assignment:	07/01/2021		
Date Inspected:	07/01/2021	Inspected At:	Tan Lim Motor Pte Ltd (Defu) 1 Defu Lane 6 Singapore 539365
Estimated Period of Repair:	2.0 days		

**Adjuster:** MARCUS CHUA**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	300.00	100.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	500.00	400.00
<b>Gross Labour Cost (\$\$)</b>			<b>800.00</b>	<b>500.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >