

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21000292/UVD3Q2

Date: 14/01/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCNSA00118412005

Claimant Vehicle No : SJX1409D **Insured Vehicle No :** EX38G

Date of Loss: 04/01/2021 Nature of Claim: TP Claim No: SNM21D200056/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJX1409D**
 Make & Model: SUZUKI SX4, 1.5 (A) Engine No: M16A1515546
 Reg. Date: 19/05/2010 (Man. Year: 2010) Chassis No: JSAGYA21S00334195
 Colour: Red Odometer: 170979 km
 Engine Capacity: 1586 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60R16 Rear Tyre Size: 205/60R16
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,586.52	1,262.41	1,324.11	51.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,310.00	1,250.00	2,060.00	62.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,896.52	2,512.41	3,384.11	57.39
Approved Total (Overridden) (S\$)		2,000.00		
Nett Amount (S\$)	5,896.52	2,000.00	3,896.52	66.08

INSPECTION

Date of Assignment: 08/01/2021

Date Inspected: 07/01/2021 Inspected At: Asia Motorsports-kaki Bukit (HQ)
 15 KAKI BUKIT ROAD 4 #01-05/53
 BARTLEY BIZ CENTRE
 Singapore 417808

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Jan 2021)
Parts:	144	SUZUKI SX4 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJX1409D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Deformed/Cracked	625.90 FL	*588.15 FL
2	2		*REAR BUMPER RETAINER	Necessary	48.80 FL	*48.80 FL
3	2		*REAR BUMPER BRACKET	No such part	46.20 FL	*- FL
4	2		*REAR BUMPER REFLECTOR	Not Necessary	46.20 FL	*- FL
5	1		*REAR BUMPER REINFORCEMENT	Bent	215.30 FL	*215.30 FL
6	1		*REAR BUMPER LOWER PROTECTOR	Distorted	344.70 FL	*344.70 FL
7	1		*REAR BUMPER LEFT PROTECTOR	Not Necessary	176.50 FL	*- FL
8	1		*REAR BUMPER RIGHT PROTECTOR	Not Necessary	176.50 FL	*- FL
9	1		*REAR END LOWER PANEL	Repair	367.80 FL	*- FL
10	1		*REAR END LOWER PANEL TOP GARNISH	Not Necessary	118.60 FL	*- FL
11	1		*SET REAR BUMPER CLIPS	Necessary	65.00 FS	*45.00 FS
12	6		*REAR BUMPER LOWER PROTECTOR CLIPS	Not Necessary	40.00 FS	*- FS
13	4		*REAR BUMPER LEFT PROTECTOR CLIPS	Not Necessary	30.00 FS	*- FS
14	4		*REAR BUMPER RIGHT PROTECTOR CLIPS	Not Necessary	30.00 FS	*- FS
15	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	300.00 FS	*200.00 FS
16	1		*REAR NO PLATE WITH GARNISH	Not Necessary	100.00 FS	*- FS
17	4		*REAR END LOWER PANEL TOP GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
18	1		*REAR END LOWER PANEL SEALANT	Not Necessary	150.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,911.50	1,441.95
- List Item Discount on L Items 15.00/15.00% (\$\$)	324.98	179.54
Total Parts (\$\$)	2,586.52	1,262.41

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN REAR AFFECTED AREA AND REPLACE REAR DAMAGED PARTS	New	1,400.00	520.00
2	TO PUTTY AND SPRAY PAINTING REAR PORTION	New	1,400.00	580.00
3	TO CHECK REAR LIGHTING AND WIRING	New	50.00	20.00
4	TO REMOVE AND INSTALL REAR INNER GARNISH AND TRIM TO FACILITATE THE REPAIR	New	140.00	80.00
5	TO APPLY ANTI RUST PROOFING TO REAR AFFECTED AREA	New	140.00	0.00
6	TO REMOVE AND INSTALL REAR BUMPER REVERSE SENSOR	New	80.00	50.00
7	TOWING SERVICE	New	100.00	0.00
Gross Labour Cost (\$\$)			3,310.00	1,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >