

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21000295/DPA3Q2
Date: 02/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800037642
Claimant Vehicle No :	SHA1550Y	Insured Vehicle No :	SLX8032L
Date of Loss:	05/01/2021	Nature of Claim:	TP
		Claim No:	6797893515SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA1550Y		
Make & Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Engine No:	G4LEKU403526
Reg. Date:	30/10/2019 (Man. Year: 2019)	Chassis No:	KMHC851CVLU188603
Colour:	Blue	Odometer:	92491 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	DURATURN 5 mm	Rear Left Side:	DURATURN 5 mm
Front Right Side:	DURATURN 5 mm	Rear Right Side:	DURATURN 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,420.58	12,653.52	11,767.06	48.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,740.00	2,680.00	3,060.00	53.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	30,160.58	15,333.52	14,827.06	49.16
+ GST 7.00/7.00% (S\$)	2,111.24	1,073.35	1,037.89	49.16

Nett Amount (S\$)	32,271.82	16,406.87	15,864.95	49.16
+ Loss of Use (10.0 x S\$50.00/day) (S\$)		500.00		
+ Car Rental (10.0 x S\$125.19/day) (S\$)		1,251.90		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		80.00		
Nett Liability (S\$)		18,246.22		

INSPECTION

Date of Assignment: 07/01/2021

Date Inspected: 07/01/2021

Estimated Period of Repair: 9.0 days

Inspected At:

Bifrost Auto Pte Ltd (sin Ming) (HQ)
 Blk 9 Sector C, #01-42 Sin Ming Industrial Estate
 Singapore 575644

Adjuster: BRYAN TANI**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Cut / Mtg Cracked	418.30 FL	*418.30 FL
2	2		*FRONT BUMPER BRACKET (LH/RH)	Serviceable	56.00 FL	*- FL
3	1		*HEADLAMP (LH)	Cut / Scratched	3,987.30 FL	*2,397.60 FL
4	1		*FRONT FENDER (LH)	Dented	490.70 FL	*490.70 FL
5	1		*FRT DOOR (LH)	Bent / Dented	1,797.20 FL	*1,797.20 FL
6	1		*FRONT DOOR MIRROR HOLDER (LH)	Not Necessary	175.90 FL	*- FL
7	1		*FRONT DOOR MIRROR LAMP (LH)	Not Necessary	97.10 FL	*- FL
8	1		*REAR DOOR (LH)	Bent/ Dented	1,789.90 FL	*1,789.90 FL
9	1		*REAR DOOR HINGE LOWER (LH)	Not Necessary	170.50 FL	*- FL
10	1		*REAR DOOR CHECK (LH)	Not Necessary	85.92 FL	*- FL
11	1		*REAR DOOR TRIM BOARD (LH)	Not Necessary	613.60 FL	*- FL
12	1		*DOOR CENTRE PILLAR OUTER (LH)	Not Necessary	3,764.90 FL	*- FL
13	1		*ROCKER PANEL OUTER GARNISH	Cut	715.60 FL	*290.00 FL
14	1		*FRONT WHEEL RIM (LH)	Bent / Distorted	1,124.20 FL	*1,124.20 FL
15	1		*FRONT WHEEL HUB ASSY (LH)	Distorted	678.50 FL	*454.00 FL
16	1		*FRONT WHEEL HUB CAP	Bent	346.40 FL	*346.40 FL
17	1		*FRONT SHOCK ABSORBER (ASSY) (LH)	Distorted	372.50 FL	*372.50 FL
18	1		*FRONT SHOCK ABSORBER MOUNTING (LH)	Not Necessary	372.50 FL	*- FL
19	1		*FRONT DRIVE SHAFT (LH)	Not Necessary	1,136.70 FL	*- FL
20	1		*FRONT DRIVE SHAFT EXTENSION RH	Not Necessary	1,125.80 FL	*- FL
21	1		*RACK & PINION ASSY	Not Necessary	1,087.40 FL	*- FL
22	1		*STG TIE ROD	Not Necessary	125.60 FL	*- FL
23	1		*STG TIE END	Not Necessary	94.70 FL	*- FL
24	1		*STABILIZER BAR	Not Necessary	326.80 FL	*- FL
25	1		*STABILIZER BAR LINK	Not Necessary	92.10 FL	*- FL
26	1		*FRONT SUSPENSION LOWER ARM (LH)	Distorted	596.80 FL	*296.80 FL
27	1		*KNUCKLE ARM (LH)	Distorted	663.60 FL	*363.60 FL
28	1		*ABS SENSOR	Not Necessary	290.00 FL	*- FL
29	1		*REAR BUMPER	Repair	459.40 FL	*- FL
30	1		*REAR BUMPER COVER CLIPS	Serviceable	22.00 FL	*- FL
31	1		*REAR FENDER (LH)	Dented	1,768.30 FL	*1,768.30 FL
32	1		*REAR TYRE RIM (LH)	Distorted	1,124.20 FL	*1,124.20 FL
33	1		*REAR WHEEL HUP-CAP (LH)	Cut	346.40 FL	*346.40 FL
34	1		*REAR WHEELBEARING & HUB ASSY	Damaged	554.00 FL	*454.00 FL
35	1		*REAR TRAILING ARM (LH)	Distorted	265.40 FL	*265.40 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*REAR ASSIST (LH)	Distorted	227.90 FL	*227.90 FL
37	1		*REAR SHOCK ABSORBER (LH)	Distorted	230.50 FL	*230.50 FL
38	1		*REAR SHOCK ABSORBER MOUNTING (LH)	Not Necessary	133.10 FL	*- FL
39	1		*REAR ABSORBER STOPPER (LH)	Not Necessary	137.60 FL	*- FL
40	1		*REAR ABSORBER CAP	Not Necessary	175.60 FL	*- FL
41	1		*STABILIZER BAR	Not Necessary	387.30 FL	*- FL
42	1		*STABILIZER LINK (LH)	Not Necessary	147.30 FL	*- FL
43	1		*REAR UPPER ARM (LH)	Distorted	239.50 FL	*239.50 FL
44	1		*REAR LOWER ARM (LH)	Distorted	393.10 FL	*393.10 FL
45	1		*REAR KNUCKLE ARM (LH)	Distorted	538.10 FL	*386.90 FL
46	1		*EMBLEM -BLUE DRIVE (LH)	Necessary	26.60 FS	*26.60 FS
47	1		*FRONT DOOR COMFORT LOGO (LH)	Necessary	75.00 FS	*75.00 FS
48	1		*REAR DOOR TEL NO.STICKER(LH)	Necessary	10.00 FS	*10.00 FS
49	1		*REAR DOOR COMFORTDELGRO & APPS STICKER (LH)	Necessary	80.00 FS	*80.00 FS
50	1		*FRONT TYRE (LH)	Serviceable	216.00 FS	*- FS
51	1		*REAR TYRE (LH)	Serviceable	216.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	30,369.82	15,769.00
- List Item Discount on L Items 20.00/20.00% (S\$)	5,949.24	3,115.48
Total Parts (S\$)	24,420.58	12,653.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,400.00	900.00
2	SPRAY PAINTING CHARGE	New	1,200.00	1,000.00
3	WIRING CHARGE	New	120.00	30.00
4	TUFF KOTE	New	160.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
7	REMOVE/REFIX UNDERCARRIAGE (RR)	New	400.00	150.00
8	RE-SET REAR ABS SYSTEM	New	400.00	0.00
9	TRANSFER OF DOOR MECHANISM FRONT	New	80.00	60.00
10	RE-SET FRT POWER WINDOW SYSTEM	New	200.00	0.00
11	TRANSFER OF DOOR MECHANISM REAR	New	80.00	60.00
12	RE-SET REAR POWER WINDOW SYSTEM	New	200.00	0.00
13	FOUR WHEEL ALIGNMENT	New	120.00	60.00
14	REMOVE/REFIX UNDERCARRIAGE (FRT)	New	400.00	150.00
15	RE-SET FRT ABS SYSTEM	New	200.00	0.00
16	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	150.00
Gross Labour Cost (S\$)			5,740.00	2,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >