

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21000298/EVD3E2

Date: 08/04/2021

REFERENCE

Insured/Claimant:	JONATHAN TEH YI HUI	Policy No:	1800024196		
Date of Loss:	06/01/2021	Nature of Claim:	OD	Claim No:	2832412512SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW9178Z	Engine No:	D4HBHH350558
Make & Model:	KIA SORENTO, 2.2 (A)	Chassis No:	KNAPH81BMJ5417812
Reg. Date:	09/03/2018 (Man. Year: 2017)	Odometer:	43364 km
Colour:	Grey		
Engine Capacity:	2199 cc		
Market Value/New Car Price:	S\$99,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/60 R18	Rear Tyre Size:	235/60 R18
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,386.40	2,344.80	2,041.60	46.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,240.00	1,890.00	1,350.00	41.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,626.40	4,234.80	3,391.60	44.47
+ GST 7.00/7.00% (S\$)	533.85	296.44	237.41	44.47
Nett Amount (S\$)	8,160.25	4,531.24	3,629.01	44.47

INSPECTION

Date of Assignment:	07/01/2021	
Date Inspected:	07/01/2021 Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	5.0 days	

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*C&C EMBLEM	Necessary	50.00 FS	*40.00 FS
2	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
3	1		*PANEL ASSY-TAIL GATE	Dented	1,445.00 FL	*1,445.00 FL
4	1		*PANEL ASSY-BACK	Not Necessary	526.00 FL	*- FL
5	1		*TRIM ASSY-RR TRANSVERSE	Not Necessary	59.00 FL	*- FL
6	1		*W/STRIP-TAIL GATE OPNG	Not Necessary	128.00 FL	*- FL
7	1		*GLASS ASSY-TAIL GATE	Not Necessary	690.00 FL	*- FL
8	1		*LOGO ASSY-KIA SUB	Necessary	69.00 FL	*69.00 FL
9	1		*EMBLEM - ECO DYNAMICS	Necessary	37.00 FL	*37.00 FL
10	1		*COVER-RR BUMPER, UPR	Crushed	605.00 FL	*605.00 FL
11	1		*WIRING HARNESS-R.P.A.S	Not Necessary	240.00 FL	*- FL
12	1		*RAIL ASSY-REAR BUMPER	Not Necessary	341.00 FL	*- FL
13	1		*ANTENNA ASSY-SMARTKEY	Not Necessary	53.00 FL	*- FL
14	1		*COVER-BLANKING RR FOG, LH	Not Necessary	11.00 FL	*- FL
15	1		*COVER-RR BUMPER LWR	Cut	565.00 FL	*565.00 FL
16	1		*SKID PLATE-RR BUMPER	Cut	103.00 FL	*103.00 FL
17	1		*COVER ASSY-RR BPR UNDER	Not Necessary	30.00 FL	*- FL
18	2		*RETAINER-BUMPER MTG	Broken	4.00 FL	*4.00 FL
19	1		*BRACKET ASSY-RR BUMPER SIDE, LH	Not Necessary	25.00 FL	*- FL
20	1		*BRACKET ASSY-RR BUMPER SIDE, RH	Not Necessary	25.00 FL	*- FL
21	1		*ULTRASONIC SENSOR - S.P.A.S	Not Necessary	187.00 FL	*- FL
22	1		*ULTRASONIC SENSOR - S.P.A.S	Not Necessary	187.00 FL	*- FL
23	1		*EMBLEM-SORENTO	Necessary	28.00 FL	*28.00 FL
			(Supplementary)			

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,458.00	2,916.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,071.60	571.20
Total Parts (\$\$)	4,386.40	2,344.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE REAR TAILGATE, BUMPER & AFFECTED AREA. REPAIR ON END PANEL	New	1,600.00	800.00
2	PAINT WORK ON REAR TAILGATE, REAR BUMPER & END PANEL	New	1,050.00	700.00
3	REMOVE & INSTALL REAR PARKING ASSIST	New	120.00	120.00
4	REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR	New	120.00	0.00
5	TO TRANSFER REAR BOOT ATTACHMENT TO NEW PANEL	New	120.00	120.00
6	PERFORM RUST PREVENTION	New	80.00	0.00
7	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
8	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
Gross Labour Cost (\$)			3,240.00	1,890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >