

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Co Reg No : 199405410K

Authorized signatory and company stamp

ESTIMATE

GST Reg No : MR-8500111-X

invoice Name & Address	Owner Name & Vehicle Info				
AIG Asia Pacific Insurance Pte.	Cust No/Name	/Jonathan Teh Yi Hui			
Ltd.	Reg No/Reg Date	SLW9178Z / 09/03/201			
MOTOR CLAIM DEPARTMENT	Date In/Mileage	07/01/2021/ 0			
78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Chassis No	KNAPH81BMJ5417812			
	Engine No	D4HBHH350558			
	Make/Model	KIA/SORENTO 2.2 A SR GDCO			
	Colour/Trim	MST METAL STREAM / WK SATURN BLACK			

Account No	Terms	Date/Time Printed	CSE	Operator	100 0 W. C. 100 0 100 0	WIP No			
	Credit		QUK	282 / Kevin Leong		26897			
The second secon		Description of Goods	s / Services		Qty	Unit Price	Disc%		nount
E PNT88000	,	1						800	1600.00
REPLACE F	REAR'TAIL	GATE, BUMPER & AFFEC	CTED AREA	410 12				ľ	
REPAIR ON	END PAN	EL						700	1050.00
E PNT98000		-1		PANEL 350 X 2				100	1030.00
	K ON REA	R [!] TAILGATE, REAR ['] BUM	IPER & ENU	PANEL 130 X 7					120.00
E PNT88000	THETALL	DEAD DADVING ASSIST						1 _	220.0
	INSTALL	REAR PARKING ASSIST				(0)	mto)	3	120.0
E PNT88000	TNCTALL	REAR BOOT COMPARTMEN	T FOR FAC	ILITATE REPAIR			' '	, ×	
E PNT88000	INSTALL	NEAR DOOT COMPARTMEN	1 101 1710	ILITATE NETTIEN					120.0
	FR RFAR F	BOOT ATTACHMENT TO N	EW PANEL I		П			1 20	
M SUNDRY			25	ima	12/	2			80.0
PERFORM RI	JST PREVE	ENTION C	511			77		1	
A 54900099		L 7	ン) [L]			フ			30.0
	ING & CHA	SSIS ELECTRICAL SYS	TEM						
10028901									120.0
TO CARRY C	UT DIAGN	OSTIC CHECK USING H	I-SCAN PRO	O TEST					
USING HI-S	CAN PRO	TEST						10	2
1 SUNDRY								1 4%	7 50.0
TO SUPPLY	C & C EM	BLEM						1 2	2 50 0
SUNDRY								10	50.0
SUNDRIES		00				1445 00	00.00	1	1156 0
I PANEL ASSY		TE / VP			1.00	1445.00		1000	1156.0 420.8
PANEL ASSY		VERSE X MM			1.00		20.00		47.2
TRIM ASSY-	RR TRANS				1.00	128.00			102.4
W/STRIP-TA					1.00	690.00			552.0
GLASS ASSY	- TAIL GA				1.00		20.00	1	55.2
LOGO ASSY-					1.00		20.00	7	29.6
M EMBLEM-ECO M COVER-RR B					1.00	605.00			484.0
M WIRING HAR					1.00	240.00			192.0
M RAIL ASSY-		- /1 . / ./			1.00	341.00			272.8
M ANTENNA AS					1.00		20.00		42.4
M ANTENNA AS	cepted by				1.00	33.00		L	

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Page 1 of 2



CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Investor Name & Address	Owner Name & Vehicle Info			
Invoice Name & Address AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Engine No	/Jonathan Teh Yi Hui SLW9178Z / 09/03/201 07/01/2021/ 0 KNAPH818MJ5417812 D4H8HH350558 KIA/SORENTO 2.2 A SR GDCO MST METAL STREAM / WK SATURN BLACK		

			CSE	Operator		WIP No		
Account No	Terms	Date/Time Printed		282 / Kevin Leong		26897		
_AX00000	Credit	07/01/2021/ 09:50	QUK	ZOZ / KETTII ZEONG	Qty	Unit Price		Amount
		Description of Good	STSERVICES		1.00	11.00	20.00	8.8
M COVER-BLA	NKING RE	R FOG, LH X M/LI			1.00	565.00	20.00	452.0
M COVER-RR	BUMPER L	LWR / CUT) (U	IT		1.00	103.00	20.00	82.4 24.0
M SKID PLAT	E-RR BUN	MPER (SILVE) (N R UNDER 1 X MI	M		1.00	30.00	20.00	3.2
M COLEN USA		ITC AP			2.00	2.00	20.00	20.0
M RETAINER-	CCV DD E	DIMPER SIDE IH	MKI		1.00	25.00	20.00	20.0
M BRACKET A M BRACKET A	SSY-RR E	SUMPER SIDE, KH . J	MM		1.00 1.00		20.00	149.6
M III TRASONI	C SENSOR	R-S.P.A.S T X N	M		1.00		20.00	149.
M ULTRASONI	C SENSOR	R-S.P.A.S 1 X	MM		1.00			
			п		Π			
			\sim 4 1 1 1	ima	17/0		= = = = = = = = = = = = = = = = = = = =	
			\geq		ILIC	J 7		
			(1/1/2)	00 1/1 /1				
		Ctore (LKK)	NV- NV A				
		01016		1-17971-1				
		7/1/2 20	nam	Lyling,				
		111/11, 20	1	00- AM AL Excess - ? P/P				
				1 //				
				Ry Br Sy 5 dis	1			
				,] , 00			- 1	
				7007				
				0				
				V				
1		ts hence notify						
1	rer of the for	ollowing: r spray painting						
1		rt(s) during resurvey						
1		t to confirmation						
Third part	y survey is or	a "Without Prejudice" basis		8 (E)				
		by ist be resurveyed and						
		oval from Insurance Company				Net	tt	7,604.
Acknowled	ged by Repair	rer		7	% GST on	7604.0	00	532.
1						and the second		1
Signature:						tal Payab		8,136.2

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen the rubber seal or other repair requiring the removal of the windscreen.