Adjuster Report Page 1 of 5

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21000304/KTD3Q2

Date: 25/02/2021

REFERENCE

China Taiping Insurance Policy No: Handling Insurer:

(Singapore) Pte. Ltd.

DMHCSNW00005102000

Claimant Vehicle No:

GBA6062C

Insured SJP1922E Vehicle No:

Date of Loss: 04/01/2021 Nature of

TP Claim:

Claim SNM21D200080/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBA6062C**

Make & Model: SUZUKI EVERY, 660cc GA (M) Engine No: **HIDDEN** Reg. Date: 12/09/2007 (Man. Year: 2007) Chassis No: DA64V209560 Colour: Odometer: 174153 km White

Engine Capacity: 658 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 155 R12X8 Rear Tyre Size: 155 R12X8 Front Left Side: Yokohama 7 mm Rear Left Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm Front Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,464.70	3,037.26	6,427.44	67.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,670.00	1,915.00	1,755.00	47.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,134.70	4,952.26	8,182.44	62.30
Approved Total (Overridden) (S\$)		2,500.00		
(S\$)	13,134.70	2,500.00	10,634.70	80.97
+ GST 7.00/7.00% (S\$)	919.43	175.00	744.43	80.97
Nett Amount (S\$)	14,054.13	2,675.00	11,379.13	80.97

INSPECTION

Date of Assignment: 20/01/2021

Date Inspected: 08/01/2021 Inspected At: Yee Auto Pte Ltd (HQ)

160 SIN MING DRIVÉ, #02-17 SIN

MING AUTOCITY Singapore 575722

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG Manager: DENISE TAY KWEE CHENG Adjuster Report Page 2 of 5

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 5

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 22 Feb 2021)

Parts: N/A SUZUKI EVERY 660cc GA (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBA6062C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR AIR VENT	Serviceable	45.10 F	*- FL
2	1		*REAR BUMPER	Bent	850.15 F	*850.15 FL
3	1		*REAR BUMPER BRACKET -LH	Serviceable	50.35 F	*- FL
4	1		*REAR BUMPER BRACKET -RH	Distorted	50.35 F	*50.35 FL
5	1		*SET REAR BUMPER CLIPS	Necessary	40.00 F	*40.00 FL
6	1		*REAR BUMPER SIDE RETAINER -LH	Serviceable	40.35 F	*- FL
7	1		*REAR BUMPER SIDE RETAINER -RH	Cracked	40.35 F	*40.35 FL
8	1		*REAR DUST COVER -LH	Serviceable	48.50 F	*- FL
9	1		*REAR DUST COVER -RH	Serviceable	48.50 F	*- FL
10	1		*REAR END INNER PANEL	Bent	300.05 F	*300.05 FL
11	1		*REAR END PANEL	Bent	350.85 F	*350.85 FL
12	1		*REAR FLOOR BOARD INSULATOR	Serviceable	180.05 F	*- FL
13	1		*REAR FLOOR BOARD PANEL	Repair	1,240.05 F	*- FL
14	1		*EXHAUST MOUNTING	Serviceable	70.10 F	*-FL
15	1		*REAR EXHAUST MUFFLER	Repair	584.35 F	*- FL
16	1		*REAR NUMBER PLATE LAMP -LH	Serviceable	60.10 F	*-FL
17	1		*REAR NUMBER PLATE LAMP -RH	Serviceable	60.10 F	*- FL
18	1		*REAR WINDSCREEN MOULDINGS	Not Necessary	108.50 F	*- FL
19	1		*REAR WINDSCREEN SOLAR FILM	Not Necessary	200.00 F	*- FL
20	1		*REAR WIPER ARM	Serviceable	73.10 F	*- FL
21	1		*REAR WIPER BLADE	Serviceable	33.10 F	*- FL
22	1		*REAR WIPER MOTOR	Serviceable	385.10 F	*- FL
23	1		*SPARE WHEEL CARRIER	Repair	220.05 F	*- FL
24	1		*SPARE WHEEL HOLDER	Repair	80.10 F	*-FL
25	1		*SPEED LIMIT STICKER 70KM/H	Necessary	20.00 FS	*12.00 FS
26	1		*REAR TAILGATE	Bent	1,360.35 F	*1,360.35 FL
27	1		*REAR TAILGATE SHOCK ABSORBER -LH	Serviceable	240.10 F	*-FL
28	1		*REAR TAILGATE SHOCK ABSORBER -RH	Serviceable	240.10 F	*-FL
29	1		*REAR TAILGATE INNER HOLDER	Dented	80.00 F	*80.00 FL
30	1		*REAR TAILGATE INNER TRIM BOARD	Serviceable	355.05 F	*-FL
31	1		*REAR TAILGATE LOWER LOCK	Repair	30.05 F	*- FL
32	1		*REAR TAILGATE OUTER HANDLE	Serviceable	92.00 F	*- FL
33	1		*REAR TAILGATE STICKER 5PAX	Necessary	20.00 FS	*12.00 FS
34	1		*REAR TAILGATE STICKER EVERY	Necessary	45.00 F	*45.00 FL
35	1		*REAR TAILGATE LOGO SUZUKI	Necessary	48.00 F	*48.00 FL
36	1		*REAR TAILGATE TOP LOCK	Dented	250.05 F	*250.05 FL
37	1		*REAR TAILGATE WEATHERSTRIP (50%)	Distorted / Dented	180.75 FS	*90.38 FS
38	1		*TAIL LAMP LH	Serviceable	642.00 F	*- FL
39	1		*TAIL LAMP RH	Serviceable	642.00 F	*- FL
40	1		*REAR NUMBER PLATE	Dented	60.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$	9,464.70	3,549.53
- List Item Discount on L Items 0.00/15.00% (S\$	0.00	512.27

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 5

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Total Parts (S\$)	9,464.70	3,037.26
	Report was unsubmitted during this print-out.					

Adjuster Report Page 5 of 5

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO DISMANTLE & REPLACE DAMAGED PARTS ,PANEL BEAT WHERE NECESSARY	New	1,600.00	800.00
2	TO PUTTY ,APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION	New	1,300.00	800.00
3	TO APPLY RUST-PROOFING ON REPAIRED ,REPLACED PANEL	New	220.00	60.00
4	TO REMOVE /REFIX REAR WINDSCREEN TO FACILITATE REPAIRS	New	200.00	120.00
5	TO REMOVE /TRANSFER TAILGATE COMPONENTS	New	100.00	60.00
6	TO REMOVE/RENEW EXHAUST MUFFLER	New	80.00	60.00
7	TOWING FEE	New	120.00	0.00
8	TO CHECK WIRING FUNCTIONS	New	50.00	15.00
	Gross Labou	3,670.00	1,915.00	
	Report was unsubmitted durin	g this print-out.		

< END OF ESTIMATES >