

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG21000324/ATD3E2

**Date:** 27/07/2021

### REFERENCE

Insured/Claimant:	WIDDEK HELMUT	Policy No:	1900141530		
Date of Loss:	05/01/2021	Nature of Claim:	OD	Claim No:	3294633077SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFQ1282K	Engine No:	CZS009717
Make & Model:	AUDI A8 L, 3.0 TFSI QU (A)	Chassis No:	WAUZZZF87JN014090
Reg. Date:	13/08/2019 (Man. Year: 2018)	Odometer:	8206 km
Colour:	Maroon		
Engine Capacity:	2995 cc		
Market Value/New Car Price:	S\$290,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	255/45 R19	Rear Tyre Size:	255/45 R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre tread depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	77,602.00	25,814.16	51,787.84	66.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,572.00	7,672.00	2,900.00	27.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>88,174.00</b>	<b>33,486.16</b>	<b>54,687.84</b>	<b>62.02</b>
<b>- Excess (S\$)</b>	<b>2,400.00</b>	<b>2,400.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>85,774.00</b>	<b>31,086.16</b>	<b>54,687.84</b>	<b>63.76</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>6,004.18</b>	<b>2,176.03</b>	<b>3,828.15</b>	<b>63.76</b>
<b>Nett Amount (S\$)</b>	<b>91,778.18</b>	<b>33,262.19</b>	<b>58,515.99</b>	<b>63.76</b>

### INSPECTION

Date of Assignment:	07/01/2021		Premium Automobiles Pte Ltd
Date Inspected:	07/01/2021	Inspected At:	24 Benoi Sector Singapore 629857
Estimated Period of Repair:	12.0 days		

**Adjuster:** ADRIAN LING

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REAR ALUMINIUM RIM - LH / RH	Cut	2,862.00 FS	*2,289.60 FS
2	1		*SUPPORT FRAME	Bent	3,454.00 FS	*2,763.20 FS
3	2		*ECCENTRIC WASHER	Not Necessary	11.00 FS	*- FS
4	1		*REAR SUBFRAME SUPPORT	Not Necessary	154.00 FS	*- FS
5	1		*REAR AXLE DIFFERENTIAL	Not Necessary	13,680.00 FS	*- FS
6	1		*AXLE OIL	Not Necessary	133.00 FS	*- FS
7	2		*REAR DRIVE SHAFT - LH / RH	Not Necessary	3,930.00 FS	*- FS
8	1		*GUARD PLATE - LH	Not Necessary	132.00 FS	*- FS
9	1		*SEALANT	Not Necessary	192.00 FS	*- FS
10	1		*LOWER ARM WISHBONE - LH / RH	N/S NotNecessary / O/S Bent	1,718.00 FS	*687.20 FS
11	1		*UPPER ARM WISHBONE - LH / RH	N/S NotNecessary / O/S Bent	1,186.00 FS	*474.40 FS
12	1		*LOWER WISHBONE STEEL VERSION - LH / RH	N/S NotNecessary / O/S Bent	458.00 FS	*183.20 FS
13	1		*REAR WISHBONE - LH / RH	N/S NotNecessary / O/S Bent	590.00 FS	*236.00 FS
14	1		*TRACK ROD - LH / RH REAR	N/S NotNecessary / O/S Bent	394.00 FS	*157.20 FS
15	1		*WHEEL BEARING HOUSING - LH / RH	N/S NotNecessary / O/S Damaged	1,964.00 FS	*785.60 FS
16	2		*UPPER ARM WISHBONE STEEL VERSION STONE CHIP GUARD - LH / RH INNER	Not Necessary	86.00 FS	*- FS
17	2		*UPPER ARM WISHBONE STONE CHIP GUARD - LH / RH	Not Necessary	90.00 FS	*- FS
18	1		*REAR STEERING GEAR	Damaged	5,991.00 FS	*4,792.80 FS
19	2		*REAR SHOCK ABSORBER - LH / RH	Not Necessary	9,198.00 FS	*- FS
20	1		*REAR SUSPENSION FORKS	N/S NotNecessary / O/S Bent	527.00 FS	*210.80 FS
21	1		*ANTI-ROLL BAR	Bent	433.00 FS	*345.60 FS
22	2		*COUPLING ROD - REAR	Bent	171.00 FS	*136.16 FS
23	1		*CARDAN SHAFT	Not Necessary	5,189.00 FS	*- FS
24	1		*REAR SILENCER - LH / RH	O/S Dented	2,904.00 FS	*1,161.60 FS
25	2		*REAR SILENCER DUAL CLIP	Necessary	118.00 FS	*94.24 FS
26	1		*CENTRE SILENCER	Not Necessary	1,303.00 FS	*- FS
27	4		*CENTRE SILENCER DUAL CLIP	Not Necessary	236.00 FS	*- FS
28	2		*EXHAUST SILENCER BRACKET	Not Necessary	83.00 FS	*- FS
29	1		*UNDERBODY TRIM - REAR CENTRE	Torn	278.00 FS	*222.40 FS
30	2		*UNDERBODY TRIM - LH / RH REAR	Not Necessary	378.00 FS	*- FS
31	2		*REAR SILENCER HEAT SHIELD - LH / RH	Not Necessary	310.00 FS	*- FS
32	1		*REAR SUBFRAME BRACA - LH / RH	O/S Bent	1,038.00 FS	*414.80 FS
33	1		*HEAT SHIELD - REAR	Not Necessary	245.00 FS	*- FS
34	1		*FUEL TANK	Cut	6,972.00 FS	*5,577.60 FS
35	1		*FUEL TANK SEAL RING	Not Necessary	40.00 FS	*- FS
36	1		*FUEL TANK PROTECTIVE PLATE	Necessary	79.00 FS	*62.48 FS
37	1		*REAR BUMPER	Deformed	3,976.00 FS	*3,180.80 FS
38	2		*REAR BUMPER CLOSING ELEMENT - LH / RH	Not Necessary	68.00 FS	*- FS
39	1		*REAR BUMPER SPOILER	Deformed	1,114.00 FS	*891.20 FS
40	1		*REAR BUMPER SECURING STRIP	Necessary	157.00 FS	*125.60 FS
41	2		*REAR BUMPER TRIM - LH / RH LOWER	Not Necessary	1,014.00 FS	*- FS
42	1		*REAR BUMPER CHROME TRIM - LOWER CENTRE	Not Necessary	309.00 FS	*- FS
43	2		*REAR BUMPER CHROME TRIM - LH / RH UPPER	Not Necessary	578.00 FS	*- FS
44	1		*REAR BUMPER CHROME TRIM - UPPER CENTRE	Deformed	520.00 FS	*415.60 FS
45	2		*REAR LIGHT REFLECTOR - LH / RH OUTER	Not Necessary	82.00 FS	*- FS
46	2		*REAR LIGHT REFLECTOR - LH / RH INNER	Not Necessary	60.00 FS	*- FS
47	2		*REAR PARKING AID SENSOR	Not Necessary	484.00 FS	*- FS
48	4		*REAR PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
49	1		*REAR BUMPER CARRIER	Not Necessary	1,525.00 FS	*- FS
50	1		*REAR BUMPER HOLDING STRAP	Not Necessary	106.00 FS	*- FS
51	2		*REAR BUMPER SEAL - LH / RH	Not Necessary	28.00 FS	*- FS
52	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
53	1		*SUNDRIES	Necessary	600.00 FS	*349.60 FS
54	1		*REAR BUMPER FIXING PARTS	Not Necessary	164.00 FS	*- FS
55	1		*FUEL TANK INSERT	Necessary	96.00 FS	*76.48 FS
			(Supplementary)			
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					77,602.00	25,814.16

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR SPARE WHEEL HOUSING. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,800.00	900.00
3	TO RESPRAY REAR UPPER BUMPER, REAR BUMPER LOWER SPOILER AND SPARE WHEEL HOUSING	New	3,600.00	1,600.00
4	TO REMOVE AND RENEW REAR SUSPENSION ASSEMBLY WITH SUBFRAME. INCLUDING REAR AXLE AND PORPELLOR SHAFT. RENEW ACCORDINGLY	New	2,800.00	2,800.00
5	TO REMOVE AND RENEW FUEL TANK ASSY	New	780.00	780.00
6	TO RENEW BOTH REAR RIMS. TO CARRY OUT PRE AND POST WHEEL ALIGNMENT	New	560.00	560.00
7	TO REMOVE AND RENEW BOTH REAR EXHAUST SILENCER AND ALIGN TO POSITION	New	480.00	480.00
8	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>10,572.00</b>	<b>7,672.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >