

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG21000326/ATD3Q2

Date: 22/03/2021

REFERENCE

Insured/Claimant:	ROOPAK SEKHRI	Policy No:	2070172487	
Date of Loss:	30/12/2020	Nature of Claim:	OD	Claim No: 7854714297SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBN7541L		
Make & Model:	AUDI Q3 SPORTBACK, 1.4 TFSI S TRONIC (17) (A)	Engine No:	CZDC09552
Reg. Date:	15/12/2020 (Man. Year: 2020)	Chassis No:	WAUZZZF32M1023683
Colour:	Grey	Odometer:	293 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$150,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65R17	Rear Tyre Size:	215/65R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,649.00	428.80	6,220.20	93.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,032.00	1,822.00	6,210.00	77.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,681.00	2,250.80	12,430.20	84.67
- Excess (S\$)	400.00	400.00	0.00	0.00
(S\$)	14,281.00	1,850.80	12,430.20	87.04
+ GST 7.00/7.00% (S\$)	999.67	129.56	870.11	87.04
Nett Amount (S\$)	15,280.67	1,980.36	13,300.31	87.04

INSPECTION

Date of Assignment:	07/01/2021	
Date Inspected:	07/01/2021	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT SPOILER	Not Necessary	379.00 FS	*- FS
2	1		*FRONT BUMPER GUIDE SECTION-LH	Not Necessary	38.00 FS	*- FS
3	1		*FRONT FENDER-LH	Repair	1,271.00 FS	*- FS
4	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	62.00 FS	*- FS
5	1		*FRONT FENDER BRACE-LH	Not Necessary	87.00 FS	*- FS
6	1		*FRONT FENDER BRACKET-LH	Not Necessary	31.00 FS	*- FS
7	1		*FRONT WHEEL COVER-LH/RH	N/s Cut	530.00 FS	*214.40 FS
8	1		*FRONT DOOR-LH	Repair	2,542.00 FS	*- FS
9	1		*FRONT DOOR OUTER SEAL-LH	Not Necessary	164.00 FS	*- FS
10	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	155.00 FS	*- FS
11	1		*FRONT DOOR CATCH	Not Necessary	119.00 FS	*- FS
12	1		*FRONT DOOR COVER-LH	Cut	265.00 FS	*214.40 FS
13	1		*FRONT ALUMINIUM RIM-LH	Not Necessary	756.00 FS	*- FS
14	1		*SUNDRIES	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	6,649.00	428.80
--------------------------	-----------------	---------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	280.00	0.00
2	TO DISMANTLE AND REINSTALL LHS FRONT DOOR PANEL TRIM.TO REMOVE AND REINSTALL LHS WING MIRROR ASSY	New	400.00	280.00
3	TO REMOVE AND TRANSFER LHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES	New	280.00	0.00
4	TO DISMANTLE FRONT BUMPER,LHS FRONT FENDER AND LHS FRONT DOOR.TO RENEW LHS FRONT FENDER AND LHS FRONT DOOR.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	3,200.00	250.00
5	TO RESPRAY FRONT BUMPER,LHS FRONT FENDER AND LHS FRONT DOOR	New	3,400.00	1,100.00
6	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			8,032.00	1,822.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >