



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Ref: CS3/III20011781/Gvd3e2-1	
			Date: 22/01/2021	
			Code: III2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 4033Z	Veh. Inspected	GBG 8908T
	Policy No.	MCOM0015	Coverage (\$)	0.00
	Claim No.	MCT20100461/01	Excess (\$)	0.00
	Assign From	CARINE KEK	Assign Date	08/01/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA DYNA	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	KDY2318027636	Colour	SILVER
	Odometer	75325 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185 R15	BRIDGESTONE	6 mm
	L/H Front Tyre	185 R15	BRIDGESTONE	6 mm
	R/H Rear Tyre	165 R13	BRIDGESTONE	6 mm
	L/H Rear Tyre	165 R13	BRIDGESTONE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	28/10/2020	Inspection Date	29/10/2020
	Survey held at	EVERDAWN AUTO SERVICE 8 KAKI BUKIT AVE 4 #01-02 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	