

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CS/AIG21000328/EQD3E2

**Date:** 26/01/2021

### REFERENCE

Insured/Claimant:	SENG BOON TECK	Policy No:	1900254065		
Date of Loss:	06/01/2021	Nature of Claim:	OD	Claim No:	1371093144SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCU7887R	Engine No:	G3LCKP111753
Make & Model:	KIA STONIC, 998cc (A)	Chassis No:	KNAD6811VL6346850
Reg. Date:	12/12/2019 (Man. Year: 2019)	Odometer:	21228 km
Colour:	White		
Engine Capacity:	998 cc		
Market Value/New Car Price:	S\$79,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/55R17	Rear Tyre Size:	205/55R17
Front Left Side:	Continental 5 mm	Rear Left Side:	Continental 5 mm
Front Right Side:	Continental 5 mm	Rear Right Side:	Continental 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,288.40	972.00	1,316.40	57.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,710.00	660.00	2,050.00	75.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>4,998.40</b>	<b>1,632.00</b>	<b>3,366.40</b>	<b>67.35</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>349.89</b>	<b>114.24</b>	<b>235.65</b>	<b>67.35</b>
<b>Nett Amount (S\$)</b>	<b>5,348.29</b>	<b>1,746.24</b>	<b>3,602.05</b>	<b>67.35</b>

### INSPECTION

Date of Assignment:	08/01/2021		
Date Inspected:	08/01/2021	Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	3.0 days		

**Adjuster:** CHEN TSUE YEE

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BRACKET ASSY-RR BUMPER SIDE,LH	Not Necessary	27.00 FL	*- FL
2	1		*BRACKET ASSY-RR BUMPER SIDE,RH	Not Necessary	27.00 FL	*- FL
3	1		*ANTENNA ASSY-SMARTKEY	Not Necessary	32.00 FL	*- FL
4	2		*BRACKET-RR BEAM UPR MTG	Not Necessary	14.00 FL	*- FL
5	1		*BRACKET-RR BEAM LWR MTG,LH	Broken	7.00 FL	*7.00 FL
6	1		*BRACKET-RR BEAM LWR MTG,RH	Not Necessary	5.00 FL	*- FL
7	1		*STAY-RR BUMPER LH	Not Necessary	55.00 FL	*- FL
8	1		*STAY-RR BUMPER RH	Not Necessary	55.00 FL	*- FL
9	1		*WIRING HARNESS-BWS EXT	Not Necessary	245.00 FL	*- FL
10	10		*CLIP	Necessary	10.00 FL	*10.00 FL
11	1		*COVER-RR BUMPER LWR	Crushed	366.00 FL	*366.00 FL
12	1		*MOULDING ASSY-RR BUMPER SIDE,L	Not Necessary	152.00 FL	*- FL
13	1		*MOULDING ASSY-RR BUMPER SIDE,R	Not Necessary	152.00 FL	*- FL
14	1		*CAP-RR HOOK	Crushed	5.00 FL	*5.00 FL
15	1		*SKID PLATE-RR BUMPER	Crushed	122.00 FL	*122.00 FL
16	10		*CLIP	Necessary	10.00 FL	*10.00 FL
17	1		*ULTRASONIC SENSOR ASSY-BWS	Shorted	189.00 FL	*189.00 FL
18	1		*ULTRASONIC SENSOR ASSY-BWS	Not Necessary	189.00 FL	*- FL
19	1		*ULTRASONIC SENSOR ASSY-BWS	Not Necessary	189.00 FL	*- FL
20	1		*ULTRASONIC SENSOR ASSY-BWS	Not Necessary	189.00 FL	*- FL
21	1		*TRIM ASSY-RR TRANSVERSE	Not Necessary	55.00 FL	*- FL
22	1		*LAMP ASSY-REAR FOG & R/REFL,LH	Not Necessary	111.00 FL	*- FL
23	1		*LAMP ASSY-REAR FOG & R/REFL,RH	Not Necessary	111.00 FL	*- FL
24	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
25	1		*BEAM-RR BUMPER (Supplementary)	Broken	419.00 FL	*419.00 FL
26	1		*COVER-RR BUMPER SIDE UNDER (Supplementary)	Broken	62.00 FL	*62.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>2,848.00</b>	<b>1,210.00</b>
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	559.60	238.00
<b>Total Parts (S\$)</b>	<b>2,288.40</b>	<b>972.00</b>

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	RENEW ACCIDENT DAMAGED PARTS ON REAR BUMPER FACE,REPAIR REAR END PANEL	New	1,200.00	400.00
2	REMOVE AND INSTALL PARKING ASSIST	New	60.00	60.00
3	REMOVE AND INSTALL REAR BOOT GARNISH TO FACILITATE REPAIR WORK	New	120.00	0.00
4	PAINT WORK SPRAY REAR END PANEL,REAR BUMPER AND AFFECTED PORTION	New	1,050.00	0.00
5	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
6	PERFORM RUST PREVENTION	New	80.00	0.00
7	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
8	SUPPLY REAR NUMBER PLATE WITH FRAME	New	50.00	50.00

<b>Gross Labour Cost (\$\$)</b>	<b>2,710.00</b>	<b>660.00</b>
---------------------------------	-----------------	---------------

Report was unsubmitted during this print-out.

< END OF ESTIMATES >