



CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

ESTIMATE

GST Reg No : MR-8500111-X

Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV11677/SENG BOON TECK Reg No/Reg Date SCU7887R*KC17/ 12/12/201 Date In/Mileage / 21228 Chassis No KNAD6811VL6346850 Engine No G3LCKP111753 Make/Model KIA/STONIC 1.0 A SX BJ3 W SUNROOF Colour/Trim UD CLEAR WHITE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	07/01/2021/ 16:40	QUD	247 / DonBong	26943			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW ACCIDENT DAMAGED PARTS ON REAR BUMPER FACE, REPAIR REAR END PANEL								1200.00
E PNT88000 REMOVE AND INSTALL PARKING ASSIST								60.00
E PNT88000 REMOVE AND INSTALL REAR BOOT GARNISH TO FACILITATE REPAIR WORK								120.00
E PNT98000 PAINT WORK SPRAY REAR END PANEL, REAR BUMPER AND AFFECTED PORTION								1050.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								30.00
M SUNDRY PERFORM RUST PREVENTION								80.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								120.00
M SUNDRY SUPPLY REAR NUMBER PLATE WITH FRAME								50.00
M SUNDRY SUNDRIES								50.00
M BRACKET ASSY-RR BUMPER SIDE, LH					1.00	27.00	20.00	21.60
M BRACKET ASSY-RR BUMPER SIDE, RH					1.00	27.00	20.00	21.60
M ANTENNA ASSY-SMARTKEY					1.00	32.00	20.00	25.60
M BRACKET-RR BEAM UPR MTG					2.00	7.00	20.00	11.20
M BRACKET-RR BEAM LWR MTG, LH					1.00	7.00	20.00	5.60
M BRACKET-RR BEAM LWR MTG, RH					1.00	5.00	20.00	4.00
M STAY-RR BUMPER LH					1.00	55.00	20.00	44.00
M STAY-RR BUMPER RH					1.00	55.00	20.00	44.00
M WIRING HARNESS-BWS EXT					1.00	245.00	20.00	196.00
M CLIP					10.00	1.00	20.00	8.00
M COVER-RR BUMPER LWR (Black)					1.00	366.00	20.00	292.80

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV11677/SENG BOON TECK Reg No/Reg Date SCU7887R*KC17/ 12/12/201 Date In/Mileage / 21228 Chassis No KNAD6811VL6346850 Engine No G3LCKP111753 Make/Model KIA/STONIC 1.0 A SX BJ3 W SUNROOF Colour/Trim UD CLEAR WHITE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	07/01/2021/ 16:40	QUD	247 / DonBong	26943			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	MOULDING ASSY-RR BUMPER SIDE, L	?	X NN		1.00	152.00	20.00	121.60
M	MOULDING ASSY-RR BUMPER SIDE, R	?	X NN		1.00	152.00	20.00	121.60
M	CAP-RR HOOK / CR				1.00	5.00	20.00	4.00
M	SKID PLATE-RR BUMPER (S/L) - CR				1.00	122.00	20.00	97.60
M	CLIP / RK				10.00	1.00	20.00	8.00
M	ULTRASONIC SENSOR ASSY-BWS	/	PL		1.00	189.00	20.00	151.20
M	ULTRASONIC SENSOR ASSY-BWS	?	X NN		1.00	189.00	20.00	151.20
M	ULTRASONIC SENSOR ASSY-BWS	?	X NN		1.00	189.00	20.00	151.20
M	ULTRASONIC SENSOR ASSY-BWS	?	X NN		1.00	189.00	20.00	151.20
M	TRIM ASSY-RR TRANSVERSE X		NN		1.00	55.00	20.00	44.00
M	LAMP ASSY-REAR FOG & R/REFL TH		X NN		1.00	111.00	20.00	88.80
M	LAMP ASSY-REAR FOG & R/REFL RH		X NN		1.00	111.00	20.00	88.80

Estimate

SURVEYOR NAME: Steve (LKK) 8/1/21, 10.30 am

SURVEYOR SIGNATURE: DD-NH Aut

DATE: Excess - ?

REMARKS: P/P

My Bel sp
3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

Confirm & accepted by

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Authorized signatory and company stamp

7% GST on Net 4,613.60
4613.60 322.95
Total Payable 4,936.55

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.