

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21000339/ATD3Q2

Date: 05/02/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNA00004132000

Claimant Vehicle No : JPE732 **Insured Vehicle No :** SLE7938E

Date of Loss: 19/12/2020 Nature of Claim: TP Claim No: SNM20D204982/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	JPE732	Engine No:	G399EE098282
Make & Model:	YAMAHA 135LC, 135cc ES	Chassis No:	PMYKG054000038282
Reg. Date:	20/02/2013 (Man. Year: 2013)	Odometer:	74128 km
Colour:	White		
Engine Capacity:	135 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	70/90R17	Rear Tyre Size:	80/90R17
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,039.54	2,290.60	1,748.94	43.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,280.00	620.00	660.00	51.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,319.54	2,910.60	2,408.94	45.28
Approved Total (Overridden) (S\$)		1,500.00		
Nett Amount (S\$)	5,319.54	1,500.00	3,819.54	71.80

INSPECTION

Date of Assignment: 08/01/2021

Date Inspected: 07/01/2021 Inspected At:

Ms Car Auto Pte Ltd (HQ)
8 KAKI BUKIT AVE 4 #01-07
PREMIER @ KAKI BUKIT
Singapore 415875

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 04 Feb 2021)	
Parts:	N/A	YAMAHA 135LC 135cc ES (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for JPE732)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP	Cut	184.50 FL	*184.50 FL
2	1		*HEADLAMP COWLING	Cut	136.10 FL	*136.10 FL
3	1		*FRONT CENTER COWLING	Cut	167.50 FL	*167.50 FL
4	2		*SIGNAL R/L	Not Necessary	106.40 FL	*- FL
5	1		*FRONT FENDER	Cut	146.40 FL	*146.40 FL
6	1		*MIRROR L+R	N/s Cut	100.00 FL	*50.00 FL
7	1		*HANDERBAR	Not Necessary	86.40 FL	*- FL
8	1		*SET BALANCER	N/s Cut	84.30 FL	*30.00 FL
9	1		*BRAKE LEVER	Not Necessary	65.00 FL	*- FL
10	1		*FORK ASSY	Not Necessary	582.70 FL	*- FL
11	1		*FORK STEM	Not Necessary	62.40 FL	*- FL
12	3		*EMBLEM YAMAHA	Necessary	30.00 FL	*30.00 FL
13	1		*FRONT SIDE FAIRING L+R	N/s Cut	336.80 FL	*168.40 FL
14	1		*FRONT WHEEL BEARING	Not Necessary	60.00 FL	*- FL
15	1		*FOOT REST BAR	Cut	187.30 FL	*58.00 FL
16	1		*FOOT REST RUBBER L+R	N/s Cut	80.00 FL	*40.00 FL
17	1		*REAR HANDER	Cut	121.50 FL	*121.50 FL
18	2		*REAR SIGNAL RL	Not Necessary	110.00 FL	*- FL
19	1		*SWING ARM	Bent	386.40 FL	*386.40 FL
20	1		*REAR LIGHT	Smashed	158.00 FL	*158.00 FL
21	1		*GEAR PEDAL	Cut	125.20 FL	*125.20 FL
22	2		*REAR SIGNAL RL	Not Necessary	130.40 FL	*- FL
23	1		*REAR MUDGARD	Cracked	124.60 FL	*124.60 FL
24	1		*REAR CHAIN	Not Necessary	164.30 FL	*- FL
25	2		*REAR SIDE FAIRING R/L	Cracked	297.40 FL	*297.40 FL
26	1		*FRONT NUMBER PLATE	Necessary	20.00 FS	*20.00 FS
27	1		*REAR NUMBER PLATE	Missing	30.00 FS	*30.00 FS
28	1		*REAR TYRE	Not Necessary	75.30 FS	*- FS
29	1		*REAR RIM	Cracked	134.80 FS	*134.80 FS
30	1		*CENTER BASKET	Bent	104.20 FS	*104.20 FS
31	1		*FORK OIL	Not Necessary	45.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,442.90	2,513.00
- List Item Discount on L Items 10.00/10.00% (\$)	403.36	222.40
Total Parts (\$)	4,039.54	2,290.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	WORKMANSHIP	New	600.00	250.00
2	SPRAY PAINTING	New	400.00	200.00
3	ELECTRICAL	New	80.00	30.00
4	TO CHECK CHASSIS ALIGNMENT	New	80.00	80.00
5	TO CHECK WHEEL ALIGNMENT	New	120.00	60.00
Gross Labour Cost (\$\$)			1,280.00	620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >