LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.

Our File No: CS/AIG21000357/EQD3E2

AIG Building, 78 Shenton Way, #09-16

Singapore 079120 Date: 23/03/2021

REFERENCE

Insured/Claimant: YEE WAN FIRNG Policy No: 2100459013

Date of Loss: 06/01/2021 Nature of Claim: OD Claim No: 3827252746SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLB5796B

Make & Model: KIA SORENTO, 2.2 UM (A) Engine No: D4HBGH265701

Reg. Date: 05/04/2016 (Man. Year: 2016) Chassis No: KNAPH81BMG5202033

Colour: Grey Odometer: 179515 km

Engine Capacity: 2199 cc
Market Value/New Car Price: \$\$78,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55Z R19 Rear Tyre Size: 235/55Z R19
Front Left Side: Kumho 5 mm Rear Left Side: Kumho 5 mm
Front Right Side: Kumho 5 mm
Rear Right Side: Kumho 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		3,991.20	1,285.60	2,705.60	67.79
Miscellaneous Items		0.00	0.00	0.00	
Labour		3,380.00	1,020.00	2,360.00	69.82
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	7,371.20	2,305.60	5,065.60	68.72
	- Excess (S\$)	600.00	600.00	0.00	0.00
	(S\$)	6,771.20	1,705.60	5,065.60	74.81
	+ GST 7.00/7.00% (S\$)	473.98	119.39	354.59	74.81
	Nett Amount (S\$)	7,245.18	1,824.99	5,420.19	74.81

INSPECTION

Date of Assignment: 08/01/2021

Cycle & Carriage KIA Pte Ltd (Pandan Gardens)

Date Inspected: 08/01/2021 Inspected At: 209 Pandan Gardens

Singapore 609339

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
2	1		*C&C BADGE	Not Necessary	40.00 FS	*- FS
3	1		*PANEL ASSY-FRONT DOOR, LH	Dented	1,582.00 FL	*1,582.00 FL
4	1		*W/STRIP ASSY-FR DR BELT O/S LH	Not Necessary	95.00 FL	*- FL
5	1		*GARNISH ASSY-DR FRAME LH	Not Necessary	98.00 FL	*- FL
6	1		*GARNISH ASSY-FRT DR SIDE, LH	Not Necessary	204.00 FL	*- FL
7	1		*COVER-RR BUMPER, UPR	Not Necessary	696.00 FL	*- FL
8	1		*COVER-RR BUMPER LWR	Not Necessary	650.00 FL	*- FL
9	1		*LAMP ASSY-REAR COMB INSIDE, LH	Not Necessary	796.00 FL	*-FL
10	1		*LAMP ASSY-REAR COMBINATION, LH	Not Necessary	687.00 FL	*- FL
11	1		*LOGO ASSY-KIA SUB	Not Necessary	69.00 FL	*- FL
12	1		*EMBLEM-ECO DYNAMICS	Not Necessary	37.00 FL	*- FL
F=Fra	nchise	part. S=SpcN	ett. L=ListItemDisc.	_		
				Sub Total (S\$)	4,974.00	1,602.00
	- List Item Discount on L Items 20.00/20.00% (S\$)					316.40
				Total Parts (S\$)	3,991.20	1,285.60
			Report was unsubmitted du	ring this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	RENEW LHF DOOR & RR BUMPER. REPAIR TAILGATE	New	2,000.00	400.00
2	RESPRAY TAILGATE, LHF DOOR & RR BUMPER	New	1,050.00	350.00
3	REMOVE & REFIT LHF DOOR COMPONENTS	New	120.00	120.00
4	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
5	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
6	REMOVE & REFIT REVERSE SENSOR	New	60.00	0.00
	Gross Labo	our Cost (S\$)	3,380.00	1,020.00
	Report was unsubmitted during thi	is print-out.		

< END OF ESTIMATES >