

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21000358/EQD3E2

Date: 15/04/2021

REFERENCE

Insured/Claimant:	TAN KIAN SIONG	Policy No:	2070176085		
Date of Loss:	06/01/2021	Nature of Claim:	OD	Claim No:	4786331505SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX1126J	Engine No:	D4HELH262447
Make & Model:	KIA SORENTO, 2.2 (A)	Chassis No:	KNARH81BVM5066376
Reg. Date:	28/12/2020 (Man. Year: 2020)	Odometer:	541 km
Colour:	White		
Engine Capacity:	2151 cc		
Market Value/New Car Price:	S\$148,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/60 R18	Rear Tyre Size:	235/60 R18
Front Left Side:	Continental 4 mm	Rear Left Side:	Continental 4 mm
Front Right Side:	Continental 4 mm	Rear Right Side:	Continental 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,757.20	2,468.80	288.40	10.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,920.00	2,590.00	2,330.00	47.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,677.20	5,058.80	2,618.40	34.11
+ GST 7.00/7.00% (S\$)	537.40	354.12	183.28	34.10
Nett Amount (S\$)	8,214.60	5,412.92	2,801.68	34.11

INSPECTION

Date of Assignment:	08/01/2021		
Date Inspected:	08/01/2021	Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	5.0 days		

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*COVER-RR BUMPER LWR	Cut	565.00 FL	*565.00 FL
3	1		*GARNISH ASSY-QTR SIDE, RH	Cut	38.00 FL	*38.00 FL
4	1		*GARNISH ASSY-RR DR SIDE, RH	Cut	210.00 FL	*210.00 FL
5	1		*PANEL ASSY-REAR DOOR, RH	Dented	1,290.00 FL	*1,290.00 FL
6	1		*W/STRIP ASSY-RR DR SIDE RH	Not Necessary	76.00 FL	*- FL
7	1		*W/STRIP-RR DR BELT I/S RH	Not Necessary	24.00 FL	*- FL
8	1		*W/STRIP ASSY-RR DR BELT O/S RH	Not Necessary	88.00 FL	*- FL
9	1		*MOULDING ASSY-RR DR FRAME, RH	Not Necessary	38.00 FL	*- FL
10	1		*GARNISH ASSY-RR DR RR FRAME, RH	Not Necessary	48.00 FL	*- FL
11	1		*GARNISH ASSY-RR DR FR FRAME, RH	Not Necessary	49.00 FL	*- FL
12	1		*WHEEL ASSY-ALUMINIUM	Cut	799.00 FL	*799.00 FL
13	1		*VALVE-TPMS (Supplementary)	Necessary	159.00 FL	*159.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,434.00	3,081.00
- List Item Discount on L Items 20.00/20.00% (S\$)	676.80	612.20
Total Parts (S\$)	2,757.20	2,468.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE REAR RH DOOR, REAR BUMPER LOWER & AFFECTED AREA. REPAIR ON REAR BUMPER & REAR RH FENDER	New	1,600.00	400.00
2	PAINT WORK ON REAR BUMPER, REAR RH FENDER & REAR RH DOOR	New	1,050.00	1,050.00
3	PAINT WORK ON REAR BUMPER, REAR RH FENDER & REAR RH DOOR	New	1,050.00	0.00
4	REMOVE & INSTALL REAR PARKING ASSIST	New	120.00	120.00
5	PERFORM RUST PREVENTION	New	80.00	0.00
6	TO TRANSFER REAR RH DOOR ATTACHMENT TO NEW PANEL	New	120.00	120.00
7	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
8	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
9	TO TRANSFER REAR RH RIM INCLUDING BALANCING	New	30.00	30.00
10	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
11	REMOVE & REINSTALL REAR BUMPER ASSY TO FACILITATE REPAIR, RESPRAY REAR UPPER BUMPER, REPLACE REAR BUMPER LOWER COVER (Supplementary)	New	400.00	400.00
12	REPAIR RH REAR FENDER (Supplementary)	New	200.00	200.00
Gross Labour Cost (\$\$)			4,920.00	2,590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >