

Surveyor : STEVE LKK
 Claim : AIG OD
 DOA : 06.01.2021
 Emailed : 09.04.2021, 11.30am
 Date Survey : 07.01.2021

VEHICLE NO : SMX 1126 J
 MODEL : KIA SORENTO 2.2 A D SX
 WIP : 26959

Material	:	\$	<u>2,448.80</u>
Labour	:	\$	<u>2,610.00</u>
Sub-Total	:	\$	<u>5,058.80</u>
	:	\$	<u>-</u>
Less Excess	:	\$	<u>-</u>
Total	:	\$	<u>5,058.80</u>
GST 7%	:	\$	<u>354.12</u>
Grand Total	:	\$	<u>5,412.92</u>
Finalise By/Date	:	<u>LOI / 09/04/2021</u>	

☒ REVERT BACK WITHIN 7 DAYS,
 OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
 + 0 Days (0) Public Holiday
 TOTAL DAYS REPAIR TOOK = 0

☐ TP claim _____

☐ Claim GIA / LTA fee _____

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others _____

☐ Third Party Report - _____

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 08/03/2021	<table> <tr> <td>Cust No/Name</td><td>/TAN KIAN SIONG (CHEN JIANXIONG)</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMX1126J / 28/12/2020</td></tr> <tr> <td>Date In/Mileage</td><td>08/03/2021/ 3760</td></tr> <tr> <td>Chassis/Package</td><td>KNARH81BVM5066376 /KC17PT</td></tr> <tr> <td>Engine No</td><td>D4HELH262447</td></tr> <tr> <td>Make/Model</td><td>KIA/SORENTO 2.2 A D SX SR G898</td></tr> <tr> <td>Colour/Trim</td><td>SWP SNOW WHITE PEAR/ WK SATURN BLACK</td></tr> </table>	Cust No/Name	/TAN KIAN SIONG (CHEN JIANXIONG)	Reg No/Reg Date	SMX1126J / 28/12/2020	Date In/Mileage	08/03/2021/ 3760	Chassis/Package	KNARH81BVM5066376 /KC17PT	Engine No	D4HELH262447	Make/Model	KIA/SORENTO 2.2 A D SX SR G898	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK
Cust No/Name	/TAN KIAN SIONG (CHEN JIANXIONG)														
Reg No/Reg Date	SMX1126J / 28/12/2020														
Date In/Mileage	08/03/2021/ 3760														
Chassis/Package	KNARH81BVM5066376 /KC17PT														
Engine No	D4HELH262447														
Make/Model	KIA/SORENTO 2.2 A D SX SR G898														
Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	08/04/2021/ 15:21	BLK	260 / AiTing	26959			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								✓ 400.00
REPLACE DAMAGED PARTS, REPLACE RH REAR DOOR, REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								
E PNT98000								✓ 1050.00
RESPRAY ON REAR BUMPER, RH REAR FENDER, RH REAR DOOR, AND ALL OTHER AFFECTED AREAS TO THE SAME								
E PNT88000								✓ 120.00
REMOVE & INSTALL REAR PARKING ASSIST TO FACILITATE REPAIR								
E PNT88000								✓ 120.00
TRANSFER RH REAR DOOR ATTACHMENTS TO NEW PANEL								
A 54900099								✓ 30.00
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								
A 10028901								✓ 120.00
CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE								
A WHEELALIGNMENTBP								✓ 120.00
CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT								
M SUNDRY								✓ 20.00
SUNRIES								
E PNT88000								400.00
REMOVE & REINSTALL REAR BUMPER ASSY TO FACILITATE, RESPRAY REAR UPPER BUMPER, REPLACE REAR BUMPER LOWER COVER → Supp.								
E PNT88000								200.00
REPAIR RH REAR FENDER → Supp.								
S SPECIALISTJOB								✓ 30.00
TRANSFER RH REAR RIM, REPLACE TIRE VALVE, CONDUCT WHEEL BALANCING								
X COVER-RR BUMPER LWR					1.00	✓ 565.00	20.00	452.00
X GARNISH ASSY-QTR SIDE,RH					1.00	✓ 38.00	20.00	30.40
X GARNISH ASSY-RR DR SIDE,RH					1.00	✓ 210.00	20.00	168.00
X PANEL ASSY-REAR DOOR,RH					1.00	✓ 1290.00	20.00	1032.00
X WHEEL ASSY-ALUMINIUM					1.00	✓ 799.00	20.00	639.20
X VALVE-TPMS → Supp.					1.00	159.00	20.00	127.20
Z TEXT								

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



GST Reg No : MR-8500111-X


INSURANCE CO. : **AIG**

Supplementary Parts For Registration No.: **SMX 1126 J**

<u>Materials</u>		<u>Cost (\$)</u>
1	Valve-TPMS	159.00 / nec
Total Materials		159.00
Less 20% discount		31.80
Total after discount		127.20
<u>Labour</u>		<u>Cost (\$)</u>
1	Remove & reinstall rear bumper assy to facilitate repair, respray rear upper bumper, replace rear bumper lower cover	400.00 /
2	Repair RH rear fender	200.00 /
Total labour		600.00
Total amount		727.20
7% GST		50.90
Grand total		<u>\$ 778.10</u>

Thank You.

Yours faithfully



LOI AI TING
SENIOR OFFICER - ADMIN
KIA SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240

CAR NO: SMX1126J

WIP: 26959

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Labeour as R/L rear bump L/R ✓ \$4.00	? / SUPP		✓	
2	Repair rear RM fender ✓ \$2.00	? / SUPP		✓	
3	Add 1 repair day ✓	? / SUPP		✓	
4		? / SUPP			
5		? / SUPP			
6		? / SUPP			
7		? / SUPP			
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

DATE	TAKEN BY
9/3/21	JH
PHOTO BEFORE PAINT	
PHOTO AFTER PAINT	
PHOTO OF MOUNT TO CELLETTE BENCH	
REMOVE AND INSTALL ENGINE	
REMOVE AND INSTALL DASHBAORD	
REMOVE & INSTALL FUEL TANK	
PHOTO UNDERCARRIAGE PARTS	

MODEL: Sorento 2.2 SX

SURVEYOR: Steve - LHK

Work Order: R001381
 License: smx 1126 j
 Technician: kfsan 810119
 Mileage: 3761
 Date: 16.3.21 15:10

Kia : Sorento : 2020- (MQ4) : except HEV : Front Wheel Drive

Front : Left

Actual	Before	Specified Range
-0°29'	-0°29'	-1°00' 0°00'
4°00'	4°00'	3°44' 4°44'
0°05'	0°05'	-0°03' 0°09'
13°14'*	13°14'*	13°18' 14°18'
12°45'	12°45'	12°18' 14°18'

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°48'	-0°48'	-1°00' 0°00'
4°53'*	4°53'*	3°44' 4°44'
0°08'	0°08'	-0°03' 0°09'
11°54'*	11°54'*	13°18' 14°18'
11°07'*	11°07'*	12°18' 14°18'

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
0°19'	0°19'	
-0°52'	-0°52'	
1°20'	1°20'	
0°13'	0°13'	-0°06' 0°18'

Rear : Left

Actual	Before	Specified Range
-0°58'	-0°58'	-1°30' -0°30'
0°07'	0°07'	0°00' 0°12'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-1°23'	-1°23'	-1°30' -0°30'
0°08'	0°08'	0°00' 0°12'

Rear

Cross Camber
 Total Toe
 Thrust Angle

Actual	Before	Specified Range
0°25'	0°25'	
0°15'	0°15'	0°00' 0°24'
-0°01'	-0°01'	

* This value is not within specification. Tire wear, handling and safety problems may result.



HOME

Online



SORENTO(MQ4)/2021/D 2.2 TCI..

VCI



Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save



PTG



ICU



CLU

20/20

System	Status	Result
PSM	No Current DTC	Good
SHVU	No Current DTC	Good
WPC	No Current DTC	Good
CLU	No Current DTC	Good
ICU	No Current DTC	Good
PTG	No Current DTC	Good

System	DTC	Description	State
DDM	B161C00	LIN Error RH Outside Mirror Unit	History
IBU-BCM	B163400	LIN Communication Error - RR SPW	History

S/W Ver.

M-E-K-01-00-0241

VCI Ver.

02.51

ECU Ver.

M-E-K-01-00-0182

OS Ver.

Android 10